

March 27, 2023

Chris Martin

New Water
333 Cyprus Run Ste 146
Houston, TX 77094

SATL Report No.: 2303372

RE: State - Oak Hill Acres

Project Number: 0150156

Dear Chris Martin

SATL received 1 Sample(s) on 03/22/2023 for analyses identified on the chain of custody. The analyses were performed using methods indicated on the laboratory report. Any deviations observed at sample receiving are notated on the Sample Receipt Checklist and/or Chain of Custody documents attached as part of this analytical report.

Sincerely,

For San Antonio Testing Laboratory, Inc.



Richard Hawk,
General Manager

The results in this report apply to the samples analyzed in accordance with the chain of custody document. This analytical report must be reproduced in its entirety.



New Water
333 Cyprus Run Ste 146
Houston TX, 77094

Project Manager: Chris Martin
Project: State - Oak Hill Acres
Project Number: 0150156

Reported:
03/27/23 18:15
Received:
03/22/23 12:28

Additional Notes:

Report No. 2303372

SAMPLE SUMMARY

Total Samples received in this work order: 1

The following samples were requested for analysis as per the CoC. Any re-runs or re-analyses requested are identified as such.

<u>Sample ID</u>	<u>Laboratory ID</u>	<u>Matrix</u>	<u>Sampling Method</u>	<u>Date Sampled</u>	<u>Date Received</u>
Tank Site	2303372-01	Drinking Water	Grab	03/22/23 09:15	03/22/23 12:28

Notes

All quality control samples and checks are within acceptance limits unless otherwise indicated.
Test results pertain only to those items tested.
All samples were in good condition when received by the laboratory unless otherwise noted.

New Water
333 Cyprus Run Ste 146
Houston TX, 77094

Project Manager: Chris Martin
Project: State - Oak Hill Acres
Project Number: 0150156

Reported:
03/27/23 18:15
Received:
03/22/23 12:28

Additional Notes:

Report No. 2303372

Sample ID #: Tank Site

Sampling Method: Grab

Lab Sample ID #: 2303372-01

Sample Matrix: Drinking Water

Date/Time Collected: 03/22/23 09:15

Analyte	Result	Units	PQL	Prep Method	Batch	Analyzed	Method	Analyst	Notes
Microbiological Parameters									
Total Coliforms *	Absent	-		Start 03/22/23 15:44/End 03/23/23 16:34			Colilert	JA	
E. Coli *	Absent	-		Start 03/22/23 15:44/End 03/23/23 16:34			Colilert	JA	
Field Parameters									
Residual Chlorine	1.41	mg/L							

New Water
333 Cyprus Run Ste 146
Houston TX, 77094

Project Manager: Chris Martin
Project: State - Oak Hill Acres
Project Number: 0150156

Reported:
03/27/23 18:15
Received:
03/22/23 12:28

Additional Notes:

Report No. 2303372

DEFINITIONS

*	TNI / NELAC accredited analyte
PQL	Practical Quantitation Limit
MCL	Maximum Contaminant Level
mg/Kg	Milligrams per Kilogram (Parts per Million)
mg/L	Milligrams per Liter (Parts per Million)
PPM	Parts per Million
L	LCS recovery is outside QC acceptance limits, the results may have a slight bias.
M	MS recovery is outside QC limits, the results may have a slight bias due to possible matrix interferences.
NR	Not Recovered due to source sample concentration exceeds spiked concentration.
RMCCCL	Recommended Maximum Concentration of Contaminants Level
Surr L	Surrogate recovery is low outside QC limits.
Surr H	Surrogate recovery is high outside QC limits.
HT	Sample received past holdtime
IC	Improper Container for this analyte(s)
IP	Improper preservation for this analyte(s)
IT	Improper Temperature
V	Inssufficient Volume
B	Sample collected in Bulk
S	RPD is outside QC limits.
AB	VOA Vial contained air bubbles.
OP	ortho-Phosphate was not filtered in the field within 15minutes of collection.
CCV	Continuing Calibration Verification Standard.
ICV	Initial Calibration Verification Standard.

Test Methods followed by the laboratory are referenced in the following approved methodology, unless otherwise specified.

Standard Methods for the Examination of Water and Wastewater, 23rd Edition, 2017
Methods for Chemical Analysis of Water and Wastes, EPA 600/4-79-020, Rev. March 1983
EPA SW Test Methods for the Examination of Solid Waste, SW-846, 1996



New Water
333 Cyprus Run Ste 146
Houston TX, 77094

Project Manager: Chris Martin
Project: State - Oak Hill Acres
Project Number: 0150156

Reported:
03/27/23 18:15
Received:
03/22/23 12:28

Additional Notes:

Report No. 2303372

Aimee Landon For Sairam Abburu, Lab Director For

The results in this report apply to the samples analyzed in accordance with the chain of custody document. This analytical report must be reproduced in its entirety.



Richard Hawk, General Manager

TCEQ Microbial Reporting Form

TCEQ Form 10525
08/2017

Water System Identification & Sample Collection Information (Please type or use block print)

Public Water System ID: TX 0150156

Public Water System Name: OAK HILL

County: BEXAR

Name: NEW WATER SYSTEMS

Address: 333 CYPRESS RUN STE 146

City: HOUSTON

State: TX Zip Code: 77094

Phone #: 713 882 3165 Other Contact: ~~XXXXXXXXXX~~

Signature: CHRIS MARTIN

Operator License #: WG0018569

Operator: Owner Other:

I hereby certify that the information provided on this form is true and accurate to the best of my knowledge and belief.

Signature of Operator: *[Signature]*

Sample ID & Date of Original Sample (All Repeat, Replacement, & Triggered Raw Samples)

Sample ID: TANK STB Date: 3/22/23 Time: 9:15 am

Sample Type: (one) Routine Repeat Raw Well Special Construction

Collection Date: 3/22/23 Time: 9:15 am

Collection Time: am pm

Collection Date: 3/22/23 Time: 9:15 am

Collection Time: am pm

Collection Date: 3/22/23 Time: 9:15 am

Collection Time: am pm

Collection Date: 3/22/23 Time: 9:15 am

Collection Time: am pm

Collection Date: 3/22/23 Time: 9:15 am

Collection Time: am pm

Collection Date: 3/22/23 Time: 9:15 am

Collection Time: am pm

Collection Date: 3/22/23 Time: 9:15 am

Collection Time: am pm



2303372

SAN ANTONIO TESTING LABORATORY



TCEQ Laboratory ID:

T104704360

Test Results must meet all accreditation / certification requirements unless stated otherwise.

SHADED AREA FOR LABORATORY USE ONLY

Relinquished By (Signature): *[Signature]*

Date / Time: 3/22/23 12:28pm

Date / Time: 3/22/23 12:28pm

Date / Time: 3/22/23 12:28pm

Date / Time: 3/22/23 12:28pm

Date / Time: 3/22/23 12:28pm

Date / Time: 3/22/23 12:28pm

Date / Time: 3/22/23 12:28pm

Date / Time: 3/22/23 12:28pm

Date / Time: 3/22/23 12:28pm

Date / Time: 3/22/23 12:28pm

Date / Time: 3/22/23 12:28pm

Date / Time: 3/22/23 12:28pm

Date / Time: 3/22/23 12:28pm

Date / Time: 3/22/23 12:28pm

Date / Time: 3/22/23 12:28pm

Date / Time: 3/22/23 12:28pm

Date / Time: 3/22/23 12:28pm

Date / Time: 3/22/23 12:28pm

Date / Time: 3/22/23 12:28pm

Date / Time: 3/22/23 12:28pm

Date / Time: 3/22/23 12:28pm

Date / Time: 3/22/23 12:28pm

Date / Time: 3/22/23 12:28pm

Date / Time: 3/22/23 12:28pm

Date / Time: 3/22/23 12:28pm

Date / Time: 3/22/23 12:28pm

Date / Time: 3/22/23 12:28pm

Date / Time: 3/22/23 12:28pm

Date / Time: 3/22/23 12:28pm

Date / Time: 3/22/23 12:28pm

Date / Time: 3/22/23 12:28pm

Date / Time: 3/22/23 12:28pm

Date / Time: 3/22/23 12:28pm

Date / Time: 3/22/23 12:28pm

Date / Time: 3/22/23 12:28pm

Date / Time: 3/22/23 12:28pm

Date / Time: 3/22/23 12:28pm

Date / Time: 3/22/23 12:28pm

Date / Time: 3/22/23 12:28pm

Date / Time: 3/22/23 12:28pm

Date / Time: 3/22/23 12:28pm

Date / Time: 3/22/23 12:28pm

Date / Time: 3/22/23 12:28pm

Lab Rejected Code (LR) - Document Reason:

* Special and Construction samples are NOT FOR COMPLIANCE

Instructions: www.tceq.texas.gov/drinkingwater/microbial/revise-total-collform-rule

CMONWEUSA.COM

Sample Receipt Checklist

Client: New Water	Project Manager: Sairam Abburu
Project: State - Oak Hill Acres	Project Number: 0150156

Report To:
Chris Martin

SATL Report Number: 2303372

Work Order Due by:	03/27/23 17:00 (3 day TAT)	Date Received:	03/22/23 12:28
Received By:	Joana Martinez	Date Logged In:	03/22/23 13:52
Logged In By:	Joana Martinez		

Sample(s) Received on ICE/evidence of Ice (cooler with melted ice,etc):	Yes
Sample temperature at receipt *:	19°C
Custody Seals Present:	No
All containers intact:	Yes
Sample labels/COC agree:	Yes
Samples Received within Holding time :	Yes
Samples appropriately preserved **:	Yes
Containers received broken/damaged/leaking:	No
Air bubbles present in VOA vials for VOC/TPH analyses, if applicable:	Not Applicable
TRRP 13 Reporting requested?	No
BacT Sample bottles filled to volume (100mL mark), if applicable:	Not Applicable
LCR Sample bottles filled to volume (1 Liter mark), if applicable:	Not Applicable
Subcontracting required for any analyses:	No
RUSH turnaround time requested:	Yes
Requested Turnaround Time:	3 Business days
Samples delivered via :	Hand Delivered
Air bill included if Samples were shipped:	No
Other deviations not meeting SATL sample acceptance criteria notated on CoC:	Notated on CoC, if any

Notes:
 * Samples delivered to the laboratory on the same day that they are collected may not meet thermal preservation criteria (>0°C but <6°C) but are acceptable, if they arrive on ice.
 ** If improperly preserved, notate client authorization on CoC to proceed with analysis.

Checked By : Joana Martinez Date : 03/22/23 12:28