

Portable /Fixed Appliance

Equipment formal visual and combined inspection and test

FT/PAT

6242000001968

Part 1: Details of Installation

Client Ryan Robinson			Installation			Inspector Name	
Address			Address 104 Greenfield Avenue NORTHAMPTON			Branch No. Ryan Robinson	
Postcode			Postcode NN3 2BB			Date of Test	
						Test Equipment	
						Signature	
						001	
						Scheme No.	
						Date of Re-test	
						12/02/2026	
						12/02/2027	
						Seaward Prime Test 50	

Part 2: Test Results

Appliance No.	Description	Date of test	Serial / Identification No.	Class I / II	Fuse size	Visual Only	Continuity/ Earth Bond Ω	Polarity	Insulation M Ω	Load KW	Function Run	Earth leak mA	RCD Check	Repair Code	Pass / Fail	Location
1	Speaker JBL	12/02/2026	41984	II	3	✓	N/A	✓	>299	0.8	✓	N/A	N/A	N/A	✓	
2	Speaker JBL	12/02/2026	45076	II	3	✓	N/A	✓	>299	1.1	✓	N/A	N/A	N/A	✓	
3	Speaker JBL	12/02/2026	10003	II	3	✓	N/A	✓	>299	0.24	✓	N/A	N/A	N/A	✓	
4	Speaker JBL	12/02/2026	10004	II	3	✓	N/A	✓	>299	0.24	✓	N/A	N/A	N/A	✓	
5	Speaker Vonxy	12/02/2026	17369	I	3	✓	Pass	✓	>299	0.05	✓	N/A	N/A	N/A	✓	
6	Air Blower	12/02/2026	23328	I	13	✓	Pass	✓	>299	1.8	✓	N/A	N/A	N/A	✓	
7	Air Blower	12/02/2026	15756	I	13	✓	Pass	✓	>299	1.8	✓	N/A	N/A	N/A	✓	

Repair codes: 1 - Damaged flex – Re-terminated 2 - Damaged – Plug removed 3 - Safety fault R1 - Replaced plug top R2 - Replaced plug top fuse R3 - Change plug top fuse from 13A to 3A fuse
 R4 - Change plug top fuse from 13A to 5A fuse R5 - Change plug top fuse from 13A to 10A fuse R6 - Replaced extension lead R7 - Shortened damaged power-cord/cable and refitted plug top
 R8 - Rewired incorrectly wired plug top R9 - Repaired/refitted insecure or wrongly fitted power-cord/cable grip R10 - Removed cardboard wiring diagram from plug top (Fire hazard)
 R11 - Repaired or refitted appliance case

Portable /Fixed Appliance

FT/PAT 624200001968

Equipment formal visual and combined inspection and test

8	Air Blower	12/02/2026	23365	I	13	✓	Pass	✓	>299	1.8	✓	N/A	N/A	N/A	✓	
9	Air Blower	12/02/2026	39103	I	5	✓	Pass	✓	>299	0.75	✓	N/A	N/A	N/A	✓	
10	Air Blower	12/02/2026	41268	I	13	✓	Pass	✓	>299	1.8	✓	N/A	N/A	N/A	✓	
11	Air Blower	12/02/2026	10011	I	13	✓	Pass	✓	>299	1.8	✓	N/A	N/A	N/A	✓	

Part 2: Test Results

Appliance No.	Description	Date of test	Serial / Identification No.	Class I / II	Fuse size	Visual Only	Continuity/ Earth Bond Ω	Polarity	Insulation MΩ	Load KW	Function Run	Earth leak mA	RCD Check	Repair Code	Pass / Fail	Location
12	Blow Heater Erberur	12/02/2026	08816	I	13	✓	Pass	✓	>299	2.5	✓	N/A	N/A	N/A	✓	
13	Light	12/02/2026	10013	I	13	✓	Pass	✓	>299	2.5	✓	N/A	N/A	N/A	✓	
14	Extension Lead	12/02/2026	38952	I	13	✓	Pass	✓	>299	3.12	✓	N/A	N/A	N/A	✓	
15	Extension Lead	12/02/2026	10015	I	13	✓	Pass	✓	>299	N/A	✓	N/A	N/A	N/A	✓	
16	Extension Lead	12/02/2026	10015	I	13	✓	Pass	✓	>299	N/A	✓	N/A	✓	N/A	✓	
17	Extension Lead	12/02/2026	10016	I	13	✓	Pass	✓	>299	N/A	✓	N/A	✓	N/A	✓	
18	Extension Lead	12/02/2026	10018	I	13	✓	Pass	✓	>299	N/A	✓	N/A	✓	N/A	✓	
19	Extension Lead	12/02/2026	10019	I	13	✓	Pass	✓	>299	N/A	✓	N/A	✓	N/A	✓	
20	Extension Lead	12/02/2026	10020	I	13	✓	Pass	✓	>299	N/A	✓	N/A	N/A	N/A	✓	
21	Extension Lead	12/02/2026	10021	I	13	✓	Pass	✓	>299	N/A	✓	N/A	N/A	N/A	✓	
22	Extension Lead	12/02/2026	10020	I	13	✓	Pass	✓	>299	N/A	✓	N/A	N/A	N/A	✓	
23	Light	12/02/2026	10023	II	3	✓	N/A	✓	>299	N/A	✓	N/A	N/A	N/A	✓	

Repair codes: 1 - Damaged flex – Re-terminated 2 - Damaged – Plug removed 3 - Safety fault R1 - Replaced plug top R2 - Replaced plug top fuse R3 - Change plug top fuse from 13A to 3A fuse
 R4 - Change plug top fuse from 13A to 5A fuse R5 - Change plug top fuse from 13A to 10A fuse R6 - Replaced extension lead R7 - Shortened damaged power-cord/cable and refitted plug top
 R8 - Rewired incorrectly wired plug top R9 - Repaired/refitted insecure or wrongly fitted power-cord/cable grip R10 - Removed cardboard wiring diagram from plug top (Fire hazard)
 R11 - Repaired or refitted appliance case

Portable /Fixed Appliance

FT/PAT 6242000001968

Equipment formal visual and combined inspection and test

24	Light	12/02/2026	10024	II	3	✓	N/A	✓	>299	N/A	✓	N/A	N/A	N/A	✓	
25	Light	12/02/2026	10025	II	3	✓	N/A	✓	>299	N/A	✓	N/A	N/A	N/A	✓	
26	Beamz 1	12/02/2026	62963	II	13	✓	N/A	✓	>299	N/A	✓	N/A	N/A	N/A	✓	
27	Extension Lead	12/02/2026	10027	I	13	✓	Pass	✓	>299	N/A	✓	N/A	N/A	N/A	✓	
28	Extension Lead	12/02/2026	10028	I	13	✓	Pass	✓	>299	N/A	✓	N/A	N/A	N/A	✓	

Part 2: Test Results

Appliance No.	Description	Date test	Serial / Identification No.	Class I / II	Fuse size	Visual Only	Continuity/ Earth Bond Ω	Polarity	Insulation MΩ	Load KW	Function Run	Earth leak mA	RCD Check	Repair Code	Pass / Fail	Location
29	Light	12/02/2026	10029	II	3	✓	N/A	✓	>299	N/A	✓	N/A	N/A	N/A	✓	
30	Light	12/02/2026	10030	II	3	✓	N/A	✓	>299	N/A	✓	N/A	N/A	N/A	✓	
31	Extension Lead	12/02/2026	10031	I	13	✓	Pass	✓	>299	N/A	✓	N/A	N/A	N/A	✓	
32	Extension Lead	12/02/2026	10032	I	13	✓	Pass	✓	>299	N/A	✓	N/A	N/A	N/A	✓	
33	Light	12/02/2026	10033	II	3	✓	N/A	✓	>299	N/A	✓	N/A	N/A	N/A	✓	
34	Light Qtx	12/02/2026	10034	II	3	✓	N/A	✓	>299	N/A	✓	N/A	N/A	N/A	✓	
35	Beamz 2	12/02/2026	61285	II	13	✓	N/A	✓	>299	N/A	✓	N/A	N/A	N/A	✓	
36	Extension Lead	12/02/2026	10036	I	13	✓	Pass	✓	>299	N/A	✓	N/A	N/A	N/A	✓	
37	Extension Lead	12/02/2026	10037	I	13	✓	Pass	✓	>299	N/A	✓	N/A	N/A	N/A	✓	
38	Commando Extension Lead	12/02/2026	10038	I	13	✓	Pass	✓	>299	N/A	✓	N/A	N/A	N/A	✓	

Repair codes: 1 - Damaged flex – Re-terminated 2 - Damaged – Plug removed 3 - Safety fault R1 - Replaced plug top R2 - Replaced plug top fuse R3 - Change plug top fuse from 13A to 3A fuse
 R4 - Change plug top fuse from 13A to 5A fuse R5 - Change plug top fuse from 13A to 10A fuse R6 - Replaced extension lead R7 - Shortened damaged power-cord/cable and refitted plug top
 R8 - Rewired incorrectly wired plug top R9 - Repaired/refitted insecure or wrongly fitted power-cord/cable grip R10 - Removed cardboard wiring diagram from plug top (Fire hazard)
 R11 - Repaired or refitted appliance case

Portable /Fixed Appliance

FT/PAT 6242000001968

Equipment formal visual and combined inspection and test

39	Commando Extension Lead	12/02/2026	10039	I	13	✓	Pass	✓	>299	N/A	✓	N/A	N/A	N/A	✓	
40	Speaker & Light	12/02/2026	29984	II	3	✓	N/A	✓	N/A	0.05	✓	N/A	N/A	N/A	✓	
41	Extension Lead	12/02/2026	10041	I	13	✓	Pass	✓	>299	N/A	✓	N/A	N/A	N/A	✓	
42	Extension Lead	12/02/2026	10042	I	13	✓	Pass	✓	>299	N/A	✓	N/A	N/A	N/A	✓	
43	Beamz 3	12/02/2026	62948	II	13	✓	N/A	✓	>299	N/A	✓	N/A	N/A	N/A	✓	
44	Party Light	12/02/2026	10044	II	13	✓	N/A	✓	>299	N/A	✓	N/A	N/A	N/A	✓	

Part 2: Test Results

Appliance No.	Description	Date of test	Serial / Identification No.	Class I / II	Fuse size	Visual Only	Continuity/ Earth Bond Ω	Polarity	Insulation MΩ	Load KW	Function Run	Earth leak mA	RCD Check	Repair Code	Pass / Fail	Location
45	Light	12/02/2026	10045	II	3	✓	N/A	✓	>299	N/A	✓	N/A	N/A	N/A	✓	
46	Light	12/02/2026	10046	II	3	✓	N/A	✓	>299	0.02	✓	N/A	N/A	N/A	✓	
47	Light	12/02/2026	10047	II	3	✓	N/A	✓	>299	N/A	✓	N/A	N/A	N/A	✓	

Test Result Totals:

Total Items Tested: | Total Failed Items Tested:

Repair codes: 1 - Damaged flex – Re-terminated 2 - Damaged – Plug removed 3 - Safety fault R1 - Replaced plug top R2 - Replaced plug top fuse R3 - Change plug top fuse from 13A to 3A fuse
 R4 - Change plug top fuse from 13A to 5A fuse R5 - Change plug top fuse from 13A to 10A fuse R6 - Replaced extension lead R7 - Shortened damaged power-cord/cable and refitted plug top
 R8 - Rewired incorrectly wired plug top R9 - Repaired/refitted insecure or wrongly fitted power-cord/cable grip R10 - Removed cardboard wiring diagram from plug top (Fire hazard)
 R11 - Repaired or refitted appliance case