

For detailed instructions CLICK HERE!													
<div><div></div><div>Press the +/- button to display or hide the PWS Information box</div></div> <div>Location Information</div>													
Unique Service Line ID	Site Name	Street Number	Street Name	City	Zip Code	County	Latitude	985.0000	In Asset Management	Asset Status	Asset Start Date	Asset End Date	System-Owned Portion Service Line Material Classification
A Unique ID by the public water system for each service line.		Water systems must track addresses of all service lines in their internal inventory. For the publicly accessible version, location identifiers are required for lead and galvanized requiring replacement. If the system does not use addresses for their location identifier, other options could include GPS coordinates, landmark, intersection, block, or other details to specify service line locations.											If "Non-Lead Other", describe in Comments field
Example 1 (DO NOT DELETE)	Site Name	1234	Test St.	Test City	88888	Test County	##.####	-##.####	Yes, No, Unknown	Active, Inactive, Not Applicable	mm/dd/yyyy	mm/dd/yyyy	Non-Lead - Copper
Example 2 (DO NOT DELETE)	House 1	1502	Main St	Braceville	44444	Adams	41.2566	-80.9806	No	Active	1/1/2022	1/1/2023	Non-Lead - Plastic
Example 3 (DO NOT DELETE)	Business 1	1268	Main St	Braceville	44444	Adams	41.2560	-80.9820	Yes	Inactive	1/15/2016		Non-Lead - Copper
100100	House 1	203	W. Vine St.	Belle Center	43310	Logan	40.5105	-83.7506	Yes	Active			Non-Lead - Copper
100200	House 1	202	W. Vine St.	Belle Center	43310	Logan	40.5107	-83.7504	Yes	Active			Non-Lead - Copper
100300	House 1	206	W. Vine St.	Belle Center	43310	Logan	40.5111	-83.7510	Yes	Active			Non-Lead - Copper
100500	Garage	205	W. Vine St.	Belle Center	43310	Logan	40.5105	-83.7511	Yes	Active			Non-Lead - Copper
100700	House 1	208	W. Vine St.	Belle Center	43310	Logan	40.5105	-83.7515	Yes	Active			Non-Lead - Copper
101200	House 1	214	W. Vine St.	Belle Center	43310	Logan	40.5101	-83.7521	Yes	Active			Non-Lead - Copper
101400	House 1	302	W. Buckeye St.	Belle Center	43310	Logan	40.5094	-83.7526	Yes	Active			Non-Lead - Copper
101500	House 1	303	W. Buckeye St.	Belle Center	43310	Logan	40.5093	-83.7531	Yes	Active			Non-Lead - Copper
101600	House 1	304	W. Buckeye St.	Belle Center	43310	Logan	40.5096	-83.7528	Yes	Active			Non-Lead - Copper
101650	House 1	308	W. Buckeye St.	Belle Center	43310	Logan	40.5097	-83.7530	Yes	Active			Non-Lead - Copper
101700	House 1	305	W. Buckeye St.	Belle Center	43310	Logan	40.5094	-83.7532	Yes	Active			Non-Lead - Copper
102000	House 1	307	W. Buckeye St.	Belle Center	43310	Logan	40.5096	-83.7534	Yes	Active			Non-Lead - Copper
102200	House 1	310	W. Buckeye St.	Belle Center	43310	Logan	40.5098	-83.7532	Yes	Active			Non-Lead - Copper
102300	House 1	312	W. Buckeye St.	Belle Center	43310	Logan	40.51	-83.7534	Yes	Active			Non-Lead - Copper
102400	House 1	309	W. Buckeye St.	Belle Center	43310	Logan	40.5097	-83.7537	Yes	Active			Non-Lead - Copper
102500	House 1	311	W. Buckeye St.	Belle Center	43310	Logan	40.5098	-83.754	Yes	Active			Non-Lead - Copper
102800	House 1	316	W. Buckeye St.	Belle Center	43310	Logan	40.5102	-83.7539	Yes	Active			Non-Lead - Copper
102700	House 1	313	W. Buckeye St.	Belle Center	43310	Logan	40.51	-83.7543	Yes	Active			Non-Lead - Copper
102850	House 1	318	W. Buckeye St.	Belle Center	43310	Logan	40.5103	-83.7541	Yes	Active			Non-Lead - Copper
103000	House 1	320	W. Buckeye St.	Belle Center	43310	Logan	40.5106	-83.7544	Yes	Active			Non-Lead - Copper
103200	House 1	324	W. Buckeye St.	Belle Center	43310	Logan	40.5108	-83.7547	Yes	Active			Non-Lead - Copper
103300	House 1	326	W. Buckeye St.	Belle Center	43310	Logan	40.5109	-83.755	Yes	Active			Non-Lead - Copper
103500	House 1	231	W. Main St.	Belle Center	43310	Logan	40.5108	-83.7562	Yes	Active			Non-Lead - Copper

Unique Service Line ID	Site Name	Street Number	Street Name	City	Zip Code	County	Latitude	985.0000	In Asset Management	Asset Status	Asset Start Date	Asset End Date	System-Owned Portion Service Line Material Classification
103600	House 1	229	W. Main St.	Belle Center	43310	Logan	40.5104	-83.7558	Yes	Active			Non-Lead - Copper
103700	House 1	230	W. Main St.	Belle Center	43310	Logan	40.5104	-83.755	Yes	Active			Non-Lead - Copper
103800	House 1	228	W. Main St.	Belle Center	43310	Logan	40.5103	-83.7549	Yes	Active			Non-Lead - Copper
103900	House 1	227	W. Main St.	Belle Center	43310	Logan	40.5101	-83.7553	Yes	Active			Non-Lead - Copper
104100	House 1	226	W. Main St.	Belle Center	43310	Logan	40.5101	-83.7548	Yes	Active			Non-Lead - Copper
104200	House 1	315	W. Buckeye St.	Belle Center	43310	Logan	40.5101	-83.7544	Yes	Active			Non-Lead - Copper
104300	House 1	223	W. Main St.	Belle Center	43310	Logan	40.5098	-83.7552	Yes	Active			Non-Lead - Copper
104500	House 1	224	W. Main St.	Belle Center	43310	Logan	40.5096	-83.7547	Yes	Active			Non-Lead - Copper
104600	House 1	222	W. Main St.	Belle Center	43310	Logan	40.5094	-83.7544	Yes	Active			Non-Lead - Copper
104700	House 1	219	W. Main St.	Belle Center	43310	Logan	40.5093	-83.7549	Yes	Active			Non-Lead - Copper
104800	House 1	217	W. Main St.	Belle Center	43310	Logan	40.5092	-83.7549	Yes	Active			Non-Lead - Copper
105200	House 1	215	W. Main St.	Belle Center	43310	Logan	40.5089	-83.7559	Yes	Active			Non-Lead - Copper
105100	House 1	218	W. Main St.	Belle Center	43310	Logan	40.5092	-83.7542	Yes	Active			Non-Lead - Copper
105600	House 1	211	W. Main St.	Belle Center	43310	Logan	40.5086	-83.7541	Yes	Active			Non-Lead - Copper
105800	House 1	207	W. Main St.	Belle Center	43310	Logan	40.5084	-83.7539	Yes	Active			Non-Lead - Copper
105900	House 1	208	W. Main St.	Belle Center	43310	Logan	40.5105	-83.7515	Yes	Active			Non-Lead - Copper
106300	House 1	210	W. Buckeye St.	Belle Center	43310	Logan	40.5089	-83.7525	Yes	Active			Non-Lead - Copper
106400	House 1	301	W. Buckeye St.	Belle Center	43310	Logan	40.5091	-83.7529	Yes	Active			Non-Lead - Copper
106600	House 1	301	E. Main St.	Belle Center	43310	Logan	40.5058	-83.7487	Yes	Active			Non-Lead - Copper
106900	House 1	304	E. Main St.	Belle Center	43310	Logan	40.5054	-83.749	Yes	Active			Non-Lead - Copper
107000	House 1	305	E. Main St.	Belle Center	43310	Logan	40.5056	-83.7486	Yes	Active			Non-Lead - Copper
107300	House 1	308	E. Main St.	Belle Center	43310	Logan	40.5051	-83.7487	Yes	Active			Non-Lead - Copper
107400	House 1	307	E. Main St.	Belle Center	43310	Logan	40.5055	-83.7483	Yes	Active			Non-Lead - Copper
107500	House 1	309	E. Main St.	Belle Center	43310	Logan	40.5053	-83.7482	Yes	Active			Non-Lead - Copper
107800	House 1	314	E. Main St.	Belle Center	43310	Logan	40.5049	-83.7483	Yes	Active			Non-Lead - Copper
107900	House 1	311	E. Main St.	Belle Center	43310	Logan	40.5053	-83.7478	Yes	Active			Non-Lead - Copper
108100	House 1	315	E. Main St.	Belle Center	43310	Logan	40.5052	-83.7476	Yes	Active			Non-Lead - Copper
108300	House 1	317	E. Main St.	Belle Center	43310	Logan	40.505	-83.7474	Yes	Active			Non-Lead - Copper
108500	House 1	318	E. Main St.	Belle Center	43310	Logan	40.5045	-83.7478	Yes	Active			Non-Lead - Copper

Unique Service Line ID	Site Name	Street Number	Street Name	City	Zip Code	County	Latitude	985.0000	In Asset Management	Asset Status	Asset Start Date	Asset End Date	System-Owned Portion Service Line Material Classification
108600	House 1	320	E. Main St.	Belle Center	43310	Logan	40.5045	-83.7476	Yes	Active			Non-Lead - Copper
108800	House 1	402	E. Main St.	Belle Center	43310	Logan	40.5042	-83.7472	Yes	Active			Non-Lead - Copper
108900	House 1	321	E. Main St.	Belle Center	43310	Logan	40.5048	-83.7472	Yes	Active			Non-Lead - Copper
109000	House 1	401	E. Main St.	Belle Center	43310	Logan	40.5046	-83.7467	Yes	Active			Non-Lead - Copper
109100	House 1	316	E. Buckeye St.	Belle Center	43310	Logan	40.5053	-83.7466	Yes	Active			Non-Lead - Copper
109200	House 1	317	E. Buckeye St.	Belle Center	43310	Logan	40.5055	-83.7463	Yes	Active			Non-Lead - Copper
109300	House 1	316	Torrence St.	Belle Center	43310	Logan	40.506	-83.7458	Yes	Active			Non-Lead - Copper
109400	House 1	314	Torrence St.	Belle Center	43310	Logan	40.5062	-83.746	Yes	Active			Non-Lead - Copper
109500	House 1	312	Torrence St.	Belle Center	43310	Logan	40.5064	-83.7462	Yes	Active			Non-Lead - Copper
109900	House 1	401	Torrence St.	Belle Center	43310	Logan	40.5065	-83.7451	Yes	Active			Non-Lead - Copper
110000	House 1	402	Torrence St.	Belle Center	43310	Logan	40.5058	-83.7455	Yes	Active			Non-Lead - Copper
110100	House 1	404	Torrence St.	Belle Center	43310	Logan	40.5057	-83.7452	Yes	Active			Non-Lead - Copper
110200	House 1	403	Torrence St.	Belle Center	43310	Logan	40.5062	-83.745	Yes	Active			Non-Lead - Copper
110700	House 1	408 1/2	Torrence St.	Belle Center	43310	Logan	40.5055	-83.7448	Yes	Active			Non-Lead - Copper
110400	House 1	405	Torrence St.	Belle Center	43310	Logan	40.506	-83.7446	Yes	Active			Non-Lead - Copper
110500	House 1	407	Torrence St.	Belle Center	43310	Logan	40.5058	-83.7443	Yes	Active			Non-Lead - Copper
110600	House 1	408	Torrence St.	Belle Center	43310	Logan	40.5055	-83.7448	Yes	Active			Non-Lead - Copper
110800	House 1	410	Torrence St.	Belle Center	43310	Logan	40.5053	-83.7445	Yes	Active			Non-Lead - Copper
110900	House 1	409	Torrence St.	Belle Center	43310	Logan	40.5056	-83.744	Yes	Active			Non-Lead - Copper
111000	House 1	412	Torrence St.	Belle Center	43310	Logan	40.5051	-83.7443	Yes	Active			Non-Lead - Copper
111100	House 1	414	Torrence St.	Belle Center	43310	Logan	40.5049	-83.7442	Yes	Active			Non-Lead - Copper
111200	House 1	306	Charles St.	Belle Center	43310	Logan	40.5055	-83.7435	Yes	Active			Non-Lead - Copper
111300	House 1	317	Charles St.	Belle Center	43310	Logan	40.5057	-83.7435	Yes	Active			Non-Lead - Copper
111400	House 1	601	Charles St.	Belle Center	43310	Logan	40.505	-83.7435	Yes	Active			Non-Lead - Copper
111500	Business 1	2598	sr. 273 w	Belle Center	43310	Logan	40.5045	-83.7432	Yes	Active			Non-Lead - Copper
111600	House 1	417	E. Buckeye St.	Belle Center	43310	Logan	40.5044	-83.7438	Yes	Active			Non-Lead - Copper
111700	House 1	2599	sr. 273 w	Belle Center	43310	Logan	40.5038	-83.7431	Yes	Active			Non-Lead - Copper
111800	House 1	418	E. Buckeye St.	Belle Center	43310	Logan	40.5039	-83.7439	Yes	Active			Non-Lead - Copper
112000	House 1	415	E. Buckeye St.	Belle Center	43310	Logan	40.5045	-83.7443	Yes	Active			Non-Lead - Copper
112200	House 1	412	E. Buckeye St.	Belle Center	43310	Logan	40.5044	-83.7451	Yes	Active			Non-Lead - Copper

Unique Service Line ID	Site Name	Street Number	Street Name	City	Zip Code	County	Latitude	985.0000	In Asset Management	Asset Status	Asset Start Date	Asset End Date	System-Owned Portion Service Line Material Classification
112300	Business 1	413	E. Buckeye St.	Belle Center	43310	Logan	40.5048	-83.7449	Yes	Active			Non-Lead - Copper
112400	House 1	410	E. Buckeye St.	Belle Center	43310	Logan	40.5044	-83.746	Yes	Active			Non-Lead - Copper
112500	House 1	407	E. Buckeye St.	Belle Center	43310	Logan	40.5057	-83.7452	Yes	Active			Non-Lead - Copper
112600	House 1	405	E. Buckeye St.	Belle Center	43310	Logan	40.5051	-83.7455	Yes	Active			Non-Lead - Copper
112700	House 1	406	E. Buckeye St.	Belle Center	43310	Logan	40.5049	-83.746	Yes	Active			Non-Lead - Copper
112800	House 1	402	E. Buckeye St.	Belle Center	43310	Logan	40.5051	-83.7463	Yes	Active			Non-Lead - Copper
112900	House 1	403	E. Buckeye St.	Belle Center	43310	Logan	40.5053	-83.7457	Yes	Active			Non-Lead - Copper
113000	House 1	401	E. Buckeye St.	Belle Center	43310	Logan	40.5055	-83.7459	Yes	Active			Non-Lead - Copper
113100	House 1	314	E. Buckeye St.	Belle Center	43310	Logan	40.5055	-83.7469	Yes	Active			Non-Lead - Copper
113200	House 1	315	E. Buckeye St.	Belle Center	43310	Logan	40.5057	-83.7466	Yes	Active			Non-Lead - Copper
113300	House 1	313	E. Buckeye St.	Belle Center	43310	Logan	40.5058	-83.7467	Yes	Active			Non-Lead - Copper
113400	House 1	312	E. Buckeye St.	Belle Center	43310	Logan	40.5056	-83.7471	Yes	Active			Non-Lead - Copper
113500	House 1	310	E. Buckeye St.	Belle Center	43310	Logan	40.5057	-83.7473	Yes	Active			Non-Lead - Copper
113600	House 1	311	E. Buckeye St.	Belle Center	43310	Logan	40.506	-83.747	Yes	Active			Non-Lead - Copper
113700	House 1	309	E. Buckeye St.	Belle Center	43310	Logan	40.5061	-83.7473	Yes	Active			Non-Lead - Copper
113800	House 1	308	E. Buckeye St.	Belle Center	43310	Logan	40.5059	-83.7475	Yes	Active			Non-Lead - Copper
113900	House 1	307	E. Buckeye St.	Belle Center	43310	Logan	40.5069	-83.746	Yes	Active			Non-Lead - Copper
114000	House 1	305	E. Buckeye St.	Belle Center	43310	Logan	40.5064	-83.7477	Yes	Active			Non-Lead - Copper
114100	House 1	306	E. Buckeye St.	Belle Center	43310	Logan	40.506	-83.7477	Yes	Active			Non-Lead - Copper
114200	House 1	304	E. Buckeye St.	Belle Center	43310	Logan	40.5062	-83.7479	Yes	Active			Non-Lead - Copper
114600	House 1	217	E. Main St.	Belle Center	43310	Logan	40.506	-83.7492	Yes	Active			Non-Lead - Copper
200100	House 1	106	Maple St.	Belle Center	43310	Logan	40.5054	-83.7535	Yes	Active			Non-Lead - Copper
200200	House 1	108	Maple St.	Belle Center	43310	Logan	40.5053	-83.7533	Yes	Active			Non-Lead - Copper
200300	House 1	114	Maple St.	Belle Center	43310	Logan	40.5046	-83.7535	Yes	Active			Non-Lead - Copper
200400	House 1	110	Maple St.	Belle Center	43310	Logan	40.5051	-83.753	Yes	Active			Non-Lead - Copper
200500	House 1	112	Maple St.	Belle Center	43310	Logan	40.505	-83.7528	Yes	Active			Non-Lead - Copper
200600	House 1	202	Maple St.	Belle Center	43310	Logan	40.5047	-83.7525	Yes	Active			Non-Lead - Copper
200700	House 1	204	Maple St.	Belle Center	43310	Logan	40.5046	-83.7523	Yes	Active			Non-Lead - Copper
200800	House 1	206	Maple St.	Belle Center	43310	Logan	40.5045	-83.7519	Yes	Active			Non-Lead - Copper
200900	House 1	208	Maple St.	Belle Center	43310	Logan	40.5043	-83.7518	Yes	Active			Non-Lead - Copper

Unique Service Line ID	Site Name	Street Number	Street Name	City	Zip Code	County	Latitude	985.0000	In Asset Management	Asset Status	Asset Start Date	Asset End Date	System-Owned Portion Service Line Material Classification
201000	House 1	210	Maple St.	Belle Center	43310	Logan	40.5041	-83.7515	Yes	Active			Non-Lead - Copper
201100	House 1	306	S. State St	Belle Center	43310	Logan	40.5035	-83.7516	Yes	Active			Non-Lead - Copper
201550	House 1	314	S. State St.	Belle Center	43310	Logan	40.5019	-83.7528	Yes	Active			Non-Lead - Copper
201600	House 1	212	Maple St.	Belle Center	43310	Logan	40.504	-83.7513	Yes	Active			Non-Lead - Copper
201700	House 1	214	Maple St.	Belle Center	43310	Logan	40.5039	-83.751	Yes	Active			Non-Lead - Copper
201800	House 1	10288	CR 39	Belle Center	43310	Logan	40.5023	-83.7517	Yes	Active			Non-Lead - Copper
201900	House 1	216	Maple St.	Belle Center	43310	Logan	40.5038	-83.751	Yes	Active			Non-Lead - Copper
202000	House 1	301	S. State St.	Belle Center	43310	Logan	40.5038	-83.7504	Yes	Active			Non-Lead - Copper
202200	House 1	205	S. State St.	Belle Center	43310	Logan	40.5037	-83.7506	Yes	Active			Non-Lead - Copper
202400	House 1	201	S. State St.	Belle Center	43310	Logan	40.5046	-83.75	Yes	Active			Non-Lead - Copper
202500	House 1	304	Walnut St.	Belle Center	43310	Logan	40.5044	-83.7498	Yes	Active			Non-Lead - Copper
202600	House 1	303	Walnut St.	Belle Center	43310	Logan	40.5048	-83.7494	Yes	Active			Non-Lead - Copper
202700	House 1	305	Walnut St.	Belle Center	43310	Logan	40.5047	-83.7491	Yes	Active			Non-Lead - Copper
203000	House 1	311	Walnut St.	Belle Center	43310	Logan	40.504	-83.7485	Yes	Active			Non-Lead - Copper
203200	House 1	310	Walnut St.	Belle Center	43310	Logan	40.504	-83.7493	Yes	Active			Non-Lead - Copper
203400	House 1	306	Walnut St.	Belle Center	43310	Logan	40.5043	-83.7497	Yes	Active			Non-Lead - Copper
203500	House 1	301	Walnut St.	Belle Center	43310	Logan	40.505	-83.7495	Yes	Active			Non-Lead - Copper
203600	House 1	213	Walnut St.	Belle Center	43310	Logan	40.5052	-83.7501	Yes	Active			Non-Lead - Copper
203700	House 1	105	S. State St.	Belle Center	43310	Logan	40.5052	-83.7494	Yes	Active			Non-Lead - Copper
203900	House 1	216	E. Main St.	Belle Center	43310	Logan	40.5057	-83.7494	Yes	Active			Non-Lead - Copper
204200	House 1	210	E. Main St.	Belle Center	43310	Logan	40.506	-83.7499	Yes	Active			Non-Lead - Copper
204300	House 1	211	Walnut St.	Belle Center	43310	Logan	40.5055	-83.7504	Yes	Active			Non-Lead - Copper
204400	House 1	209	Walnut St.	Belle Center	43310	Logan	40.5055	-83.7507	Yes	Active			Non-Lead - Copper
204500	House 1	208	E. Main St.	Belle Center	43310	Logan	40.5061	-83.7501	Yes	Active			Non-Lead - Copper
204600	House 1	206	E. Main St.	Belle Center	43310	Logan	40.5062	-83.7502	Yes	Active			Non-Lead - Copper
204900	House 1	203	Walnut St.	Belle Center	43310	Logan	40.5058	-83.7512	Yes	Active			Non-Lead - Copper
205000	House 1	201	Walnut St.	Belle Center	43310	Logan	40.5059	-83.7513	Yes	Active			Non-Lead - Copper
205100	church	202	E. Main St.	Belle Center	43310	Logan	40.5064	-83.7506	Yes	Active			Non-Lead - Copper
205200	House 1	207	Walnut St.	Belle Center	43310	Logan	40.5056	-83.7508	Yes	Active			Non-Lead - Copper

Unique Service Line ID	Site Name	Street Number	Street Name	City	Zip Code	County	Latitude	985.0000	In Asset Management	Asset Status	Asset Start Date	Asset End Date	System-Owned Portion Service Line Material Classification
205501	House 1	212	Walnut St.	Belle Center	43310	Logan	40.5049	-83.7505	Yes	Active			Non-Lead - Copper
205600	House 1	209	Maple St.	Belle Center	43310	Logan	40.5045	-83.7511	Yes	Active			Non-Lead - Copper
205700	House 1	210	Walnut St.	Belle Center	43310	Logan	40.505	-83.7506	Yes	Active			Non-Lead - Copper
205800	House 1	207	Maple St.	Belle Center	43310	Logan	40.5046	-83.7514	Yes	Active			Non-Lead - Copper
205900	House 1	205	Maple St.	Belle Center	43310	Logan	40.5048	-83.7516	Yes	Active			Non-Lead - Copper
206000	House 1	208	Walnut St.	Belle Center	43310	Logan	40.5051	-83.7509	Yes	Active			Non-Lead - Copper
206200	House 1	203	Maple St.	Belle Center	43310	Logan	40.5049	-83.7518	Yes	Active			Non-Lead - Copper
206400	House 1	201	Maple St.	Belle Center	43310	Logan	40.5051	-83.7521	Yes	Active			Non-Lead - Copper
206500	church	202	Walnut St.	Belle Center	43310	Logan	40.5055	-83.7516	Yes	Active			Non-Lead - Copper
206600	House 1	115	Maple St.	Belle Center	43310	Logan	40.5053	-83.7524	Yes	Active			Non-Lead - Copper
206700	House 1	112	Walnut St.	Belle Center	43310	Logan	40.5057	-83.752	Yes	Active			Non-Lead - Copper
206800	House 1	110	Walnut St.	Belle Center	43310	Logan	40.5059	-83.7522	Yes	Active			Non-Lead - Copper
206900	House 1	111	Maple St.	Belle Center	43310	Logan	40.5055	-83.7526	Yes	Active			Non-Lead - Copper
207000	House 1	109	Maple St.	Belle Center	43310	Logan	40.5056	-83.7529	Yes	Active			Non-Lead - Copper
207100	House 1	108	Walnut St.	Belle Center	43310	Logan	40.5061	-83.7524	Yes	Active			Non-Lead - Copper
207200	House 1	106	Walnut St.	Belle Center	43310	Logan	40.5062	-83.7527	Yes	Active			Non-Lead - Copper
207300	House 1	107	Maple St.	Belle Center	43310	Logan	40.5058	-83.7531	Yes	Active			Non-Lead - Copper
207400	House 1	104	Walnut St.	Belle Center	43310	Logan	40.5063	-83.7529	Yes	Active			Non-Lead - Copper
207500	House 1	203	S. Elizabeth St.	Belle Center	43310	Logan	40.5064	-83.7533	Yes	Active			Non-Lead - Copper
207600	House 1	205	S. Elizabeth St.	Belle Center	43310	Logan	40.5062	-83.7535	Yes	Active			Non-Lead - Copper
207700	House 1	207	S. Elizabeth St.	Belle Center	43310	Logan	40.5059	-83.7537	Yes	Active			Non-Lead - Copper
207800	House 1	301	S. Elizabeth St.	Belle Center	43310	Logan	40.5057	-83.7539	Yes	Active			Non-Lead - Copper
208000	House 1	305	S. Elizabeth St.	Belle Center	43310	Logan	40.5054	-83.7542	Yes	Active			Non-Lead - Copper
208100	House 1	307	S. Elizabeth St.	Belle Center	43310	Logan	40.5052	-83.7545	Yes	Active			Non-Lead - Copper
208200	House 1	309	S. Elizabeth St.	Belle Center	43310	Logan	40.505	-83.7546	Yes	Active			Non-Lead - Copper
208300	House 1	311	S. Elizabeth St.	Belle Center	43310	Logan	40.5049	-83.7548	Yes	Active			Non-Lead - Copper
208500	House 1	314	S. Elizabeth St.	Belle Center	43310	Logan	40.5049	-83.7554	Yes	Active			Non-Lead - Copper
208600	House 1	312	S. Elizabeth St.	Belle Center	43310	Logan	40.5051	-83.7552	Yes	Active			Non-Lead - Copper
208700	House 1	310	S. Elizabeth St.	Belle Center	43310	Logan	40.5052	-83.7551	Yes	Active			Non-Lead - Copper

Unique Service Line ID	Site Name	Street Number	Street Name	City	Zip Code	County	Latitude	985.0000	In Asset Management	Asset Status	Asset Start Date	Asset End Date	System-Owned Portion Service Line Material Classification
208800	House 1	308	S. Elizabeth St.	Belle Center	43310	Logan	40.5055	-83.7548	Yes	Active			Non-Lead - Copper
208900	House 1	306	S. Elizabeth St.	Belle Center	43310	Logan	40.5056	-83.7547	Yes	Active			Non-Lead - Copper
209100	House 1	302	S. Elizabeth St.	Belle Center	43310	Logan	40.5061	-83.7543	Yes	Active			Non-Lead - Copper
209200	House 1	208	S. Elizabeth St.	Belle Center	43310	Logan	40.5062	-83.7541	Yes	Active			Non-Lead - Copper
209300	House 1	206	S. Elizabeth St.	Belle Center	43310	Logan	40.5064	-83.7539	Yes	Active			Non-Lead - Copper
209400	House 1	204	S. Elizabeth St.	Belle Center	43310	Logan	40.5066	-83.7537	Yes	Active			Non-Lead - Copper
209500	House 1	102	Walnut St.	Belle Center	43310	Logan	40.5065	-83.7531	Yes	Active			Non-Lead - Copper
209800	House 1	202	S. Elizabeth St.	Belle Center	43310	Logan	40.5068	-83.7534	Yes	Active			Non-Lead - Copper
209900	House 1	108	S. Elizabeth St.	Belle Center	43310	Logan	40.5071	-83.7532	Yes	Active			Non-Lead - Copper
209600	House 1	107	S. Elizabeth St.	Belle Center	43310	Logan	40.5068	-83.7529	Yes	Active			Non-Lead - Copper
209700	House 1	105	S. Elizabeth St.	Belle Center	43310	Logan	40.5069	-83.7528	Yes	Active			Non-Lead - Copper
210100	House 1	104	S. Elizabeth St.	Belle Center	43310	Logan	40.5072	-83.753	Yes	Active			Non-Lead - Copper
210200	Business 1	109	W. Main St.	Belle Center	43310	Logan	40.5077	-83.7529	Yes	Active			Non-Lead - Copper
210300	Business 1	107	W. Main St.	Belle Center	43310	Logan	40.5077	-83.7528	Yes	Active			Non-Lead - Copper
210400	Business 1	105	W. Main St.	Belle Center	43310	Logan	40.5077	-83.7527	Yes	Active			Non-Lead - Copper
210500	Business 1	103	W. Main St.	Belle Center	43310	Logan	40.5076	-83.7527	Yes	Active			Non-Lead - Copper
210800	church	102	E. Main St.	Belle Center	43310	Logan	40.5074	-83.7522	Yes	Active			Non-Lead - Copper
211000	House 1	101	S. Elizabeth St.	Belle Center	43310	Logan	40.5072	-83.7525	Yes	Active			Non-Lead - Copper
211100	library	103	S. Elizabeth St.	Belle Center	43310	Logan	40.507	-83.7526	Yes	Active			Non-Lead - Copper
211200	House 1	110	E. Main St.	Belle Center	43310	Logan	40.5072	-83.752	Yes	Active			Non-Lead - Copper
211300	House 1	103	Walnut St.	Belle Center	43310	Logan	40.5068	-83.7525	Yes	Active			Non-Lead - Copper
211400	House 1	112	E. Main St.	Belle Center	43310	Logan	40.5071	-83.7518	Yes	Active			Non-Lead - Copper
211700	House 1	120	E. Main St.	Belle Center	43310	Logan	40.5069	-83.7516	Yes	Active			Non-Lead - Copper
211800	House 1	122	E. Main St.	Belle Center	43310	Logan	40.5069	-83.7515	Yes	Active			Non-Lead - Copper
212000	House 1	107	Walnut St.	Belle Center	43310	Logan	40.5064	-83.7521	Yes	Active			Non-Lead - Copper
212100	Business 1	126	E. Main St.	Belle Center	43310	Logan	40.5068	-83.7513	Yes	Active			Non-Lead - Copper
212400	House 1	115	Walnut St.	Belle Center	43310	Logan	40.5061	-83.7516	Yes	Active			Non-Lead - Copper
300100	House 1	617	N. Center St.	Belle Center	43310	Logan	40.5122	-83.7452	Yes	Active			Non-Lead - Copper
300200	House 1	202	Charles St.	Belle Center	43310	Logan	40.5119	-83.7449	Yes	Active			Non-Lead - Copper

Unique Service Line ID	Site Name	Street Number	Street Name	City	Zip Code	County	Latitude	985.0000	In Asset Management	Asset Status	Asset Start Date	Asset End Date	System-Owned Portion Service Line Material Classification
300300	Business 1	615	N. Center St.	Belle Center	43310	Logan	40.512	-83.7454	Yes	Active			Non-Lead - Copper
300500	House 1	612	N. Center St.	Belle Center	43310	Logan	40.5113	-83.7453	Yes	Active			Non-Lead - Copper
300600	House 1	610	N. Center St.	Belle Center	43310	Logan	40.5112	-83.7456	Yes	Active			Non-Lead - Copper
300800	House 1	606	N. Center St.	Belle Center	43310	Logan	40.5109	-83.7458	Yes	Active			Non-Lead - Copper
300900	House 1	512	N. Center St.	Belle Center	43310	Logan	40.5107	-83.7459	Yes	Active			Non-Lead - Copper
301000	House 1	510	N. Center St.	Belle Center	43310	Logan	40.5106	-83.7461	Yes	Active			Non-Lead - Copper
301100	House 1	508	N. Center St.	Belle Center	43310	Logan	40.5105	-83.7463	Yes	Active			Non-Lead - Copper
301200	House 1	507	N. Center St.	Belle Center	43310	Logan	40.5108	-83.7467	Yes	Active			Non-Lead - Copper
301300	House 1	505	N. Center St.	Belle Center	43310	Logan	40.5106	-83.747	Yes	Active			Non-Lead - Copper
301500	House 1	504	N. Center St.	Belle Center	43310	Logan	40.5102	-83.7467	Yes	Active			Non-Lead - Copper
301700	House 1	502	N. Center St.	Belle Center	43310	Logan	40.5099	-83.7468	Yes	Active			Non-Lead - Copper
301800	House 1	503 1/2	N. State St.	Belle Center	43310	Logan	40.5096	-83.7458	Yes	Active			Non-Lead - Copper
301900	House 1	501	N. Center St.	Belle Center	43310	Logan	40.5103	-83.7472	Yes	Active			Non-Lead - Copper
302000	House 1	407	N. Center St.	Belle Center	43310	Logan	40.5099	-83.7476	Yes	Active			Non-Lead - Copper
302100	House 1	405	N. Center St.	Belle Center	43310	Logan	40.5097	-83.7477	Yes	Active			Non-Lead - Copper
302200	House 1	408	N. Center St.	Belle Center	43310	Logan	40.5097	-83.747	Yes	Active			Non-Lead - Copper
302300	House 1	406	N. Center St.	Belle Center	43310	Logan	40.5095	-83.7472	Yes	Active			Non-Lead - Copper
302400	House 1	403	N. Center St.	Belle Center	43310	Logan	40.5096	-83.7479	Yes	Active			Non-Lead - Copper
302500	House 1	401	N. Center St.	Belle Center	43310	Logan	40.5094	-83.7481	Yes	Active			Non-Lead - Copper
302600	House 1	404	N. Center St.	Belle Center	43310	Logan	40.5093	-83.7474	Yes	Active			Non-Lead - Copper
302700	House 1	402	N. Center St.	Belle Center	43310	Logan	40.5094	-83.7481	Yes	Active			Non-Lead - Copper
302800	House 1	205	E. Vine St.	Belle Center	43310	Logan	40.5089	-83.7473	Yes	Active			Non-Lead - Copper
303000	House 1	308	N. Center St.	Belle Center	43310	Logan	40.5088	-83.7479	Yes	Active			Non-Lead - Copper
303100	House 1	307	N. Center St.	Belle Center	43310	Logan	40.5092	-83.7484	Yes	Active			Non-Lead - Copper
303200	House 1	305	N. Center St.	Belle Center	43310	Logan	40.509	-83.7486	Yes	Active			Non-Lead - Copper
303300	House 1	303	N. Center St.	Belle Center	43310	Logan	40.5088	-83.7489	Yes	Active			Non-Lead - Copper
303400	House 1	302	N. Center St.	Belle Center	43310	Logan	40.5083	-83.7486	Yes	Active			Non-Lead - Copper
303600	House 1	304	N. Center St.	Belle Center	43310	Logan	40.5085	-83.7484	Yes	Active			Non-Lead - Copper
303700	House 1	306	N. Center St.	Belle Center	43310	Logan	40.5087	-83.7481	Yes	Active			Non-Lead - Copper

Unique Service Line ID	Site Name	Street Number	Street Name	City	Zip Code	County	Latitude	985.0000	In Asset Management	Asset Status	Asset Start Date	Asset End Date	System-Owned Portion Service Line Material Classification
303800	House 1	204	E. Vine St.	Belle Center	43310	Logan	40.5086	-83.7476	Yes	Active			Non-Lead - Copper
303900	House 1	206	E. Vine St.	Belle Center	43310	Logan	40.5084	-83.7473	Yes	Active			Non-Lead - Copper
304000	House 1	211	Torrence St.	Belle Center	43310	Logan	40.5079	-83.7479	Yes	Active			Non-Lead - Copper
304100	House 1	305	N. State St.	Belle Center	43310	Logan	40.5079	-83.7472	Yes	Active			Non-Lead - Copper
304200	House 1	210	E. Vine St.	Belle Center	43310	Logan	40.5083	-83.7471	Yes	Active			Non-Lead - Copper
304300	House 1	308	N. State St.	Belle Center	43310	Logan	40.5078	-83.7468	Yes	Active			Non-Lead - Copper
304400	House 1	306	N. State St.	Belle Center	43310	Logan	40.5077	-83.7469	Yes	Active			Non-Lead - Copper
304500	House 1	304	N. State St.	Belle Center	43310	Logan	40.5076	-83.747	Yes	Active			Non-Lead - Copper
304600	House 1	301	Torrence St.	Belle Center	43310	Logan	40.5074	-83.747	Yes	Active			Non-Lead - Copper
304700	House 1	301	N. State St.	Belle Center	43310	Logan	40.5076	-83.7475	Yes	Active			Non-Lead - Copper
304800	House 1	208	Torrence St.	Belle Center	43310	Logan	40.5073	-83.7479	Yes	Active			Non-Lead - Copper
304900	House 1	214	N. State St.	Belle Center	43310	Logan	40.5072	-83.7473	Yes	Active			Non-Lead - Copper
305100	House 1	303	Torrence St.	Belle Center	43310	Logan	40.5072	-83.7465	Yes	Active			Non-Lead - Copper
305200	House 1	308	Torrence St.	Belle Center	43310	Logan	40.5066	-83.7469	Yes	Active			Non-Lead - Copper
305250	House 1	310	Torrence St.	Belle Center	43310	Logan	40.5066	-83.7464	Yes	Active			Non-Lead - Copper
305300	House 1	305	Torrence St.	Belle Center	43310	Logan	40.5071	-83.7463	Yes	Active			Non-Lead - Copper
305400	House 1	307	Torrence St.	Belle Center	43310	Logan	40.5069	-83.746	Yes	Active			Non-Lead - Copper
305500	House 1	402	E. Vine St.	Belle Center	43310	Logan	40.5074	-83.7455	Yes	Active			Non-Lead - Copper
305600	House 1	404	Washington St.	Belle Center	43310	Logan	40.5078	-83.7453	Yes	Active			Non-Lead - Copper
305700	House 1	406	Washington St.	Belle Center	43310	Logan	40.5081	-83.7449	Yes	Active			Non-Lead - Copper
305800	House 1	407	Washington St.	Belle Center	43310	Logan	40.5085	-83.7453	Yes	Active			Non-Lead - Copper
306000	House 1	240	Charles St.	Belle Center	43310	Logan	40.5092	-83.7446	Yes	Active			Non-Lead - Copper
306100	House 1	301	Charles St.	Belle Center	43310	Logan	40.5074	-83.7393	Yes	Active			Non-Lead - Copper
306200	House 1	302	Charles St.	Belle Center	43310	Logan	40.5084	-83.7445	Yes	Active			Non-Lead - Copper
306400	House 1	307	Charles St.	Belle Center	43310	Logan	40.5082	-83.7439	Yes	Active			Non-Lead - Copper
306500	House 1	308	Charles St.	Belle Center	43310	Logan	40.5078	-83.7445	Yes	Active			Non-Lead - Copper
306700	House 1	303	Charles St.	Belle Center	43310	Logan	40.5074	-83.7437	Yes	Active			Non-Lead - Copper
306900	House 1	311	Charles St.	Belle Center	43310	Logan	40.5067	-83.7436	Yes	Active			Non-Lead - Copper
307000	House 1	313	Charles St.	Belle Center	43310	Logan	40.5064	-83.7436	Yes	Active			Non-Lead - Copper

Unique Service Line ID	Site Name	Street Number	Street Name	City	Zip Code	County	Latitude	985.0000	In Asset Management	Asset Status	Asset Start Date	Asset End Date	System-Owned Portion Service Line Material Classification
307200	House 1	404	Charles St.	Belle Center	43310	Logan	40.5062	-83.7442	Yes	Active			Non-Lead - Copper
307300	House 1	315	Charles St.	Belle Center	43310	Logan	40.5061	-83.7435	Yes	Active			Non-Lead - Copper
307400	House 1	316	Charles St.	Belle Center	43310	Logan	40.5073	-83.7444	Yes	Active			Non-Lead - Copper
307600	House 1	406	E. Vine St.	Belle Center	43310	Logan	40.5072	-83.7451	Yes	Active			Non-Lead - Copper
307800	House 1	305	E. Vine St.	Belle Center	43310	Logan	40.508	-83.7457	Yes	Active			Non-Lead - Copper
307900	House 1	308	E. Vine St.	Belle Center	43310	Logan	40.5076	-83.7459	Yes	Active			Non-Lead - Copper
308100	House 1	302	E. Vine St.	Belle Center	43310	Logan	40.508	-83.7466	Yes	Active			Non-Lead - Copper
308200	House 1	303	E. Vine St.	Belle Center	43310	Logan	40.5084	-83.746	Yes	Active			Non-Lead - Copper
308300	House 1	301	E. Vine St.	Belle Center	43310	Logan	40.5084	-83.7462	Yes	Active			Non-Lead - Copper
308400	House 1	209	E. Vine St.	Belle Center	43310	Logan	40.5086	-83.7469	Yes	Active			Non-Lead - Copper
308500	House 1	406	N. State St.	Belle Center	43310	Logan	40.5088	-83.7459	Yes	Active			Non-Lead - Copper
308600	House 1	408	N. State St.	Belle Center	43310	Logan	40.5089	-83.7457	Yes	Active			Non-Lead - Copper
308700	House 1	407	N. State St.	Belle Center	43310	Logan	40.5091	-83.7463	Yes	Active			Non-Lead - Copper
308800	House 1	502	N. State St.	Belle Center	43310	Logan	40.5091	-83.7456	Yes	Active			Non-Lead - Copper
308900	House 1	501	N. State St.	Belle Center	43310	Logan	40.5094	-83.746	Yes	Active			Non-Lead - Copper
309000	House 1	503	N. State St.	Belle Center	43310	Logan	40.5096	-83.7458	Yes	Active			Non-Lead - Copper
309100	House 1	506	N. State St.	Belle Center	43310	Logan	40.5094	-83.7453	Yes	Active			Non-Lead - Copper
309200	House 1	505	N. State St.	Belle Center	43310	Logan	40.5099	-83.7456	Yes	Active			Non-Lead - Copper
309300	House 1	508	N. State St.	Belle Center	43310	Logan	40.5096	-83.7451	Yes	Active			Non-Lead - Copper
209400	House 1	509	N. State St.	Belle Center	43310	Logan	40.5101	-83.7453	Yes	Active			Non-Lead - Copper
309500	House 1	510	N. State St.	Belle Center	43310	Logan	40.5101	-83.7447	Yes	Active			Non-Lead - Copper
309600	House 1	511	N. State St.	Belle Center	43310	Logan	40.5104	-83.7453	Yes	Active			Non-Lead - Copper
309700	House 1	513	N. State St.	Belle Center	43310	Logan	40.5106	-83.7451	Yes	Active			Non-Lead - Copper
309800	House 1	605	N. State St.	Belle Center	43310	Logan	40.5108	-83.7449	Yes	Active			Non-Lead - Copper
309900	House 1	218	Charles St.	Belle Center	43310	Logan	40.511	-83.7448	Yes	Active			Non-Lead - Copper
310000	House 1	10629	CR 102	Belle Center	43310	Logan	40.5137	-83.7421	Yes	Active			Non-Lead - Copper
310100	House 1	10659	CR 102	Belle Center	43310	Logan	40.514	-83.7419	Yes	Active			Non-Lead - Copper
310200	House 1	105	Charles St.	Belle Center	43310	Logan	40.5154	-83.7444	Yes	Active			Non-Lead - Copper
310300	House 1	103	Charles St.	Belle Center	43310	Logan	40.5143	-83.7444	Yes	Active			Non-Lead - Copper

Unique Service Line ID	Site Name	Street Number	Street Name	City	Zip Code	County	Latitude	985.0000	In Asset Management	Asset Status	Asset Start Date	Asset End Date	System-Owned Portion Service Line Material Classification
310500	House 1	104	Charles St.	Belle Center	43310	Logan	40.5138	-83.7455	Yes	Active			Non-Lead - Copper
310700	House 1	408	W. Vine St.	Belle Center	43310	Logan	40.5073	-83.7548	Yes	Active			Non-Lead - Copper
310800	House 1	406	W. Vine St.	Belle Center	43310	Logan	40.5077	-83.7543	Yes	Active			Non-Lead - Copper
311000	House 1	205	W. Main St.	Belle Center	43310	Logan	40.5082	-83.7537	Yes	Active			Non-Lead - Copper
311100	House 1	3562	SR 273 W.	Belle Center	43310	Logan	40.5121	-83.7581	Yes	Active			Non-Lead - Copper
311200	House 1	3496	SR 273 W.	Belle Center	43310	Logan	40.5135	-83.7573	Yes	Active			Non-Lead - Copper
311300	House 1	411	E. Buckeye St.	Belle Center	43310	Logan	40.505	-83.7448	Yes	Active			Non-Lead - Copper
311400	Business 1	414	E. Buckeye St.	Belle Center	43310	Logan	40.505	-83.7462	Yes	Active			Non-Lead - Copper
311500	House 1	246	Charles St.	Belle Center	43310	Logan	40.5097	-83.7446	Yes	Active			Non-Lead - Copper
400200	House 1	108	School St.	Belle Center	43310	Logan	40.511	-83.7471	Yes	Active			Non-Lead - Copper
400400	House 1	106	School St.	Belle Center	43310	Logan	40.5112	-83.7472	Yes	Active			Non-Lead - Copper
400600	House 1	510	N. Elizabeth St.	Belle Center	43310	Logan	40.5115	-83.7476	Yes	Active			Non-Lead - Copper
400800	House 1	509	N. Elizabeth St.	Belle Center	43310	Logan	40.5118	-83.748	Yes	Active			Non-Lead - Copper
400900	House 1	507	N. Elizabeth St.	Belle Center	43310	Logan	40.5116	-83.7482	Yes	Active			Non-Lead - Copper
401000	House 1	508	N. Elizabeth St.	Belle Center	43310	Logan	40.5113	-83.7479	Yes	Active			Non-Lead - Copper
401100	House 1	506	N. Elizabeth St.	Belle Center	43310	Logan	40.5112	-83.7481	Yes	Active			Non-Lead - Copper
401200	House 1	505	N. Elizabeth St.	Belle Center	43310	Logan	40.5115	-83.7483	Yes	Active			Non-Lead - Copper
401300	House 1	503	N. Elizabeth St.	Belle Center	43310	Logan	40.5113	-83.7486	Yes	Active			Non-Lead - Copper
401500	House 1	504	N. Elizabeth St.	Belle Center	43310	Logan	40.5111	-83.7481	Yes	Active			Non-Lead - Copper
401400	House 1	501	N. Elizabeth St.	Belle Center	43310	Logan	40.5111	-83.7488	Yes	Active			Non-Lead - Copper
401600	House 1	502	N. Elizabeth St.	Belle Center	43310	Logan	40.5109	-83.7484	Yes	Active			Non-Lead - Copper
401700	House 1	105	Plum St.	Belle Center	43310	Logan	40.5106	-83.7479	Yes	Active			Non-Lead - Copper
401900	House 1	108	Plum St.	Belle Center	43310	Logan	40.5103	-83.748	Yes	Active			Non-Lead - Copper
402000	House 1	106	Plum St.	Belle Center	43310	Logan	40.5104	-83.7483	Yes	Active			Non-Lead - Copper
402100	House 1	408	N. Elizabeth St.	Belle Center	43310	Logan	40.5106	-83.7485	Yes	Active			Non-Lead - Copper
402200	House 1	407	N. Elizabeth St.	Belle Center	43310	Logan	40.5109	-83.7491	Yes	Active			Non-Lead - Copper
402300	House 1	405	N. Elizabeth St.	Belle Center	43310	Logan	40.5106	-83.7492	Yes	Active			Non-Lead - Copper
402400	House 1	406	N. Elizabeth St.	Belle Center	43310	Logan	40.5104	-83.7489	Yes	Active			Non-Lead - Copper
402500	House 1	404	N. Elizabeth St.	Belle Center	43310	Logan	40.5103	-83.7492	Yes	Active			Non-Lead - Copper

Unique Service Line ID	Site Name	Street Number	Street Name	City	Zip Code	County	Latitude	985.0000	In Asset Management	Asset Status	Asset Start Date	Asset End Date	System-Owned Portion Service Line Material Classification
402600	House 1	403	N. Elizabeth St.	Belle Center	43310	Logan	40.5104	-83.7494	Yes	Active			Non-Lead - Copper
402700	House 1	401	N. Elizabeth St.	Belle Center	43310	Logan	40.5103	-83.7497	Yes	Active			Non-Lead - Copper
402800	House 1	402	N. Elizabeth St.	Belle Center	43310	Logan	40.5101	-83.7492	Yes	Active			Non-Lead - Copper
402900	House 1	307	N. Elizabeth St.	Belle Center	43310	Logan	40.5101	-83.7499	Yes	Active			Non-Lead - Copper
403000	House 1	306	N. Elizabeth St.	Belle Center	43310	Logan	40.5097	-83.7495	Yes	Active			Non-Lead - Copper
403500	House 1	305	N. Elizabeth St.	Belle Center	43310	Logan	40.5099	-83.75	Yes	Active			Non-Lead - Copper
403600	House 1	303	N. Elizabeth St.	Belle Center	43310	Logan	40.5098	-83.7502	Yes	Active			Non-Lead - Copper
403700	House 1	301	N. Elizabeth St.	Belle Center	43310	Logan	40.5097	-83.7503	Yes	Active			Non-Lead - Copper
403801	House 1	304	N. Elizabeth St.	Belle Center	43310	Logan	40.5095	-83.7498	Yes	Active			Non-Lead - Copper
403900	House 1	302	N. Elizabeth St.	Belle Center	43310	Logan	40.5092	-83.75	Yes	Active			Non-Lead - Copper
404000	House 1	209	N. Elizabeth St.	Belle Center	43310	Logan	40.5094	-83.7507	Yes	Active			Non-Lead - Copper
404100	House 1	104	Torrence St.	Belle Center	43310	Logan	40.5091	-83.7503	Yes	Active			Non-Lead - Copper
404200	House 1	105	Torrence St.	Belle Center	43310	Logan	40.509	-83.7497	Yes	Active			Non-Lead - Copper
404300	House 1	107	Torrence St.	Belle Center	43310	Logan	40.5089	-83.7494	Yes	Active			Non-Lead - Copper
404400	House 1	301	N. Center St.	Belle Center	43310	Logan	40.5086	-83.749	Yes	Active			Non-Lead - Copper
404500	House 1	209	N. Center St.	Belle Center	43310	Logan	40.5084	-83.7492	Yes	Active			Non-Lead - Copper
404700	House 1	115	E. Buckeye St.	Belle Center	43310	Logan	40.5078	-83.7497	Yes	Active			Non-Lead - Copper
404800	House 1	113	E. Buckeye St.	Belle Center	43310	Logan	40.5079	-83.75	Yes	Active			Non-Lead - Copper
404900	House 1	111	E. Buckeye St.	Belle Center	43310	Logan	40.508	-83.7503	Yes	Active			Non-Lead - Copper
405000	House 1	108	Torrence St.	Belle Center	43310	Logan	40.5085	-83.7497	Yes	Active			Non-Lead - Copper
405100	House 1	106	Torrence St.	Belle Center	43310	Logan	40.5087	-83.75	Yes	Active			Non-Lead - Copper
405200	House 1	107	E. Buckeye St.	Belle Center	43310	Logan	40.5082	-83.7505	Yes	Active			Non-Lead - Copper
405300	House 1	105	E. Buckeye St.	Belle Center	43310	Logan	40.5083	-83.7507	Yes	Active			Non-Lead - Copper
405400	Business 1	202	N. Elizabeth St.	Belle Center	43310	Logan	40.5087	-83.7508	Yes	Active			Non-Lead - Copper
405700	Business 1	102	W. Buckeye St.	Belle Center	43310	Logan	40.5087	-83.7512	Yes	Active			Non-Lead - Copper
405600	Business 1	102	N. Elizabeth St.	Belle Center	43310	Logan	40.5089	-83.7512	Yes	Active			Non-Lead - Copper
405800	Business 1	101	W. Buckeye St.	Belle Center	43310	Logan	40.5084	-83.7515	Yes	Active			Non-Lead - Copper
405900	Business 1	101	N. Elizabeth St.	Belle Center	43310	Logan	40.5082	-83.7518	Yes	Active			Non-Lead - Copper
406000	Business 1	102	W. Main St.	Belle Center	43310	Logan	40.5078	-83.7523	Yes	Active			Non-Lead - Copper

Unique Service Line ID	Site Name	Street Number	Street Name	City	Zip Code	County	Latitude	985.0000	In Asset Management	Asset Status	Asset Start Date	Asset End Date	System-Owned Portion Service Line Material Classification
406100	Business 1	101 1/2	E. Main St.	Belle Center	43310	Logan	40.5077	-83.752	Yes	Active			Non-Lead - Copper
406400	Business 1	109	E. Main St.	Belle Center	43310	Logan	40.5075	-83.7518	Yes	Active			Non-Lead - Copper
406500	Business 1	105	E. Main St.	Belle Center	43310	Logan	40.5076	-83.7518	Yes	Active			Non-Lead - Copper
406800	House 1	104	E. Buckeye St.	Belle Center	43310	Logan	40.508	-83.751	Yes	Active			Non-Lead - Copper
406900	House 1	106	E. Buckeye St.	Belle Center	43310	Logan	40.5079	-83.7508	Yes	Active			Non-Lead - Copper
407000	House 1	115	E. Main St.	Belle Center	43310	Logan	40.5074	-83.7513	Yes	Active			Non-Lead - Copper
407200	House 1	123	E. Main St.	Belle Center	43310	Logan	40.5072	-83.7511	Yes	Active			Non-Lead - Copper
407300	House 1	108	E. Buckeye St.	Belle Center	43310	Logan	40.5078	-83.7506	Yes	Active			Non-Lead - Copper
407400	House 1	125	E. Main St.	Belle Center	43310	Logan	40.5071	-83.7509	Yes	Active			Non-Lead - Copper
407500	House 1	110	E. Buckeye St.	Belle Center	43310	Logan	40.5076	-83.7504	Yes	Active			Non-Lead - Copper
407600	House 1	112	E. Buckeye St.	Belle Center	43310	Logan	40.5074	-83.75	Yes	Active			Non-Lead - Copper
407700	House 1	202	E. Buckeye St.	Belle Center	43310	Logan	40.5074	-83.7498	Yes	Active			Non-Lead - Copper
407800	House 1	201	E. Main St.	Belle Center	43310	Logan	40.5069	-83.7502	Yes	Active			Non-Lead - Copper
407900	House 1	204	E. Buckeye St.	Belle Center	43310	Logan	40.507	-83.7496	Yes	Active			Non-Lead - Copper
408000	House 1	207	E. Main St.	Belle Center	43310	Logan	40.5064	-83.7499	Yes	Active			Non-Lead - Copper
408100	House 1	209	E. Main St.	Belle Center	43310	Logan	40.5063	-83.7498	Yes	Active			Non-Lead - Copper
408200	House 1	211	E. Main St.	Belle Center	43310	Logan	40.5062	-83.7496	Yes	Active			Non-Lead - Copper
408400	House 1	208	E. Buckeye St.	Belle Center	43310	Logan	40.5067	-83.7491	Yes	Active			Non-Lead - Copper
408500	House 1	215	E. Main St.	Belle Center	43310	Logan	40.5061	-83.7494	Yes	Active			Non-Lead - Copper
408600	House 1	213	E. Buckeye St.	Belle Center	43310	Logan	40.5068	-83.7482	Yes	Active			Non-Lead - Copper
408601	House 1	206	N. State St.	Belle Center	43310	Logan	40.5067	-83.7478	Yes	Active			Non-Lead - Copper
408800	Business 1	202	N. State St.	Belle Center	43310	Logan	40.5069	-83.7477	Yes	Active			Non-Lead - Copper
408900	House 1	210	N. State St.	Belle Center	43310	Logan	40.5069	-83.7475	Yes	Active			Non-Lead - Copper
409000	House 1	211	E. Buckeye St.	Belle Center	43310	Logan	40.5069	-83.7485	Yes	Active			Non-Lead - Copper
409100	House 1	206	Torrence St.	Belle Center	43310	Logan	40.5071	-83.7482	Yes	Active			Non-Lead - Copper
409200	House 1	209	E. Buckeye St.	Belle Center	43310	Logan	40.5071	-83.7487	Yes	Active			Non-Lead - Copper
409300	House 1	207	E. Buckeye St.	Belle Center	43310	Logan	40.5073	-83.7489	Yes	Active			Non-Lead - Copper
409400	House 1	204	Torrence St.	Belle Center	43310	Logan	40.5078	-83.7484	Yes	Active			Non-Lead - Copper
409500	House 1	205	E. Buckeye St.	Belle Center	43310	Logan	40.5074	-83.7492	Yes	Active			Non-Lead - Copper

Unique Service Line ID	Site Name	Street Number	Street Name	City	Zip Code	County	Latitude	985.0000	In Asset Management	Asset Status	Asset Start Date	Asset End Date	System-Owned Portion Service Line Material Classification
409600	House 1	201	E. Buckeye St.	Belle Center	43310	Logan	40.5075	-83.7493	Yes	Active			Non-Lead - Copper
409700	House 1	206	N. Center St.	Belle Center	43310	Logan	40.5079	-83.749	Yes	Active			Non-Lead - Copper
409800	House 1	202	Torrence St.	Belle Center	43310	Logan	40.5081	-83.7488	Yes	Active			Non-Lead - Copper

Inventory												
System-Owned Portion												
If Non-Lead in Column O...		Is the Service Line Metered	Service Line Use	Service Line Size	Service Line Length	Basis of Material Classification	Was the Service Line Material Field Verified?	If Yes in Column W...		Customer-Owned Portion Service Line Material Classification	Service Line Installation Date	Service Line Size
Was Material Ever Previously Lead?	Service Line Installation Date							Describe the Field Verification Method	Enter the Date of Field Verification			
Important for determining if service line requires replacement	Estimated date when the service line was installed or replaced	Service Line Metered or Not Metered	Drinking, Non-Drinking, Combination	Diameter in inches	Length in Feet	Select option from drop down list. If "Other," describe in the Notes field		If Other, describe in the Notes field	Estimated date of field verification or date that the record was updated	If "Non-Lead Other", describe in Comments field	Estimated date when the service line was installed or replaced	Diameter in inches
Yes	3/19/1999	Yes	Drinking	1.50	6	Field inspection only with no records	No			Lead	7/4/1905	1.25
No	4/2/2005	Yes	Drinking	1.25	6	Previous Materials Evaluation	Yes	Visual inspection at the meter pit	5/2/2019	Non-Lead - Copper	7/12/1991	2
No		Yes	Combination	2.50	8	Installation record (e.g., tap card)	No			Non-Lead - Plastic	10/1/2001	2.00
No	1/1/1939	Yes	Drinking	0.75		Field inspection only with no records	Yes	Visual inspection at meter pit	10/8/2018	Non-Lead - Copper		0.75
No	1/1/1939	Yes	Drinking	0.75		Field inspection only with no records	Yes	Visual inspection at meter pit	10/9/2018	Non-Lead - Copper		0.75
No	1/1/1939	Yes	Drinking	0.75		Field inspection only with no records	Yes	Visual inspection at meter pit	10/8/2018	Non-Lead - Copper		0.75
No	1/1/1939	Yes	Drinking	0.75		Field inspection only with no records	Yes	Visual inspection at meter pit	10/8/2018	Non-Lead - Copper		0.75
No	1/1/1939	Yes	Drinking	0.75		Field inspection only with no records	Yes	Visual inspection at meter pit	10/8/2018	Non-Lead - Copper		0.75
No	1/1/1939	Yes	Drinking	0.75		Field inspection only with no records	Yes	Visual inspection at meter pit	10/8/2018	Non-Lead - Copper		0.75
No	1/1/1939	Yes	Drinking	0.75		Field inspection only with no records	Yes	Visual inspection at meter pit	10/8/2018	Non-Lead - Copper		0.75
No	1/1/1939	Yes	Drinking	0.75		Field inspection only with no records	Yes	Visual inspection at meter pit	10/8/2018	Non-Lead - Copper		0.75
No	1/1/1939	Yes	Drinking	0.75		Field inspection only with no records	Yes	Visual inspection at meter pit	10/9/2018	Non-Lead - Copper		0.75
No	1/1/1939	Yes	Drinking	0.75		Field inspection only with no records	Yes	Visual inspection at meter pit	10/11/2018	Non-Lead - Copper		0.75
No	1/1/1939	Yes	Drinking	0.75		Field inspection only with no records	Yes	Visual inspection at meter pit	10/11/2018	Non-Lead - Copper		0.75
No	1/1/1939	Yes	Drinking	0.75		Field inspection only with no records	Yes	Visual inspection at meter pit	10/29/2018	Non-Lead - Copper		0.75
No	1/1/1939	Yes	Drinking	0.75		Field inspection only with no records	Yes	Visual inspection at meter pit	10/11/2018	Non-Lead - Copper		0.75
No	1/1/1939	Yes	Drinking	0.75		Field inspection only with no records	Yes	Visual inspection at meter pit	10/18/2018	Non-Lead - Copper		0.75
No	1/1/1939	Yes	Drinking	0.75		Field inspection only with no records	Yes	Visual inspection at meter pit	10/18/2018	Non-Lead - Copper		0.75
No	1/1/1939	Yes	Drinking	0.75		Field inspection only with no records	Yes	Visual inspection at meter pit	10/18/2018	Non-Lead - Copper		0.75
No	1/1/1939	Yes	Drinking	0.75		Field inspection only with no records	Yes	Visual inspection at meter pit	10/18/2018	Non-Lead - Copper		0.75
No	1/1/1939	Yes	Drinking	0.75		Field inspection only with no records	Yes	Visual inspection at meter pit	10/23/2018	Non-Lead - Copper		0.75
No	1/1/1939	Yes	Drinking	0.75		Field inspection only with no records	Yes	Visual inspection at meter pit	10/23/2018	Non-Lead - Copper		0.75
No	1/1/1939	Yes	Drinking	0.75		Field inspection only with no records	Yes	Visual inspection at meter pit	10/24/2023	Non-Lead - Copper		0.75
No	1/1/1939	Yes	Drinking	0.75		Field inspection only with no records	Yes	Visual inspection at meter pit	10/29/2018	Non-Lead - Copper		0.75
No	1/1/1939	Yes	Drinking	0.75		Field inspection only with no records	Yes	Visual inspection at meter pit	10/24/2018	Non-Lead - Copper		0.75
No	1/1/1939	Yes	Drinking	0.75		Field inspection only with no records	Yes	Visual inspection at meter pit	10/24/2018	Non-Lead - Copper		0.75
No	1/1/2006	Yes	Drinking	0.75		Field inspection only with no records	Yes	Visual inspection at meter pit	8/28/2019	Non-Lead - Copper		0.75

If Non-Lead in Column O...		Is the Service Line Metered	Service Line Use	Service Line Size	Service Line Length	Basis of Material Classification	Was the Service Line Material Field Verified?	If Yes in Column W...		Customer-Owned Portion Service Line Material Classification	Service Line Installation Date	Service Line Size
Was Material Ever Previously Lead?	Service Line Installation Date							Describe the Field Verification Method	Enter the Date of Field Verification			
No	1/1/2004	Yes	Drinking	0.75		Field inspection only with no records	Yes	Visual inspection at meter pit	10/24/2018	Non-Lead - Copper		0.75
No	1/1/1939	Yes	Drinking	0.75		Field inspection only with no records	Yes	Visual inspection at meter pit	10/30/2018	Non-Lead - Copper		0.75
No	1/1/1939	Yes	Drinking	0.75		Field inspection only with no records	Yes	Visual inspection at meter pit	10/30/2018	Non-Lead - Copper		0.75
No	1/1/1939	Yes	Drinking	0.75		Field inspection only with no records	Yes	Visual inspection at meter pit	10/24/2018	Non-Lead - Plastic	10/11/2023	0.75
No	1/1/1939	Yes	Drinking	0.75		Field inspection only with no records	Yes	Visual inspection at meter pit	10/25/2018	Non-Lead - Copper		0.75
No	1/1/1939	Yes	Drinking	0.75		Field inspection only with no records	Yes	Visual inspection at meter pit	10/25/2018	Non-Lead - Plastic		0.75
No	1/1/1939	Yes	Drinking	0.75		Field inspection only with no records	Yes	Visual inspection at meter pit	10/25/2018	Non-Lead - Copper		0.75
No	1/1/1939	Yes	Drinking	0.75		Field inspection only with no records	Yes	Visual inspection at meter pit	10/25/2018	Non-Lead - Copper		0.75
No	1/1/1939	Yes	Drinking	0.75		Field inspection only with no records	Yes	Visual inspection at meter pit	10/25/2018	Non-Lead - Copper		0.75
No	1/1/1939	Yes	Drinking	0.75		Field inspection only with no records	Yes	Visual inspection at meter pit	10/25/2018	Non-Lead - Copper		0.75
No	1/1/1939	Yes	Drinking	0.75		Field inspection only with no records	Yes	Visual inspection at meter pit	10/25/2018	Non-Lead - Copper		0.75
No	4/12/2011	Yes	Drinking	1		Field inspection only with no records	Yes	Visual inspection at meter pit	4/12/2011	Non-Lead - Copper	4/12/2011	1.00
No	1/1/1939	Yes	Drinking	0.75		Field inspection only with no records	Yes	Visual inspection at meter pit	10/25/2018	Non-Lead - Copper		0.75
No	1/1/1939	Yes	Drinking	0.75		Field inspection only with no records	Yes	Visual inspection at meter pit	10/30/2018	Non-Lead - Copper		0.75
No	1/1/1939	Yes	Drinking	0.75		Field inspection only with no records	Yes	Visual inspection at meter pit	10/30/2018	Non-Lead - Copper		0.75
No	1/1/1939	Yes	Drinking	0.75		Field inspection only with no records	Yes	Visual inspection at meter pit	10/30/2018	Non-Lead - Copper		0.75
No	1/1/1939	Yes	Drinking	0.75		Field inspection only with no records	Yes	Visual inspection at meter pit	10/30/2018	Non-Lead - Copper		0.75
No	1/1/1939	Yes	Drinking	0.75		Field inspection only with no records	Yes	Visual inspection at meter pit	10/30/2018	Non-Lead - Copper		0.75
No	1/1/1939	Yes	Drinking	0.75		Field inspection only with no records	Yes	Visual inspection at meter pit	10/30/2018	Non-Lead - Copper		0.75
No	1/1/1939	Yes	Drinking	0.75		Field inspection only with no records	Yes	Visual inspection at meter pit	10/30/2018	Non-Lead - Copper		0.75
No	1/1/1939	Yes	Drinking	0.75		Field inspection only with no records	Yes	Visual inspection at meter pit	10/30/2018	Non-Lead - Copper		0.75
No	1/1/1939	Yes	Drinking	0.75		Field inspection only with no records	Yes	Visual inspection at meter pit	10/30/2018	Non-Lead - Copper		0.75
No	1/1/1939	Yes	Drinking	0.75		Field inspection only with no records	Yes	Visual inspection at meter pit	11/12/2018	Non-Lead - Copper		0.75
No	1/1/1939	Yes	Drinking	0.75		Field inspection only with no records	Yes	Visual inspection at meter pit	10/30/2018	Non-Lead - Copper		0.75
No	1/1/1939	Yes	Drinking	0.75		Field inspection only with no records	Yes	Visual inspection at meter pit	10/30/2018	Non-Lead - Copper		0.75
No	1/1/1939	Yes	Drinking	0.75		Field inspection only with no records	Yes	Visual inspection at meter pit	11/12/2018	Non-Lead - Copper		0.75
No	1/1/1939	Yes	Drinking	0.75		Field inspection only with no records	Yes	Visual inspection at meter pit	11/12/2018	Non-Lead - Copper		0.75

[illegible]

[illegible]

[illegible]

If Non-Lead in Column O...		Is the Service Line Metered	Service Line Use	Service Line Size	Service Line Length	Basis of Material Classification	Was the Service Line Material Field Verified?	If Yes in Column W...		Customer-Owned Portion Service Line Material Classification	Service Line Installation Date	Service Line Size
Was Material Ever Previously Lead?	Service Line Installation Date							Describe the Field Verification Method	Enter the Date of Field Verification			
No	1/1/1939	Yes	Drinking	0.75		Field inspection only with no records	Yes	Visual inspection at meter pit	5/7/2019	Non-Lead - Copper		0.75
No	1/1/1939	Yes	Drinking	0.75		Field inspection only with no records	Yes	Visual inspection at meter pit	5/7/2019	Non-Lead - Copper		0.75
No	1/1/1939	Yes	Drinking	0.75		Field inspection only with no records	Yes	Visual inspection at meter pit	5/7/2019	Non-Lead - Copper		0.75
No	1/1/1939	Yes	Drinking	0.75		Field inspection only with no records	Yes	Visual inspection at meter pit	5/7/2019	Non-Lead - Copper		0.75
No	1/1/1939	Yes	Drinking	0.75		Field inspection only with no records	Yes	Visual inspection at meter pit	8/6/2019	Non-Lead - Copper		0.75
No	1/1/1939	Yes	Drinking	0.75		Field inspection only with no records	Yes	Visual inspection at meter pit	8/6/2019	Non-Lead - Copper		0.75
No	1/1/1939	Yes	Drinking	0.75		Field inspection only with no records	Yes	Visual inspection at meter pit	8/6/2019	Non-Lead - Copper		0.75
No	1/1/1939	Yes	Drinking	0.75		Field inspection only with no records	Yes	Visual inspection at meter pit	10/18/2018	Non-Lead - Copper		0.75
No	1/1/1939	Yes	Drinking	0.75		Field inspection only with no records	Yes	Visual inspection at meter pit	8/6/2019	Non-Lead - Copper		0.75
No	1/1/1939	Yes	Drinking	0.75		Field inspection only with no records	Yes	Visual inspection at meter pit	8/6/2019	Non-Lead - Copper		0.75
No	1/1/1939	Yes	Drinking	0.75		Field inspection only with no records	Yes	Visual inspection at meter pit	8/6/2019	Non-Lead - Copper		0.75
No	1/1/1939	Yes	Drinking	0.75		Field inspection only with no records	Yes	Visual inspection at meter pit	8/6/2019	Non-Lead - Copper		0.75
No	1/1/1939	Yes	Drinking	0.75		Field inspection only with no records	Yes	Visual inspection at meter pit	8/12/2019	Non-Lead - Copper		0.75
No	1/1/1939	Yes	Drinking	0.75		Field inspection only with no records	Yes	Visual inspection at meter pit	8/12/2019	Non-Lead - Copper		0.75
No	1/1/1939	Yes	Drinking	0.75		Field inspection only with no records	Yes	Visual inspection at meter pit	8/12/2019	Non-Lead - Copper		0.75
No	1/1/1939	Yes	Drinking	0.75		Field inspection only with no records	Yes	Visual inspection at meter pit	8/12/2019	Non-Lead - Copper		0.75
No	1/1/1939	Yes	Drinking	0.75		Field inspection only with no records	Yes	Visual inspection at meter pit	8/12/2019	Non-Lead - Copper		0.75
No	1/1/1939	Yes	Drinking	0.75		Field inspection only with no records	Yes	Visual inspection at meter pit	8/12/2019	Non-Lead - Copper		0.75
No	1/1/1939	Yes	Drinking	0.75		Field inspection only with no records	Yes	Visual inspection at meter pit	8/12/2019	Non-Lead - Copper		0.75
No	1/1/1939	Yes	Drinking	0.75		Field inspection only with no records	Yes	Visual inspection at meter pit	8/12/2019	Non-Lead - Copper		0.75
No	1/1/1939	Yes	Drinking	0.75		Field inspection only with no records	Yes	Visual inspection at meter pit	8/13/2019	Non-Lead - Copper		0.75
No	1/1/1939	Yes	Drinking	0.75		Field inspection only with no records	Yes	Visual inspection at meter pit	8/13/2019	Non-Lead - Copper		0.75
No	1/1/1939	Yes	Drinking	0.75		Field inspection only with no records	Yes	Visual inspection at meter pit	8/13/2019	Non-Lead - Copper		0.75
No	1/1/1939	Yes	Drinking	0.75		Field inspection only with no records	Yes	Visual inspection at meter pit	8/13/2019	Non-Lead - Copper		0.75
No	1/1/1939	Yes	Drinking	0.75		Field inspection only with no records	Yes	Visual inspection at meter pit	8/15/2019	Non-Lead - Copper		0.75
No	1/1/1939	Yes	Drinking	0.75		Field inspection only with no records	Yes	Visual inspection at meter pit	8/15/2019	Non-Lead - Copper		0.75

[illegible]

If Non-Lead in Column O...		Is the Service Line Metered	Service Line Use	Service Line Size	Service Line Length	Basis of Material Classification	Was the Service Line Material Field Verified?	If Yes in Column W...		Customer-Owned Portion Service Line Material Classification	Service Line Installation Date	Service Line Size
Was Material Ever Previously Lead?	Service Line Installation Date							Describe the Field Verification Method	Enter the Date of Field Verification			
No	1/1/1939	Yes	Drinking	0.75		Field inspection only with no records	Yes	Visual inspection at meter pit	9/9/2019	Non-Lead - Copper		0.75
No	1/1/1939	Yes	Drinking	0.75		Field inspection only with no records	Yes	Visual inspection at meter pit	9/11/2019	Non-Lead - Copper		0.75
No	1/1/1939	Yes	Drinking	0.75		Field inspection only with no records	Yes	Visual inspection at meter pit	9/11/2019	Non-Lead - Copper		0.75
No	1/1/1939	Yes	Drinking	0.75		Field inspection only with no records	Yes	Visual inspection at meter pit	9/11/2019	Non-Lead - Copper		0.75
No	1/1/1939	Yes	Drinking	0.75		Field inspection only with no records	Yes	Visual inspection at meter pit	9/11/2019	Non-Lead - Copper		0.75
No	1/1/1939	Yes	Drinking	0.75		Field inspection only with no records	Yes	Visual inspection at meter pit	9/11/2019	Non-Lead - Copper		0.75
No	1/1/1939	Yes	Drinking	0.75		Field inspection only with no records	Yes	Visual inspection at meter pit	9/11/2019	Non-Lead - Copper		0.75
No	1/1/1939	Yes	Drinking	0.75		Field inspection only with no records	Yes	Visual inspection at meter pit	9/11/2019	Non-Lead - Copper		0.75
No	1/1/1939	Yes	Drinking	0.75		Field inspection only with no records	Yes	Visual inspection at meter pit	9/11/2019	Non-Lead - Copper		0.75
No	1/1/1939	Yes	Drinking	0.75		Field inspection only with no records	Yes	Visual inspection at meter pit	9/11/2019	Non-Lead - Copper		0.75
No	1/1/1939	Yes	Drinking	0.75		Field inspection only with no records	Yes	Visual inspection at meter pit	9/11/2019	Non-Lead - Copper		0.75
No	1/1/1939	Yes	Drinking	0.75		Field inspection only with no records	Yes	Visual inspection at meter pit	9/11/2019	Non-Lead - Copper		0.75
No	1/1/1939	Yes	Drinking	0.75		Field inspection only with no records	Yes	Visual inspection at meter pit	9/11/2019	Non-Lead - Copper		0.75
No	1/1/1939	Yes	Drinking	0.75		Field inspection only with no records	Yes	Visual inspection at meter pit	9/30/2019	Non-Lead - Copper		0.75
No	1/1/2004	Yes	Drinking	0.75		Field inspection only with no records	Yes	Visual inspection at meter pit	9/30/2019	Non-Lead - Copper		0.75
No	1/1/1939	Yes	Drinking	0.75		Field inspection only with no records	Yes	Visual inspection at meter pit	9/30/2019	Non-Lead - Copper		0.75
No	1/1/1939	Yes	Drinking	0.75		Field inspection only with no records	Yes	Visual inspection at meter pit	9/30/2019	Non-Lead - Copper		0.75
No	1/1/1939	Yes	Drinking	0.75		Field inspection only with no records	Yes	Visual inspection at meter pit	9/30/2019	Non-Lead - Copper		0.75
No	1/1/1959	Yes	Drinking	0.75		Field inspection only with no records	Yes	Visual inspection at meter pit	9/30/2019	Non-Lead - Copper		0.75
No	1/1/1959	Yes	Drinking	0.75		Field inspection only with no records	Yes	Visual inspection at meter pit	9/30/2019	Non-Lead - Copper		0.75
No	1/1/1959	Yes	Drinking	0.75		Field inspection only with no records	Yes	Visual inspection at meter pit	9/30/2019	Non-Lead - Copper		0.75
No	1/1/1959	Yes	Drinking	1		Field inspection only with no records	Yes	Visual inspection at meter pit	9/30/2019	Non-Lead - Copper		1.00
No	1/1/1959	Yes	Drinking	0.75		Field inspection only with no records	Yes	Visual inspection at meter pit	9/30/2019	Non-Lead - Copper		0.75
No	1/1/1959	Yes	Drinking	0.75		Field inspection only with no records	Yes	Visual inspection at meter pit	9/30/2019	Non-Lead - Copper		0.75
No	1/1/1959	Yes	Drinking	0.75		Field inspection only with no records	Yes	Visual inspection at meter pit	9/30/2019	Non-Lead - Copper		0.75
No	1/1/1959	Yes	Drinking	0.75		Field inspection only with no records	Yes	Visual inspection at meter pit	10/1/2019	Non-Lead - Copper		0.75
No	1/1/1959	Yes	Drinking	0.75		Field inspection only with no records	Yes	Visual inspection at meter pit	10/1/2019	Non-Lead - Copper		0.75

[illegible]

If Non-Lead in Column O...		Is the Service Line Metered	Service Line Use	Service Line Size	Service Line Length	Basis of Material Classification	Was the Service Line Material Field Verified?	If Yes in Column W...		Customer-Owned Portion Service Line Material Classification	Service Line Installation Date	Service Line Size
Was Material Ever Previously Lead?	Service Line Installation Date							Describe the Field Verification Method	Enter the Date of Field Verification			
No	1/1/1939	Yes	Drinking	0.75		Field inspection only with no records	Yes	Visual inspection at meter pit	10/4/2019	Non-Lead - Plastic		0.75
No	1/1/1939	Yes	Drinking	0.75		Field inspection only with no records	Yes	Visual inspection at meter pit	10/8/2019	Non-Lead - Copper		0.75
No	1/1/1994	Yes	Drinking	0.75		Field inspection only with no records	Yes	Visual inspection at meter pit	10/8/2019	Non-Lead - Copper		0.75
No	1/1/1939	Yes	Drinking	0.75		Field inspection only with no records	Yes	Visual inspection at meter pit	10/8/2019	Non-Lead - Copper		0.75
No	1/1/1972	Yes	Drinking	0.75		Field inspection only with no records	Yes	Visual inspection at meter pit	10/8/2019	Non-Lead - Copper		0.75
No	1/1/1972	Yes	Drinking	0.75		Field inspection only with no records	Yes	Visual inspection at meter pit	10/8/2019	Non-Lead - Copper		0.75
No	1/1/1939	Yes	Drinking	0.75		Field inspection only with no records	Yes	Visual inspection at meter pit	10/8/2019	Non-Lead - Other		0.75
No	1/1/1939	Yes	Drinking	0.75		Field inspection only with no records	Yes	Visual inspection at meter pit	10/8/2019	Non-Lead - Copper		0.75
No	1/1/1983	Yes	Drinking	0.75		Field inspection only with no records	Yes	Visual inspection at meter pit	10/8/2019	Non-Lead - Copper		0.75
No	1/1/1939	Yes	Drinking	0.75		Field inspection only with no records	Yes	Visual inspection at meter pit	10/8/2019	Non-Lead - Copper		0.75
No	1/1/1939	Yes	Drinking	0.75		Field inspection only with no records	Yes	Visual inspection at meter pit	10/8/2019	Non-Lead - Copper		0.75
No	1/1/1939	Yes	Drinking	0.75		Field inspection only with no records	Yes	Visual inspection at meter pit	10/8/2019	Non-Lead - Copper		0.75
No	1/1/1939	Yes	Drinking	0.75		Field inspection only with no records	Yes	Visual inspection at meter pit	10/10/2019	Non-Lead - Copper		0.75
No	1/1/1939	Yes	Drinking	0.75		Field inspection only with no records	Yes	Visual inspection at meter pit	10/10/2019	Non-Lead - Copper		0.75
No	1/1/1939	Yes	Drinking	0.75		Field inspection only with no records	Yes	Visual inspection at meter pit	10/10/2019	Non-Lead - Copper		0.75
No	1/1/1939	Yes	Drinking	0.75		Field inspection only with no records	Yes	Visual inspection at meter pit	10/10/2019	Non-Lead - Copper		0.75
No	1/1/1939	Yes	Drinking	0.75		Field inspection only with no records	Yes	Visual inspection at meter pit	10/10/2019	Non-Lead - Copper		0.75
No	1/1/1939	Yes	Drinking	0.75		Field inspection only with no records	Yes	Visual inspection at meter pit	10/10/2019	Non-Lead - Copper		0.75
No	1/1/1939	Yes	Drinking	0.75		Field inspection only with no records	Yes	Visual inspection at meter pit	10/10/2019	Non-Lead - Copper		0.75
No	1/1/1939	Yes	Drinking	0.75		Field inspection only with no records	Yes	Visual inspection at meter pit	10/10/2019	Non-Lead - Plastic		0.75
No	1/1/1939	Yes	Drinking	0.75		Field inspection only with no records	Yes	Visual inspection at meter pit	10/10/2019	Non-Lead - Copper		0.75
No	1/1/1939	Yes	Drinking	0.75		Field inspection only with no records	Yes	Visual inspection at meter pit	10/11/2019	Non-Lead - Copper		0.75
No	1/1/1939	Yes	Drinking	0.75		Field inspection only with no records	Yes	Visual inspection at meter pit	10/11/2019	Non-Lead - Copper		0.75
No	1/1/1939	Yes	Drinking	0.75		Field inspection only with no records	Yes	Visual inspection at meter pit	10/11/2019	Non-Lead - Copper		0.75
No	1/1/1939	Yes	Drinking	0.75		Field inspection only with no records	Yes	Visual inspection at meter pit	10/11/2019	Non-Lead - Copper		0.75
No	1/1/1939	Yes	Drinking	0.75		Field inspection only with no records	Yes	Visual inspection at meter pit	10/11/2019	Non-Lead - Copper		0.75
No	1/1/1939	Yes	Drinking	0.75		Field inspection only with no records	Yes	Visual inspection at meter pit	10/11/2019	Non-Lead - Copper		0.75
No	1/1/1939	Yes	Drinking	0.75		Field inspection only with no records	Yes	Visual inspection at meter pit	10/11/2019	Non-Lead - Copper		0.75

[illegible]

[illegible]

If Non-Lead in Column O...		Is the Service Line Metered	Service Line Use	Service Line Size	Service Line Length	Basis of Material Classification	Was the Service Line Material Field Verified?	If Yes in Column W...		Customer-Owned Portion Service Line Material Classification	Service Line Installation Date	Service Line Size
Was Material Ever Previously Lead?	Service Line Installation Date							Describe the Field Verification Method	Enter the Date of Field Verification			
No	1/1/1939	Yes	Drinking	0.75		Field inspection only with no records	Yes	Visual inspection at meter pit	9/4/2020	Non-Lead - Copper		0.75
No	1/1/1939	Yes	Drinking	0.75		Field inspection only with no records	Yes	Visual inspection at meter pit	9/4/2020	Non-Lead - Copper		0.75
No	1/1/1939	Yes	Drinking	0.75		Field inspection only with no records	Yes	Visual inspection at meter pit	9/4/2020	Non-Lead - Copper		0.75

Customer-Owned Portion					Other Potential Sources of Lead		Additional Information	
Service Line Length	Basis of Material Classification	Was the Service Line Material Field Verified?	If Yes in Column AE...		Connector Material Type	Is there Lead Solder in the Service Line?	Building Type Connected to Service Line	If Column AJ includes a school...
			Describe the Field Verification Method	Enter the Date of Field Verification				Lowest Grade Served
Length in Feet	If Other, describe in the Notes field		If Other, describe in the Notes field	Estimated date of field verification or date that the record was updated	For example, lead gooseneck or pigtail where the water main is connected to the service line		This information is for informational purposes only.	
6	Previous materials evaluation	Yes	Visual inspection at the meter pit	5/1/2019	Lead	No	Single Family Structure	
9	Water sampling only with no records	No			Never Lead	No	Single Family Structure with Childcare Facility	
12	Installation record (e.g., tap card)	Yes	Customer self-identification	7/2/2017	Never Lead	No	Non-Residential Building	
	Field inspection only with no records	Yes	Visual inspection at the meter pit	10/8/2018	Never Lead	No	Single Family Structure	
	Field inspection only with no records	Yes	Visual inspection at the meter pit	10/9/2018	Never Lead	No	Single Family Structure	
	Field inspection only with no records	Yes	Visual inspection at the meter pit	10/8/2018	Never Lead	No	Single Family Structure	
	Field inspection only with no records	Yes	Visual inspection at the meter pit	10/8/2018	Never Lead	No	Non-Residential Building	
	Field inspection only with no records	Yes	Visual inspection at the meter pit	10/8/2018	Never Lead	No	Single Family Structure	
	Field inspection only with no records	Yes	Visual inspection at the meter pit	10/8/2018	Never Lead	No	Single Family Structure	
	Field inspection only with no records	Yes	Visual inspection at the meter pit	10/8/2018	Never Lead	No	Single Family Structure	
	Field inspection only with no records	Yes	Visual inspection at the meter pit	10/9/2018	Never Lead	No	Single Family Structure	
	Field inspection only with no records	Yes	Visual inspection at the meter pit	10/11/2018	Never Lead	No	Single Family Structure	
	Field inspection only with no records	Yes	Visual inspection at the meter pit	10/11/2018	Never Lead	No	Single Family Structure	
	Field inspection only with no records	Yes	Visual inspection at the meter pit	10/29/2018	Never Lead	No	Single Family Structure	
	Field inspection only with no records	Yes	Visual inspection at the meter pit	10/11/2018	Never Lead	No	Single Family Structure	
	Field inspection only with no records	Yes	Visual inspection at the meter pit	10/18/2018	Never Lead	No	Single Family Structure	
	Field inspection only with no records	Yes	Visual inspection at the meter pit	10/18/2018	Never Lead	No	Single Family Structure	
	Field inspection only with no records	Yes	Visual inspection at the meter pit	10/18/2018	Never Lead	No	Single Family Structure	
	Field inspection only with no records	Yes	Visual inspection at the meter pit	10/18/2018	Never Lead	No	Single Family Structure	
	Field inspection only with no records	Yes	Visual inspection at the meter pit	10/23/2018	Never Lead	No	Single Family Structure	
	Field inspection only with no records	Yes	Visual inspection at the meter pit	10/23/2018	Never Lead	No	Single Family Structure	
	Field inspection only with no records	Yes	Visual inspection at the meter pit	10/24/2023	Never Lead	No	Single Family Structure	
	Field inspection only with no records	Yes	Visual inspection at the meter pit	10/29/2018	Never Lead	No	Single Family Structure	
	Field inspection only with no records	Yes	Visual inspection at the meter pit	10/24/2018	Never Lead	No	Single Family Structure	
	Field inspection only with no records	Yes	Visual inspection at the meter pit	10/24/2018	Never Lead	No	Single Family Structure	
	Field inspection only with no records	Yes	Visual inspection at the meter pit	8/28/2019	Never Lead	No	Single Family Structure	

Service Line Length	Basis of Material Classification	Was the Service Line Material Field Verified?	If Yes in Column AE...		Connector Material Type	Is there Lead Solder in the Service Line?	Building Type Connected to Service Line	If Column AJ includes a school...
			Describe the Field Verification Method	Enter the Date of Field Verification				Lowest Grade Served
	Field inspection only with no records	Yes	Visual inspection at the meter pit	10/24/2018	Never Lead	No	Single Family Structure	
	Field inspection only with no records	Yes	Visual inspection at the meter pit	10/30/2018	Never Lead	No	Single Family Structure	
	Field inspection only with no records	Yes	Visual inspection at the meter pit	10/30/2018	Never Lead	No	Single Family Structure	
	Field inspection only with no records	Yes	Visual inspection at the meter pit	10/24/2023	Never Lead	No	Single Family Structure	
	Field inspection only with no records	Yes	Visual inspection at the meter pit	10/25/2018	Never Lead	No	Single Family Structure	
	Field inspection only with no records	Yes	Visual inspection at the meter pit	10/25/2018	Never Lead	No	Single Family Structure	
	Field inspection only with no records	Yes	Visual inspection at the meter pit	10/25/2018	Never Lead	No	Single Family Structure	
	Field inspection only with no records	Yes	Visual inspection at the meter pit	10/25/2018	Never Lead	No	Single Family Structure	
	Field inspection only with no records	Yes	Visual inspection at the meter pit	10/25/2018	Never Lead	No	Single Family Structure	
	Field inspection only with no records	Yes	Visual inspection at the meter pit	10/25/2018	Never Lead	No	Single Family Structure	
	Field inspection only with no records	Yes	Visual inspection at the meter pit	10/25/2018	Never Lead	No	Single Family Structure	
	Field inspection only with no records	Yes	Visual inspection at the meter pit	8/28/2024	Never Lead	No	Single Family Structure	
	Field inspection only with no records	Yes	Visual inspection at the meter pit	10/25/2018	Never Lead	No	Single Family Structure	
	Field inspection only with no records	Yes	Visual inspection at the meter pit	10/30/2018	Never Lead	No	Single Family Structure	
	Field inspection only with no records	Yes	Visual inspection at the meter pit	10/30/2018	Never Lead	No	Single Family Structure	
	Field inspection only with no records	Yes	Visual inspection at the meter pit	10/30/2018	Never Lead	No	Single Family Structure	
	Field inspection only with no records	Yes	Visual inspection at the meter pit	10/30/2018	Never Lead	No	Single Family Structure	
	Field inspection only with no records	Yes	Visual inspection at the meter pit	10/30/2018	Never Lead	No	Single Family Structure	
	Field inspection only with no records	Yes	Visual inspection at the meter pit	10/30/2018	Never Lead	No	Single Family Structure	
	Field inspection only with no records	Yes	Visual inspection at the meter pit	10/30/2018	Never Lead	No	Single Family Structure	
	Field inspection only with no records	Yes	Visual inspection at the meter pit	10/30/2018	Never Lead	No	Single Family Structure	
	Field inspection only with no records	Yes	Visual inspection at the meter pit	10/30/2018	Never Lead	No	Single Family Structure	
	Field inspection only with no records	Yes	Visual inspection at the meter pit	11/12/2018	Never Lead	No	Single Family Structure	
	Field inspection only with no records	Yes	Visual inspection at the meter pit	10/30/2018	Never Lead	No	Single Family Structure	
	Field inspection only with no records	Yes	Visual inspection at the meter pit	10/30/2018	Never Lead	No	Single Family Structure	
	Field inspection only with no records	Yes	Visual inspection at the meter pit	11/12/2018	Never Lead	No	Single Family Structure	
	Field inspection only with no records	Yes	Visual inspection at the meter pit	11/12/2018	Never Lead	No	Single Family Structure	

Service Line Length	Basis of Material Classification	Was the Service Line Material Field Verified?	If Yes in Column AE...		Connector Material Type	Is there Lead Solder in the Service Line?	Building Type Connected to Service Line	If Column AJ includes a school...
			Describe the Field Verification Method	Enter the Date of Field Verification				Lowest Grade Served
	Field inspection only with no records	Yes	Visual inspection at the meter pit	11/12/2018	Never Lead	No	Single Family Structure	
	Field inspection only with no records	Yes	Visual inspection at the meter pit	11/13/2018	Never Lead	No	Single Family Structure	
	Field inspection only with no records	Yes	Visual inspection at the meter pit	11/13/2018	Never Lead	No	Single Family Structure	
	Field inspection only with no records	Yes	Visual inspection at the meter pit	11/13/2018	Never Lead	No	Single Family Structure	
	Field inspection only with no records	Yes	Visual inspection at the meter pit	11/13/2018	Never Lead	No	Single Family Structure	
	Field inspection only with no records	Yes	Visual inspection at the meter pit	11/13/2018	Never Lead	No	Single Family Structure	
	Field inspection only with no records	Yes	Visual inspection at the meter pit	11/13/2018	Never Lead	No	Single Family Structure	
	Field inspection only with no records	Yes	Visual inspection at the meter pit	11/18/2018	Never Lead	No	Single Family Structure	
	Field inspection only with no records	Yes	Mechanical excavation at multiple locations	5/1/2018	Never Lead	No	Single Family Structure	
	Field inspection only with no records	Yes	Visual inspection at the meter pit	11/14/2018	Never Lead	No	Single Family Structure	
	Field inspection only with no records	Yes	Visual inspection at the meter pit	11/14/2018	Never Lead	No	Single Family Structure	
	Field inspection only with no records	Yes	Visual inspection at the meter pit	11/14/2018	Never Lead	No	Single Family Structure	
	Field inspection only with no records	Yes	Visual inspection at the meter pit	11/14/2018	Never Lead	No	Single Family Structure	
	Field inspection only with no records	Yes	Visual inspection at the meter pit	4/5/2019	Never Lead	No	Single Family Structure	
	Field inspection only with no records	Yes	Visual inspection at the meter pit	4/5/2019	Never Lead	No	Single Family Structure	
	Field inspection only with no records	Yes	Visual inspection at the meter pit	12/19/2018	Never Lead	No	Single Family Structure	
	Field inspection only with no records	Yes	Visual inspection at the meter pit	12/19/2018	Never Lead	No	Single Family Structure	
	Field inspection only with no records	Yes	Visual inspection at the meter pit	12/19/2018	Never Lead	No	Single Family Structure	
	Field inspection only with no records	Yes	Visual inspection at the meter pit	4/5/2019	Never Lead	No	Single Family Structure	
	Field inspection only with no records	Yes	Visual inspection at the meter pit	4/5/2019	Never Lead	No	Single Family Structure	
	Field inspection only with no records	Yes	Visual inspection at the meter pit	4/5/2019	Never Lead	No	Single Family Structure	
	Field inspection only with no records	Yes	Visual inspection at the meter pit	4/5/2019	Never Lead	No	Single Family Structure	
	Field inspection only with no records	Yes	Visual inspection at the meter pit	4/5/2019	Never Lead	No	Single Family Structure	
	Field inspection only with no records	Yes	Visual inspection at the meter pit	4/8/2019	Never Lead	No	Single Family Structure	
	Field inspection only with no records	Yes	Visual inspection at the meter pit	4/8/2019	Never Lead	No	Non-Residential Building	
	Field inspection only with no records	Yes	Visual inspection at the meter pit	4/8/2019	Never Lead	No	Single Family Structure	
	Field inspection only with no records	Yes	Visual inspection at the meter pit	4/8/2019	Never Lead	No	Single Family Structure	
	Field inspection only with no records	Yes	Visual inspection at the meter pit	4/8/2019	Never Lead	No	Single Family Structure	
	Field inspection only with no records	Yes	Visual inspection at the meter pit	4/8/2019	Never Lead	No	Single Family Structure	
	Field inspection only with no records	Yes	Visual inspection at the meter pit	4/8/2019	Never Lead	No	Single Family Structure	

[illegible]

Service Line Length	Basis of Material Classification	Was the Service Line Material Field Verified?	If Yes in Column AE...		Connector Material Type	Is there Lead Solder in the Service Line?	Building Type Connected to Service Line	If Column AJ includes a school...
			Describe the Field Verification Method	Enter the Date of Field Verification				Lowest Grade Served
	Field inspection only with no records	Yes	Visual inspection at the meter pit	4/22/2019	Never Lead	No	Single Family Structure	
	Field inspection only with no records	Yes	Visual inspection at the meter pit	4/22/2019	Never Lead	No	single Family Structure	
	Field inspection only with no records	Yes	Visual inspection at the meter pit	4/22/2019	Never Lead	No	single Family Structure	
	Field inspection only with no records	Yes	Visual inspection at the meter pit	4/22/2019	Never Lead	No	Single Family Structure	
	Field inspection only with no records	Yes	Visual inspection at the meter pit	4/22/2019	Never Lead	No	Single Family Structure	
	Field inspection only with no records	Yes	Visual inspection at the meter pit	7/7/2020	Never Lead	No	Single Family Structure	
	Field inspection only with no records	Yes	Visual inspection at the meter pit	4/22/2019	Never Lead	No	Single Family Structure	
	Field inspection only with no records	Yes	Visual inspection at the meter pit	4/23/2019	Never Lead	No	single Family Structure	
	Field inspection only with no records	Yes	Visual inspection at the meter pit	4/23/2019	Never Lead	No	Single Family Structure	
	Field inspection only with no records	Yes	Visual inspection at the meter pit	4/23/2019	Never Lead	No	Single Family Structure	
	Field inspection only with no records	Yes	Visual inspection at the meter pit	4/23/2019	Never Lead	No	single Family Structure	
	Field inspection only with no records	Yes	Visual inspection at the meter pit	4/23/2019	Never Lead	No	Single Family Structure	
	Field inspection only with no records	Yes	Visual inspection at the meter pit	4/23/2019	Never Lead	No	single Family Structure	
	Field inspection only with no records	Yes	Visual inspection at the meter pit	4/23/2019	Never Lead	No	Single Family Structure	
	Field inspection only with no records	Yes	Visual inspection at the meter pit	4/23/2019	Never Lead	No	Single Family Structure	
	Field inspection only with no records	Yes	Visual inspection at the meter pit	4/23/2019	Never Lead	No	Non-Residential Building	
	Field inspection only with no records	Yes	Visual inspection at the meter pit	4/23/2019	Never Lead	No	Single Family Structure	
	Field inspection only with no records	Yes	Visual inspection at the meter pit	5/1/2022	Never Lead	No	single Family Structure	
	Field inspection only with no records	Yes	Visual inspection at the meter pit	2/14/2019	Never Lead	No	Single Family Structure	
	Field inspection only with no records	Yes	Visual inspection at the meter pit	4/23/2019	Never Lead	No	Single Family Structure	
	Field inspection only with no records	Yes	Visual inspection at the meter pit	4/23/2019	Never Lead	No	Single Family Structure	
	Field inspection only with no records	Yes	Visual inspection at the meter pit	4/23/2019	Never Lead	No	single Family Structure	
	Field inspection only with no records	Yes	Visual inspection at the meter pit	4/23/2019	Never Lead	No	Single Family Structure	
	Field inspection only with no records	Yes	Visual inspection at the meter pit	4/24/2019	Never Lead	No	Single Family Structure	
	Field inspection only with no records	Yes	Visual inspection at the meter pit	4/24/2019	Never Lead	No	Single Family Structure	
	Field inspection only with no records	Yes	Visual inspection at the meter pit	4/24/2019	Never Lead	No	Non-Residential Building	
	Field inspection only with no records	Yes	Visual inspection at the meter pit	4/24/2019	Never Lead	No	Single Family Structure	

Service Line Length	Basis of Material Classification	Was the Service Line Material Field Verified?	If Yes in Column AE...		Connector Material Type	Is there Lead Solder in the Service Line?	Building Type Connected to Service Line	If Column AJ includes a school...
			Describe the Field Verification Method	Enter the Date of Field Verification				Lowest Grade Served
	Field inspection only with no records	Yes	Visual inspection at the meter pit	4/24/2019	Never Lead	No	Single Family Structure	
	Field inspection only with no records	Yes	Visual inspection at the meter pit	4/3/2019	Never Lead	No	Single Family Structure	
	Field inspection only with no records	Yes	Visual inspection at the meter pit	1/31/2019	Never Lead	No	Single Family Structure	
	Field inspection only with no records	Yes	Visual inspection at the meter pit	4/24/2019	Never Lead	No	Single Family Structure	
	Field inspection only with no records	Yes	Visual inspection at the meter pit	4/24/2019	Never Lead	No	Single Family Structure	
	Field inspection only with no records	Yes	Visual inspection at the meter pit	4/25/2019	Never Lead	No	Single Family Structure	
	Field inspection only with no records	Yes	Visual inspection at the meter pit	4/24/2019	Never Lead	No	Single Family Structure	
	Field inspection only with no records	Yes	Visual inspection at the meter pit	4/24/2019	Never Lead	No	single Family Structure	
	Field inspection only with no records	Yes	Visual inspection at the meter pit	4/24/2019	Never Lead	No	Non-Residential Building	
	Field inspection only with no records	Yes	Visual inspection at the meter pit	4/25/2019	Never Lead	No	Single Family Structure	
	Field inspection only with no records	Yes	Visual inspection at the meter pit	4/22/2019	Never Lead	No	single Family Structure	
	Field inspection only with no records	Yes	Visual inspection at the meter pit	5/6/2019	Never Lead	No	single Family Structure	
	Field inspection only with no records	Yes	Visual inspection at the meter pit	5/6/2019	Never Lead	No	Single Family Structure	
	Field inspection only with no records	Yes	Visual inspection at the meter pit	5/6/2019	Never Lead	No	single Family Structure	
	Field inspection only with no records	Yes	Visual inspection at the meter pit	5/6/2019	Never Lead	No	Single Family Structure	
	Field inspection only with no records	Yes	Visual inspection at the meter pit	5/6/2019	Never Lead	No	Single Family Structure	
	Field inspection only with no records	Yes	Visual inspection at the meter pit	7/11/2024	Never Lead	No	single Family Structure	
	Field inspection only with no records	Yes	Visual inspection at the meter pit	5/6/2019	Never Lead	No	Single Family Structure	
	Field inspection only with no records	Yes	Visual inspection at the meter pit	5/6/2019	Never Lead	No	Single Family Structure	
	Field inspection only with no records	Yes	Visual inspection at the meter pit	5/6/2019	Never Lead	No	Single Family Structure	
	Field inspection only with no records	Yes	Visual inspection at the meter pit	5/7/2019	Never Lead	No	Single Family Structure	
	Field inspection only with no records	Yes	Visual inspection at the meter pit	5/7/2019	Never Lead	No	Single Family Structure	
	Field inspection only with no records	Yes	Visual inspection at the meter pit	5/7/2019	Never Lead	No	single Family Structure	
	Field inspection only with no records	Yes	Visual inspection at the meter pit	5/7/2019	Never Lead	No	single Family Structure	
	Field inspection only with no records	Yes	Visual inspection at the meter pit	5/7/2019	Never Lead	No	Single Family Structure	
	Field inspection only with no records	Yes	Visual inspection at the meter pit	5/7/2019	Never Lead	No	Single Family Structure	
	Field inspection only with no records	Yes	Visual inspection at the meter pit	5/7/2019	Never Lead	No	Single Family Structure	
	Field inspection only with no records	Yes	Visual inspection at the meter pit	5/7/2019	Never Lead	No	Single Family Structure	
	Field inspection only with no records	Yes	Visual inspection at the meter pit	5/7/2019	Never Lead	No	single Family Structure	

Service Line Length	Basis of Material Classification	Was the Service Line Material Field Verified?	If Yes in Column AE...		Connector Material Type	Is there Lead Solder in the Service Line?	Building Type Connected to Service Line	If Column AJ includes a school...
			Describe the Field Verification Method	Enter the Date of Field Verification				Lowest Grade Served
	Field inspection only with no records	Yes	Visual inspection at the meter pit	5/7/2019	Never Lead	No	Single Family Structure	
	Field inspection only with no records	Yes	Visual inspection at the meter pit	5/7/2019	Never Lead	No	Single Family Structure	
	Field inspection only with no records	Yes	Visual inspection at the meter pit	5/7/2019	Never Lead	No	Single Family Structure	
	Field inspection only with no records	Yes	Visual inspection at the meter pit	5/7/2019	Never Lead	No	single Family Structure	
	Field inspection only with no records	Yes	Visual inspection at the meter pit	8/6/2019	Never Lead	No	Single Family Structure	
	Field inspection only with no records	Yes	Visual inspection at the meter pit	8/6/2019	Never Lead	No	Single Family Structure	
	Field inspection only with no records	Yes	Visual inspection at the meter pit	8/6/2019	Never Lead	No	single Family Structure	
	Field inspection only with no records	Yes	Visual inspection at the meter pit	10/18/2018	Never Lead	No	Single Family Structure	
	Field inspection only with no records	Yes	Visual inspection at the meter pit	8/6/2019	Never Lead	No	Single Family Structure	
	Field inspection only with no records	Yes	Visual inspection at the meter pit	8/6/2019	Never Lead	No	Single Family Structure	
	Field inspection only with no records	Yes	Visual inspection at the meter pit	8/6/2019	Never Lead	No	Single Family Structure	
	Field inspection only with no records	Yes	Visual inspection at the meter pit	8/6/2019	Never Lead	No	single Family Structure	
	Field inspection only with no records	Yes	Visual inspection at the meter pit	8/6/2019	Never Lead	No	Non-Residential Building	
	Field inspection only with no records	Yes	Visual inspection at the meter pit	8/12/2019	Never Lead	No	Non-Residential Building	
	Field inspection only with no records	Yes	Visual inspection at the meter pit	8/12/2019	Never Lead	No	Non-Residential Building	
	Field inspection only with no records	Yes	Visual inspection at the meter pit	8/12/2019	Never Lead	No	Non-Residential Building	
	Field inspection only with no records	Yes	Visual inspection at the meter pit	8/12/2019	Never Lead	No	Non-Residential Building	
	Field inspection only with no records	Yes	Visual inspection at the meter pit	8/12/2019	Never Lead	No	Single Family Structure	
	Field inspection only with no records	Yes	Visual inspection at the meter pit	8/12/2019	Never Lead	No	Non-Residential Building	
	Field inspection only with no records	Yes	Visual inspection at the meter pit	8/12/2019	Never Lead	No	Single Family Structure	
	Field inspection only with no records	Yes	Visual inspection at the meter pit	8/12/2019	Never Lead	No	Single Family Structure	
	Field inspection only with no records	Yes	Visual inspection at the meter pit	8/13/2019	Never Lead	No	Single Family Structure	
	Field inspection only with no records	Yes	Visual inspection at the meter pit	8/13/2019	Never Lead	No	Single Family Structure	
	Field inspection only with no records	Yes	Visual inspection at the meter pit	8/13/2019	Never Lead	No	Single Family Structure	
	Field inspection only with no records	Yes	Visual inspection at the meter pit	8/13/2019	Never Lead	No	Single Family Structure	
	Field inspection only with no records	Yes	Visual inspection at the meter pit	8/13/2019	Never Lead	No	Single Family Structure	
	Field inspection only with no records	Yes	Visual inspection at the meter pit	8/15/2019	Never Lead	No	Single Family Structure	
	Field inspection only with no records	Yes	Visual inspection at the meter pit	8/15/2019	Never Lead	No	single Family Structure	

Service Line Length	Basis of Material Classification	Was the Service Line Material Field Verified?	If Yes in Column AE...		Connector Material Type	Is there Lead Solder in the Service Line?	Building Type Connected to Service Line	If Column AJ includes a school...
			Describe the Field Verification Method	Enter the Date of Field Verification				Lowest Grade Served
	Field inspection only with no records	Yes	Visual inspection at the meter pit	8/15/2019	Never Lead	No	Single Family Structure	
	Field inspection only with no records	Yes	Visual inspection at the meter pit	8/15/2019	Never Lead	No	Single Family Structure	
	Field inspection only with no records	Yes	Visual inspection at the meter pit	8/15/2019	Never Lead	No	single Family Structure	
	Field inspection only with no records	Yes	Visual inspection at the meter pit	8/15/2019	Never Lead	No	single Family Structure	
	Field inspection only with no records	Yes	Visual inspection at the meter pit	8/15/2019	Never Lead	No	Single Family Structure	
	Field inspection only with no records	Yes	Visual inspection at the meter pit	8/15/2019	Never Lead	No	single Family Structure	
	Field inspection only with no records	Yes	Visual inspection at the meter pit	8/15/2019	Never Lead	No	Single Family Structure	
	Field inspection only with no records	Yes	Visual inspection at the meter pit	8/15/2019	Never Lead	No	Single Family Structure	
	Field inspection only with no records	Yes	Visual inspection at the meter pit	8/15/2019	Never Lead	No	single Family Structure	
	Field inspection only with no records	Yes	Visual inspection at the meter pit	8/15/2019	Never Lead	No	Single Family Structure	
	Field inspection only with no records	Yes	Visual inspection at the meter pit	8/15/2019	Never Lead	No	Single Family Structure	
	Field inspection only with no records	Yes	Visual inspection at the meter pit	8/15/2019	Never Lead	No	Single Family Structure	
	Field inspection only with no records	Yes	Visual inspection at the meter pit	8/15/2019	Never Lead	No	Single Family Structure	
	Field inspection only with no records	Yes	Visual inspection at the meter pit	9/5/2019	Never Lead	No	Single Family Structure	
	Field inspection only with no records	Yes	Visual inspection at the meter pit	9/5/2019	Never Lead	No	single Family Structure	
	Field inspection only with no records	Yes	Visual inspection at the meter pit	9/5/2019	Never Lead	No	single Family Structure	
	Field inspection only with no records	Yes	Visual inspection at the meter pit	9/5/2019	Never Lead	No	Single Family Structure	
	Field inspection only with no records	Yes	Visual inspection at the meter pit	9/5/2019	Never Lead	No	Single Family Structure	
	Field inspection only with no records	Yes	Visual inspection at the meter pit	9/5/2019	Never Lead	No	Single Family Structure	
	Field inspection only with no records	Yes	Visual inspection at the meter pit	9/5/2019	Never Lead	No	Single Family Structure	
	Field inspection only with no records	Yes	Visual inspection at the meter pit	9/5/2019	Never Lead	No	Single Family Structure	
	Field inspection only with no records	Yes	Visual inspection at the meter pit	9/5/2019	Never Lead	No	single Family Structure	
	Field inspection only with no records	Yes	Visual inspection at the meter pit	9/5/2019	Never Lead	No	Single Family Structure	
	Field inspection only with no records	Yes	Visual inspection at the meter pit	9/5/2019	Never Lead	No	Single Family Structure	
	Field inspection only with no records	Yes	Visual inspection at the meter pit	9/5/2019	Never Lead	No	single Family Structure	
	Field inspection only with no records	Yes	Visual inspection at the meter pit	9/9/2019	Never Lead	No	Single Family Structure	
	Field inspection only with no records	Yes	Visual inspection at the meter pit	9/9/2019	Never Lead	No	Single Family Structure	
	Field inspection only with no records	Yes	Visual inspection at the meter pit	9/9/2019	Never Lead	No	single Family Structure	
	Field inspection only with no records	Yes	Visual inspection at the meter pit	9/9/2019	Never Lead	No	Single Family Structure	

Service Line Length	Basis of Material Classification	Was the Service Line Material Field Verified?	If Yes in Column AE...		Connector Material Type	Is there Lead Solder in the Service Line?	Building Type Connected to Service Line	If Column AJ includes a school...
			Describe the Field Verification Method	Enter the Date of Field Verification				Lowest Grade Served
	Field inspection only with no records	Yes	Visual inspection at the meter pit	9/9/2019	Never Lead	No	Single Family Structure	
	Field inspection only with no records	Yes	Visual inspection at the meter pit	9/11/2019	Never Lead	No	Single Family Structure	
	Field inspection only with no records	Yes	Visual inspection at the meter pit	9/11/2019	Never Lead	No	Single Family Structure	
	Field inspection only with no records	Yes	Visual inspection at the meter pit	9/11/2019	Never Lead	No	single Family Structure	
	Field inspection only with no records	Yes	Visual inspection at the meter pit	9/11/2019	Never Lead	No	Single Family Structure	
	Field inspection only with no records	Yes	Visual inspection at the meter pit	9/11/2019	Never Lead	No	Single Family Structure	
	Field inspection only with no records	Yes	Visual inspection at the meter pit	9/11/2019	Never Lead	No	Single Family Structure	
	Field inspection only with no records	Yes	Visual inspection at the meter pit	9/11/2019	Never Lead	No	Single Family Structure	
	Field inspection only with no records	Yes	Visual inspection at the meter pit	9/11/2019	Never Lead	No	Single Family Structure	
	Field inspection only with no records	Yes	Visual inspection at the meter pit	9/11/2019	Never Lead	No	Single Family Structure	
	Field inspection only with no records	Yes	Visual inspection at the meter pit	9/11/2019	Never Lead	No	Single Family Structure	
	Field inspection only with no records	Yes	Visual inspection at the meter pit	9/11/2019	Never Lead	No	Single Family Structure	
	Field inspection only with no records	Yes	Visual inspection at the meter pit	9/11/2019	Never Lead	No	Single Family Structure	
	Field inspection only with no records	Yes	Visual inspection at the meter pit	9/30/2019	Never Lead	No	Single Family Structure	
	Field inspection only with no records	Yes	Visual inspection at the meter pit	9/30/2019	Never Lead	No	Single Family Structure	
	Field inspection only with no records	Yes	Visual inspection at the meter pit	9/30/2019	Never Lead	No	Single Family Structure	
	Field inspection only with no records	Yes	Visual inspection at the meter pit	9/30/2019	Never Lead	No	Single Family Structure	
	Field inspection only with no records	Yes	Visual inspection at the meter pit	9/30/2019	Never Lead	No	Single Family Structure	
	Field inspection only with no records	Yes	Visual inspection at the meter pit	9/30/2019	Never Lead	No	Single Family Structure	
	Field inspection only with no records	Yes	Visual inspection at the meter pit	9/30/2019	Never Lead	No	single Family Structure	
	Field inspection only with no records	Yes	Visual inspection at the meter pit	9/30/2019	Never Lead	No	Single Family Structure	
	Field inspection only with no records	Yes	Visual inspection at the meter pit	9/30/2019	Never Lead	No	Single Family Structure	
	Field inspection only with no records	Yes	Visual inspection at the meter pit	9/30/2019	Never Lead	No	single Family Structure	
	Field inspection only with no records	Yes	Visual inspection at the meter pit	9/30/2019	Never Lead	No	Single Family Structure	
	Field inspection only with no records	Yes	Visual inspection at the meter pit	9/30/2019	Never Lead	No	single Family Structure	
	Field inspection only with no records	Yes	Visual inspection at the meter pit	10/1/2019	Never Lead	No	Single Family Structure	
	Field inspection only with no records	Yes	Visual inspection at the meter pit	10/1/2019	Never Lead	No	Single Family Structure	

Service Line Length	Basis of Material Classification	Was the Service Line Material Field Verified?	If Yes in Column AE...		Connector Material Type	Is there Lead Solder in the Service Line?	Building Type Connected to Service Line	If Column AJ includes a school...
			Describe the Field Verification Method	Enter the Date of Field Verification				Lowest Grade Served
	Field inspection only with no records	Yes	Visual inspection at the meter pit	10/1/2019	Never Lead	No	single Family Structure	
	Field inspection only with no records	Yes	Visual inspection at the meter pit	10/1/2019	Never Lead	No	Single Family Structure	
	Field inspection only with no records	Yes	Visual inspection at the meter pit	10/1/2019	Never Lead	No	Single Family Structure	
	Field inspection only with no records	Yes	Visual inspection at the meter pit	10/1/2019	Never Lead	No	Single Family Structure	
	Field inspection only with no records	Yes	Visual inspection at the meter pit	10/1/2019	Never Lead	No	Single Family Structure	
	Field inspection only with no records	Yes	Visual inspection at the meter pit	10/1/2019	Never Lead	No	Single Family Structure	
	Field inspection only with no records	Yes	Visual inspection at the meter pit	10/3/2019	Never Lead	No	single Family Structure	
	Field inspection only with no records	Yes	Visual inspection at the meter pit	10/3/2019	Never Lead	No	single Family Structure	
	Field inspection only with no records	Yes	Visual inspection at the meter pit	10/3/2019	Never Lead	No	Single Family Structure	
	Field inspection only with no records	Yes	Visual inspection at the meter pit	10/3/2019	Never Lead	No	Single Family Structure	
	Field inspection only with no records	Yes	Visual inspection at the meter pit	10/3/2019	Never Lead	No	Single Family Structure	
	Field inspection only with no records	Yes	Visual inspection at the meter pit	10/3/2019	Never Lead	No	Single Family Structure	
	Field inspection only with no records	Yes	Visual inspection at the meter pit	10/3/2019	Never Lead	No	Single Family Structure	
	Field inspection only with no records	Yes	Visual inspection at the meter pit	10/3/2019	Never Lead	No	single Family Structure	
	Field inspection only with no records	Yes	Visual inspection at the meter pit	10/3/2019	Never Lead	No	Single Family Structure	
	Field inspection only with no records	Yes	Visual inspection at the meter pit	10/3/2019	Never Lead	No	Single Family Structure	
	Field inspection only with no records	Yes	Visual inspection at the meter pit	10/3/2019	Never Lead	No	Single Family Structure	
	Field inspection only with no records	Yes	Visual inspection at the meter pit	10/3/2019	Never Lead	No	single Family Structure	
	Field inspection only with no records	Yes	Visual inspection at the meter pit	10/3/2019	Never Lead	No	Single Family Structure	
	Field inspection only with no records	Yes	Visual inspection at the meter pit	10/3/2019	Never Lead	No	Single Family Structure	
	Field inspection only with no records	Yes	Visual inspection at the meter pit	10/4/2019	Never Lead	No	Single Family Structure	
	Field inspection only with no records	Yes	Visual inspection at the meter pit	10/4/2019	Never Lead	No	Single Family Structure	
	Field inspection only with no records	Yes	Visual inspection at the meter pit	10/4/2019	Never Lead	No	single Family Structure	
	Field inspection only with no records	Yes	Visual inspection at the meter pit	10/4/2019	Never Lead	No	Single Family Structure	
	Field inspection only with no records	Yes	Visual inspection at the meter pit	10/4/2019	Never Lead	No	Single Family Structure	
	Field inspection only with no records	Yes	Visual inspection at the meter pit	10/4/2019	Never Lead	No	Single Family Structure	
	Field inspection only with no records	Yes	Visual inspection at the meter pit	10/4/2019	Never Lead	No	Single Family Structure	

Service Line Length	Basis of Material Classification	Was the Service Line Material Field Verified?	If Yes in Column AE...		Connector Material Type	Is there Lead Solder in the Service Line?	Building Type Connected to Service Line	If Column AJ includes a school...
			Describe the Field Verification Method	Enter the Date of Field Verification				Lowest Grade Served
	Field inspection only with no records	Yes	Visual inspection at the meter pit	10/4/2019	Never Lead	No	Single Family Structure	
	Field inspection only with no records	Yes	Visual inspection at the meter pit	10/8/2019	Never Lead	No	Single Family Structure	
	Field inspection only with no records	Yes	Visual inspection at the meter pit	10/8/2019	Never Lead	No	Single Family Structure	
	Field inspection only with no records	Yes	Visual inspection at the meter pit	10/8/2019	Never Lead	No	Single Family Structure	
	Field inspection only with no records	Yes	Visual inspection at the meter pit	10/8/2019	Never Lead	No	Single Family Structure	
	Field inspection only with no records	Yes	Visual inspection at the meter pit	10/8/2019	Never Lead	No	Single Family Structure	
	Field inspection only with no records	Yes	Visual inspection at the meter pit	10/8/2019	Never Lead	No	Single Family Structure	
	Field inspection only with no records	Yes	Visual inspection at the meter pit	10/8/2019	Never Lead	No	Non-Residential Building	
	Field inspection only with no records	Yes	Visual inspection at the meter pit	10/8/2019	Never Lead	No	Single Family Structure	
	Field inspection only with no records	Yes	Visual inspection at the meter pit	10/8/2019	Never Lead	No	Single Family Structure	
	Field inspection only with no records	Yes	Visual inspection at the meter pit	10/8/2019	Never Lead	No	Single Family Structure	
	Field inspection only with no records	Yes	Visual inspection at the meter pit	10/8/2019	Never Lead	No	Single Family Structure	
	Field inspection only with no records	Yes	Visual inspection at the meter pit	10/8/2019	Never Lead	No	Single Family Structure	
	Field inspection only with no records	Yes	Visual inspection at the meter pit	10/10/2019	Never Lead	No	single Family Structure	
	Field inspection only with no records	Yes	Visual inspection at the meter pit	10/10/2019	Never Lead	No	Single Family Structure	
	Field inspection only with no records	Yes	Visual inspection at the meter pit	10/10/2019	Never Lead	No	Single Family Structure	
	Field inspection only with no records	Yes	Visual inspection at the meter pit	10/10/2019	Never Lead	No	single Family Structure	
	Field inspection only with no records	Yes	Visual inspection at the meter pit	10/10/2019	Never Lead	No	single Family Structure	
	Field inspection only with no records	Yes	Visual inspection at the meter pit	10/10/2019	Never Lead	No	single Family Structure	
	Field inspection only with no records	Yes	Visual inspection at the meter pit	10/10/2019	Never Lead	No	Single Family Structure	
	Field inspection only with no records	Yes	Visual inspection at the meter pit	10/10/2019	Never Lead	No	Single Family Structure	
	Field inspection only with no records	Yes	Visual inspection at the meter pit	10/10/2019	Never Lead	No	single Family Structure	
	Field inspection only with no records	Yes	Visual inspection at the meter pit	10/10/2019	Never Lead	No	Single Family Structure	
	Field inspection only with no records	Yes	Visual inspection at the meter pit	10/10/2019	Never Lead	No	Single Family Structure	
	Field inspection only with no records	Yes	Visual inspection at the meter pit	10/11/2019	Never Lead	No	single Family Structure	
	Field inspection only with no records	Yes	Visual inspection at the meter pit	10/11/2019	Never Lead	No	Single Family Structure	
	Field inspection only with no records	Yes	Visual inspection at the meter pit	10/11/2019	Never Lead	No	Single Family Structure	
	Field inspection only with no records	Yes	Visual inspection at the meter pit	10/11/2019	Never Lead	No	Single Family Structure	
	Field inspection only with no records	Yes	Visual inspection at the meter pit	10/11/2019	Never Lead	No	single Family Structure	
	Field inspection only with no records	Yes	Visual inspection at the meter pit	10/11/2019	Never Lead	No	single Family Structure	

[illegible]

[illegible]

Service Line Length	Basis of Material Classification	Was the Service Line Material Field Verified?	If Yes in Column AE...		Connector Material Type	Is there Lead Solder in the Service Line?	Building Type Connected to Service Line	If Column AJ includes a school...
			Describe the Field Verification Method	Enter the Date of Field Verification				Lowest Grade Served
	Field inspection only with no records	Yes	Visual inspection at the meter pit	9/4/2020	Never Lead	No	single Family Structure	
	Field inspection only with no records	Yes	Visual inspection at the meter pit	9/4/2020	Never Lead	No	Single Family Structure	
	Field inspection only with no records	Yes	Visual inspection at the meter pit	9/4/2020	Never Lead	No	Single Family Structure	

[illegible]

[illegible]

[illegible]

[illegible]

[illegible]

[illegible]

[illegible]

[illegible]

[illegible]

[illegible]

[illegible]

[illegible]

[illegible]

Building Construction Date	Building Plumbing Materials	Plumbing installation/replacement date	Point-of-Entry or Point-of-Use Treatment Present?	LCR Sampling Point ID	Date of System-owned LSLR	Date of Customer-owned LSLR	