

Selected Soil Interpretations

Coweta, Heard, and Troup Counties, Georgia

[The information in this table indicates the dominant soil condition but does not eliminate the need for onsite investigation. The table shows only the top five limitations for any given soil. The soil may have additional limitations. This report shows only the major soils in each map unit]

*This soil interpretation was designed as a "limitation" as opposed to a "potential" or "suitability". The numbers in the value column range from 0.01 to 1.00. The larger the value, the greater the potential limitation.

Map symbol and soil name	Pct. of map unit	ENG - Dwellings W/O Basements*		ENG - Lawn, Landscape, Golf Fairway*		ENG - Local Roads and Streets (GA)*	
		Rating class and limiting features	Value	Rating class and limiting features	Value	Rating class and limiting features	Value
CfC2:							
Cecil	100	Not limited		Very limited		Somewhat limited	
				Low exchange capacity	1.00	Low strength	0.50
				Too clayey	0.50		
				Dusty	0.08		
CfD2:							
Cecil, moderately eroded	100	Somewhat limited		Somewhat limited		Somewhat limited	
		Slope	0.84	Slope	0.84	Slope	0.84
				Low exchange capacity	0.75	Low strength	0.50
				Too clayey	0.50		
				Dusty	0.09		
PgE2:							
Pacolet, moderately eroded	98	Very limited		Very limited		Very limited	
		Slope	1.00	Slope	1.00	Slope	1.00
				Low exchange capacity	0.75	Low strength	0.50
				Too clayey	0.50		
				Dusty	0.10		
RK:							
Riverview	55	Very limited		Somewhat limited		Very limited	
		Flooding	1.00	Low exchange capacity	0.75	Flooding	1.00
				Flooding	0.60	Low strength	0.76
				Dusty	0.08		
Chewacla							
	40	Very limited		Very limited		Very limited	
		Flooding	1.00	Flooding	1.00	Flooding	1.00
		Depth to saturated zone	1.00	Depth to saturated zone	1.00	Depth to saturated zone	1.00
				Low exchange capacity	0.50		
				Dusty	0.08		

Dwellings and Small Commercial Buildings

Coweta, Heard, and Troup Counties, Georgia

[The information in this table indicates the dominant soil condition but does not eliminate the need for onsite investigation. The numbers in the value columns range from 0.01 to 1.00. The larger the value, the greater the potential limitation. The columns that identify the rating class and limiting features show no more than five limitations for any given soil. The soil may have additional limitations. This report shows only the major soils in each map unit]

Map symbol and soil name	Pct. of map unit	Dwellings without basements		Dwellings with basements		Small commercial buildings	
		Rating class and limiting features	Value	Rating class and limiting features	Value	Rating class and limiting features	Value
CfC2: Cecil	100	Not limited		Not limited		Very limited Slope	1.00
CfD2: Cecil, moderately eroded	100	Somewhat limited Slope	0.84	Somewhat limited Slope	0.84	Very limited Slope	1.00
PgE2: Pacolet, moderately eroded	98	Very limited Slope	1.00	Very limited Slope	1.00	Very limited Slope	1.00
RK: Riverview	55	Very limited Flooding	1.00	Very limited Flooding Depth to saturated zone	1.00 0.61	Very limited Flooding	1.00
Chewacla	40	Very limited Flooding Depth to saturated zone	1.00 1.00	Very limited Flooding Depth to saturated zone	1.00 1.00	Very limited Flooding Depth to saturated zone	1.00 1.00

Roads and Streets, Shallow Excavations, and Lawns and Landscaping (GA)

Coweta, Heard, and Troup Counties, Georgia

[The information in this table indicates the dominant soil condition but does not eliminate the need for onsite investigation. The numbers in the value columns range from 0.01 to 1.00. The larger the value, the greater the potential limitation. The columns that identify the rating class and limiting features show no more than five limitations for any given soil. The soil may have additional limitations. This report shows only the major soils in each map unit]

Map symbol and soil name	Pct. of map unit	Local roads and streets		Shallow excavations		Lawns and landscaping	
		Rating class and limiting features	Value	Rating class and limiting features	Value	Rating class and limiting features	Value
CfC2:							
Cecil	100	Somewhat limited Low strength	0.50	Somewhat limited Too clayey Dusty Unstable excavation walls	0.72 0.08 0.01	Very limited Low exchange capacity Too clayey Dusty	1.00 0.50 0.08
CfD2:							
Cecil, moderately eroded	100	Somewhat limited Slope Low strength	0.84 0.50	Somewhat limited Slope Too clayey Dusty Unstable excavation walls	0.84 0.72 0.09 0.01	Somewhat limited Slope Low exchange capacity Too clayey Dusty	0.84 0.75 0.50 0.09
PgE2:							
Pacolet, moderately eroded	98	Very limited Slope Low strength	1.00 0.50	Very limited Slope Too clayey Dusty Unstable excavation walls	1.00 0.50 0.10 0.01	Very limited Slope Low exchange capacity Too clayey Dusty	1.00 0.75 0.50 0.10
RK:							
Riverview	55	Very limited Flooding Low strength	1.00 0.76	Somewhat limited Depth to saturated zone Flooding Dusty Unstable excavation walls	0.61 0.60 0.08 0.01	Somewhat limited Low exchange capacity Flooding Dusty	0.75 0.60 0.08
Chewacla	40	Very limited Flooding Depth to saturated zone	1.00 1.00	Very limited Depth to saturated zone Flooding Dusty Unstable excavation walls	1.00 0.80 0.08 0.01	Very limited Flooding Depth to saturated zone Low exchange capacity Dusty	1.00 1.00 0.50 0.08