

2024 Stormwater Repair Log List

Job Number	Location	Type of Repair	Work Performed	Date
1	Utah Avenue - Riverview	Stormwater Manhole Repair	Dug up storm water manhole, replaced lid and casting	1/23/2024
2	Greensprings Avenue - Homeville Fire Station	Storm Basin Repair	Replaced & repaired collapsing storm basins in parking lot	2/21/2024
3	Constitution Avenue	Storm Basin Repair	Removed old wobbly grate and replaced it with a solid basin lid	3/6/2024
4	Corner or Neel & Ohio Avenue	Storm Basin Repair	Removed & replaced broken storm basin lid that was falling in with new basin lid	3/6/2024
5	Old Elizabeth Road	Storm Basin Repair	Removed & replaced frame and fallen in grate	3/7/2024
6	Bellwood Playground - Coal Road Ext.	Dredge Storm Drainage/Re-stone	Dug bigger opening for outfall, dug outfall side down 2 ft and re-stoned to the nearest basin	3/8/2024
7	Sylvania Street	Stormwater Manhole Repair	Installed and mortared new bricks, set casting & lid	3/13/2024
8	Old Elizabeth Road	Storm Basin Repair	Repaired/replaced front and side walls of blown out basin	3/15/2024
9	Hazel Street	Storm Basin Repair	Replaced lid/top on basin that was falling in	4/3/2024
10	Outlook Drive/Glencairn Street	Replace Storm Line	Replaced storm line pipe under road	4/17/2024
11	Duquesne Avenue/Jane Street	Storm Basin Repair	Repaired basin grate and frame that was dented inwards	7/18/2024
12	Juniper Drive	Storm Basin Repair/Inspection	Removed plant/root growth in basin & treated with root-x	8/8/2024
13	Lewis Run Road	Storm Basin Repair	Repaired & replaced basin bricks, walls, and pipes	9/25/2024
14	Satinwood Drive/Acacia Court	Installing New Storm Basin	Installed new storm basin & storm line to prevent ice from forming in the Winter	10/24/2024
15	Parkside Drive/Ashwood Court	Storm Basin Repair	Basins were falling apart - removed collapsing pieces and replaced with new walls - made all other necessary repairs	11/15/2024
16	Glencairn Street/ Everlawn Street	Storm Basin Repair	Replaced rotting metal grate	12/11/2024
17	Jane Street/ 7th Avenue	Storm Basin Repair	Replaced steel plate with new concrete lid	12/17/2024

18	Ohio Avenue	Storm Basin Repiar	Loose bricks were taken out and replaced, new lid was set in place, coldpatch added in front to make sure water went in drain correctly	12/17/2024
----	-------------	--------------------	---	------------

Proposed BMPs per MS4 Permit Requirements

**** all proposed BMPs are pending the approval of grant funding at this time ****

Streets Run

	Shara Drive/Mifflin Hill	Dry Extended Detention Basin	To Be Determined	To Be Determined
	Miller Road	Bioretention (Rain Garden)	To Be Determined	To Be Determined
	Nordeen Drive - Park	Detention Facility OR Bioretention (Rain Garden)	To Be Determined	To Be Determined
	Fidelity Drive "Soccer Field"	Dry Extended Detention Basin	To Be Determined	To Be Determined

Homestead Run

	Duquesne Avenue	Bioretention (Rain Garden) with Infiltration	To Be Determined	To Be Determined
	Spring Street	Bioretention (Rain Garden)	To Be Determined	To Be Determined
	5th Avenue - Playground	Infiltration Basin	To Be Determined	To Be Determined

UNT to Mon River

	CCAC South Campus	Bioretention with Bioswale OR Bioretention Only	To Be Determined	To Be Determined
--	-------------------	---	------------------	------------------

UNT to Mon River – New England Road (Total Phosphorus Reduction Requirement Only)-

	Pine Creek Run Road-	Bioswale-	To Be Determined-	To Be Determined-
--	----------------------	-----------	-------------------	-------------------

Purchased Stormwater Equipment & Supplies

Marking Paint, Marking Flags, and Dye Tablets
2A Slag, 2B Slag, Concrete Mix, and Rebar
Grass Seed, and Straw
Storm Basin Inserts, Risers, Grates, and Frames
Additional Safety Equipemt: Telescoping Ladders, Gas Detectors, Traffic Cones, Cone Bars, and Hard Hats
Other Misc. Costs: MS4 Advertising, and Employee Trainings