



Platinum Inspection Report

Vehicle Details

Registration	SO66BZC	Fuel Type	Petrol
Make	AUDI	Vehicle Type	Car
Model	A3 SPORT TFSI		
Colour	Black	Inspected on ramp	Yes
VIN	WAUZZZ8V5HA093540	Mileage at inspection	117232

Body Exterior

Bonnet Catch	Pass	Bonnet Hinges	Pass
Door Locks	Advisory	Fuel Filler Cap	Pass
Panoramic Roof	N/A	Sunroof/ Convertible Operation	N/A
Registration Plates	Pass	Windscreen	Pass

Interior

Air Vents	Pass	Mirrors	Pass
Roof Blind And Operation	Pass	Driver's Seat Adjustment	Pass
Seatbelts	Pass		

Engine Bay

Abnormal Noises	Pass	Antifreeze Strength	Pass
Aux Drive Belts	Pass	Brake Fluid Level	Pass
Clutch Fluid Level	Pass	Coolant Cap	Pass
Coolant Leaks	Pass	Coolant Level And Condition	Pass
Engine Mounts	Pass	Engine Oil Level	Pass
Excessive Fumes Smoke	Pass	Fuel Pipes	Pass
Hoses/Pipes	Pass	Idle Speed	Pass
Oil Fluid Leaks	Pass	Power Steering Fluid Level	Pass
Turbo/Supercharger	Pass		
Abnormal Noises/Leaks			

Electrical Systems

Air Condition Operation	Advisory	Start Stop	Pass
Aux Lights	Pass	12v Battery Visual Condition	Pass
Brake Lights	Pass	Controls Switches	Pass
Fog Lights	Pass	Headlamp Washers	Pass
Headlights	Pass	Heated Seats	Pass
Horn	Pass	Indicator/Hazard Lights	Pass
Instruments	Pass	Interior Lights	Pass
Media Volume	Pass	Number Plate Lights	Pass
Panel Lights	Pass	Parking Sensors	Pass

Reverse Lights	Pass	Side/Running Lights	Pass
Start Button/Ignition Lock	Pass	TPMS Fitted Y/N	Yes
Tyre Pressures	Pass	Window Operation	Pass
Wipers And Washer	Pass		

Front Suspension/Underbody

Anti-Roll Bar And Links	Pass	Engine Underside Leaks	Pass
Power Steering Operation	Pass	Shock Absorbers/ Condition/ Leaks	Pass
Springs/Suspension Units	Pass	Steering And Ball Joint	Pass
Steering Pipes And Hoses	Pass	Steering Rack Gaitors	Pass
Steering Rack/Box	Pass	Subframe Condition/Mountings	Pass
Suspension Arm/Bushes	Pass	Underbody Condition	Pass
Wheel Hubs/Bearings	Pass		

Rear Suspension/Underbody

Anti-Roll Bar And Links	Pass	Engine Underside Leaks	Pass
Shock Absorbers/ Condition/Leaks	Pass	Springs Suspension Units	Pass
Subframe Condition/Mountings	Pass	Suspension Arm/Bushes	Pass
Underbody Condition	Pass	Wheel Hubs/Bearings	Pass

Transmission/Drive

Casings Condition	Pass	Clutch Hydraulic System	Pass
Clutch Operation	Pass	Driveshaft Assembly	Pass
Front CV Boots	Pass	Gear Link Operation	Pass
Mountings	Pass	Oil Fluid Leaks	Pass
Propshaft	Pass	Propshaft Bearings/Supports	Pass
Rear CV Boots	Pass	Universal Joints	N/A
Abnormal Noises	Pass		

Exhaust

Catalytic Converter Condition	Pass	DPF Visual Check	
Heat Shields Mountings	Pass	Joints Couplings	N/A
Manifold Condition	Pass	Pipes Condition	Pass
Silencer	Pass		

Fuel System

Breather Pipes	Pass	Evidence Of Leaks	Pass
Fuel Lines	Pass	Tank Fixings	Pass

Tank

Tank	Pass
------	------

Brakes

Brake Pedal Operation	Pass	Brake Pipes	Pass
Discs Pads	Pass	Flexible Hoses	Pass
Fluid Leaks	Pass	Handbrake Operation	Pass
Pedal And Pad Linkage	Pass	Servo Power Assistance	Pass

Wheels & Tyres

Position	Brand	Width	Profile	Size	Damage
Front Left	Goodyear	205	55	17	Pass
Front Right	Bridgestone	205	55	17	Pass
Rear Left	Bridgestone	205	55	17	Pass
Rear Right	Bridgestone	205	55	17	Pass
Spare					N/A

Road Test

Auto Changes	N/A	Auto Gearbox Park Function	N/A
Auto Sports Function	N/A	Brakes Vibration Noise	Pass
Cruise Control	Pass	Engine Abnormal Noise	Pass
Engine Performance	Pass	Exhaust Smoke	Pass
General Steering/Handling	Pass	Hot Restarting	Pass
Instrument Controls	Pass	Overheating Evidence	Pass
Paddle Controls	N/A	Parking Sensors	Pass
Road Holding/Stability	Pass	Steering Effort	Pass
Suspension Noise	Pass		

Test Distance	8	Speed Achieved Up To	50mph
----------------------	---	-----------------------------	-------

Locking nut on alloys Yes



Warning Lights

Warning Lights Pass

Mechanic's Notes