

877-766-3979 | info@dragonflypondworks.com

Maintenance Report: LAKES OF OLD PEACHTREE

Property: LAKES OF OLD PEACHTREE

Service Date: 03/25/2025 Crew Member(s): Zack Client Name: Laura Troops

Client Email Address: president@lakesofoldpeachtree.com

Client Email Address 2:

Number of Ponds &

3 Lakes

Pond Type:

Mowing Schedule: Monthly Lake Maintenance/Quarterly Gate Valve Inspection

Standard Maintenance Program Includes:

- Treatment of nuisance vegetation in basin as needed and as permitted by municipality
- Control of unwanted vegetation on inlets, outlets, and spillway, structures
- Removal of trash from basin
- Cleaning and inspecting drain, weirs, and riser
- Hand re-arranging of riprap at inlet and outlet where applicable (does not include severe blowouts)
- Monitoring for potentially harmful wildlife activity
- Monitoring conditions favorable to mosquito habitats and recommend solutions
- Visual inspection and digital documentation of condition of pond and pond components
- Professional recommendations related to system operation, appearance, safety, and/or compliance

Pond Locations





LAKES OF OLD PEACHTREE- Lake 1

Access Address: 1895 Terrace Lake Drive Lawrenceville, GA 30043

Trash Pick Up: SC= Service Completed Invasive Treated: Service complete

Water Level Check: Above Orifice Height, Water Flowing Fountain/Aerator Condition: N/A= Not Applicable







Overview

Front of dam



Back of dam



Gate valve

Inlet 1

Inlet 2

Recommendation & Summary Notes: LAKES OF OLD PEACHTREE

Lake 1

Notes: Inspected and serviced site and its components. Collected and removed over 5 gallons worth of trash from site. Observed some erosion and missing riprap around inlets and recommended adding matting and riprap around the devices. Observed pipe separation/damage in inlet 3 and recommended corrective repairs. Outlet leads to neighboring pond 2.



LAKES OF OLD PEACHTREE- Lake 1 additional photos 1

Access Address: 1895 Terrace Lake Drive Lawrenceville, GA 30043

Trash Pick Up: Invasive Treated:

Water Level Check: Above Orifice Height, Water Flowing

Fountain/Aerator Condition: N/A= Not Applicable



Inlet 3

Recommendation & Summary Notes: LAKES OF OLD PEACHTREE

Lake 1 additional photos 1 Notes:



LAKES OF OLD PEACHTREE- Lake 2

Access Address: 1895 Terrace Lake Drive Lawrenceville, GA 30043

Trash Pick Up: SC= Service Completed Invasive Treated: Service complete

Water Level Check: Above Orifice Height, Water Flowing Fountain/Aerator Condition: N/A= Not Applicable







Overview



Front of dam



Back of dam



Gate valve

Riser with erosion

Riser interior

Recommendation & Summary Notes: LAKES OF OLD PEACHTREE

Lake 2

Notes: Inspected and serviced site and its components. Collected and removed a few gallons worth of trash from site. Cleared sticks and debris from devices and removed sediment from inlet 1. Observed sediment at inlet 1 and riser and recommended having them dredged. Observed erosion near riser and recommended corrective work/repairs. Outlet leads to lake 3.



LAKES OF OLD PEACHTREE- Lake 2 additional photos 1

Access Address: 1895 Terrace Lake Drive Lawrenceville, GA 30043

Trash Pick Up: Invasive Treated:

Water Level Check: Above Orifice Height, Water Flowing

Fountain/Aerator Condition: N/A= Not Applicable







Erosion near riser

Inlet 1

Inlet 2



Inlet 3 (lake 1 outlet)

Recommendation & Summary Notes: LAKES OF OLD PEACHTREE

Lake 2 additional photos 1 Notes:



LAKES OF OLD PEACHTREE- Lake 3

Access Address: 1895 Terrace Lake Drive Lawrenceville, GA 30043

Trash Pick Up: SC= Service Completed Invasive Treated: Service complete

Water Level Check: Above Orifice Height, Water Flowing







Overview



Front of dam



Back of dam



Gate valve

Inlet '

Inlet 2

Recommendation & Summary Notes: LAKES OF OLD PEACHTREE

Lake 3

Notes: Inspected and serviced site and its components. Collected and removed over 10 gallons of trash from site. Observed sediment at inlet 2 and recommended having it dredged. Observed pipe damage at inlet 2 and recommended corrective repairs.



LAKES OF OLD PEACHTREE- Lake 3 additional photos 1

Access Address: 1895 Terrace Lake Drive Lawrenceville, GA 30043

Trash Pick Up: Invasive Treated:

Water Level Check: Above Orifice Height, Water Flowing

Fountain/Aerator Condition: N/A= Not Applicable







Inlet 3 (lake 2 outlet)







Inlet 6 Outlet Total trash collected

Recommendation & Summary Notes: LAKES OF OLD PEACHTREE

Lake 3 additional photos 1 Notes: