

Claycomo Fire Department

333 East U.S. 69 Hwy

Claycomo Missouri, 64119

Business Phone: (816) 452-4612 Fax Number: (816) 452-7243

General Provisions

- 1. Matters not provided for Matters not provided for. Requirements that are essential for the public safety of an existing or proposed activity, building or structure, or for the safety of the occupants thereof, which are not specifically provided for by this code shall be determined by the fire code official.
- 2. Maintenance of safeguards. Whenever or wherever any device, equipment, system, condition, arrangement, level of protection, or any other feature is required for compliance with the provisions of this code, or otherwise installed, such device, equipment, system, condition, arrangement, level of protection, or other feature shall thereafter be continuously maintained in accordance with this code and applicable referenced standards (example: exit lights, alarm systems, etc.)
- 3. Permit Operational Permits must be acquired and readily available.
- 4. Address New and existing buildings shall have address that are 4" in high with ½" stroke width. It must be visible from the street or road fronting the property. Address identification shall contrast with their background.
 - a. Multitenant buildings in which tenant spaces have secondary doors from the exterior, such door shall have approved numbers or addresses on or adjacent to each door.
- 5. Key Boxes Where access to or within a structure or an area is restricted because of secured openings or where immediate access is necessary for life-saving or fire-fighting purposes, all commercial and retail structures in the Village of Clayomo shall install an approved Knox-Box® systems key box, the fire code official is authorized to require a key box to be installed in an approved location.
- 6. Signs
 - a. Max Occ Sign Every room or space that is an assembly occupancy shall have the occupant load of the room or space posted.
 - b. Warning Signs must be posted where applicable.
 - c. Stop Engine Warning Sign shall be conspicuously posted in sight of each dispenser.
 - d. No Smoking Signs Required in spaces where flammable or combustible materials are stored or handled.

Common Issues found with inspections (not all-inclusive list)

Assemblies - Group A-3 (Churches, Community Halls, Dance/Exhibition Halls):

- 1. Blocked exits
- 2. No exit sign; exit lights out
- Doors locked during hours of occupancy
- 4. Overcrowded, no occupant load sign posted
- 5. Tables and/or chairs in exit paths
- Fire extinguisher not serviced or nonexistent
- 7. Candles on tables in unsafe holders (permit required)
- 8. Extension cords and other electrical problems
- 9. Draperies shall not be placed over exit doors
- 10. Decorations, draperies shall be fire retardant treated



Claycomo Fire Department

333 East U.S. 69 Hwy

Claycomo Missouri, 64119

Business Phone: (816) 452-4612 Fax Number: (816) 452-7243

- 11. Smoking areas
- 12. Combustible materials shall not be stored in boiler rooms, mechanical
- 13. rooms, electrical equipment rooms or fire command centers
- 14. Lack of panic hardware and/or door hard to open
- 15. No emergency lighting or not tested
- 16. Fire alarm testing, or record of testing
- 17. Commercial kitchen extinguishing systems not tested
- 18. Grease accumulation on filters and/or in ducts
- 19. Locks and latches on exit doors
- 20. Painted sprinkler heads
- 21. Lack of visible address

Businesses – Group B & M (Clinics, Banks, Food Prep without restaurant < 2,500sq/ft, Professional Services, Retail, Drug Stores):

- 1. Blocked and/or obstructed egress (exit) doors
- 2. Misuse of extension cords
- 3. Extinguishers not serviced, inspected or missing, blocked, nor readily visible.
- 4. Lack of visible address
- 5. Storage of combustibles
- 6. Storage below sprinkler heads minimum of 18" (24" below ceiling without sprinklers)
- 7. Combustibles within 36" of heating equipment
- 8. Improper storage of flammable liquids
- 9. Lack of proper maintenance and/or testing of fire systems
- 10. Blocked or painted sprinkler heads
- 11. Not maintaining means of Egress or exit access clearance

Restaurants (A-2):

- 1. Grease accumulation on filters and/or in ducts
- 2. Hood system not serviced, nonexistent
- 3. Decorations, curtains, draperies shall be fire retardant treated
- 4. Fire extinguisher not serviced or nonexistent
- 5. Combustible materials shall not be stored in boiler rooms, mechanical rooms, electrical equipment rooms or fire command centers
- 6. Extension cords and other electrical problems
- 7. Lack of exit signs or exit sign lighting not working
- 8. Draperies shall not be placed over exit doors
- 9. Tables and/or chairs in exit paths
- 10. Illegal locks on egress (exit) doors
- 11. Permit required for candles
- 12. Emergency lighting missing or not tested
- 13. Storage in exit path or tables blocking exit door
- 14. No Occupant Load signs posted



Claycomo Fire Department

333 East U.S. 69 Hwy

Claycomo Missouri, 64119

Business Phone: (816) 452-4612 Fax Number: (816) 452-7243

- 15. Seating exceeds the posted Occupant Load signs
- 16. Painted sprinkler heads
- 17. Flaming food or beverage preparation

Multi-Unit Residences

- 1. Blocked exits
- 2. Fire extinguishers not serviced or missing
- 3. Storage of combustibles in exits, exit enclosure or stairways
- 4. Cluttered attic, garage, under stairs, heating room
- 5. Lack of (and/or not visible) exit signs
- 6. Lack of visible address
- 7. Combustibles stored next to water heater or furnace
- 8. Lack of emergency vehicle access to building
- 9. Fire protection equipment not working or serviced
- 10. R-2, R-3, and I-1 occupancies, a smoke alarm required in each sleeping unit
- 11. Fire safety evacuation plan (R-4) proof of staff training
- 12. Stairway doors blocked open
- 13. Smoke detectors in motels for operation
- 14. Water valves to sprinklers. Must be open
- 15. Flammable liquids storage
- 16. Painted sprinkler heads