Customer Service Report

Schedule Now For Service October 2025 Call 772-287-0651

1127 Southwest Catalina Street

Gary Lamoureux

928-899-3953

Depth Below:

Palm City, FL 34990

Work Order #

8447044389

System Location

Customer Since:

2020

System Owner

Primary Home

1127 Southwest Catalina Street

Palm City, FL 34990

Left at: 5:59 PM

Gary Lamoureux: 928-899-3953

Service Date: Oct 10/21/2024 12:00 AM Frequency:

Service Type: Septic Tank

Previous Service: 12/03/2022

1000 Approx. Gals.: **System Treatment: Custom Clean:** 0

Filter Cust Home: NO

Township: Inspection/T5:

County: **Build Up:** Martin

			l.
Description	Qty	Unit Price	Ext. Price
OS-R-Pumping 1000	1.00	\$428.9375	\$428.94
Coupon-NEWFRIEND30	1.00	-\$30.0000	-\$30.00
OS-R-Clean Filter with Pump	1.00	\$0.0000	\$0.00
		Subtotal:	\$398.94
		Tax:	\$0.00
		Total:	\$398.94

Tank Size		Но	useh	old	Осс	upa	ncy	
	1	2	3	4	5	6	7	8
1000	22	20	18	16	14	12	12	12
1250	22	20	18	18	16	14	12	12
1500	24	22	20	20	18	16	14	14
2000	26	24	22	22	20	18	16	16

Score From Table	0
Garbage Disposal (-6)?	0
System Age > 10 Years (-5)?	0
Seasonal Occupancy (+8)?	0
System Treatment Used (+5)?	0
Total Adjustments?	0
Net Score	0

0	0
Score	Service Every
< 5	6 Months
6 - 15	12 Months
16 - 23	18 Months
24+	24 Months

	Keep your system healthy by following these 3 steps:
System Normal	Regular Service
	Lie MDE Contin Conton Transferent

• Use WRE Septic System Treatment

Use a Filter

Excessive Solids Use WRE Septic System Treatment

☐ Heavy Sludge **Use WRE Septic System Treatment**

Tee Missing/Broken Repair/Replace Tee

High Liquid Level Possible system failure. Call for evaluation or customer cleaning.

Arrived at: 4:59 PM

Distribution Box Issue See notes below for details.

Schedule Now for Service October 2025 Call 772-287-0651

Payment Detail:

Amex xxxxxxxxxx2009 08/2029 Due on Receipt

Customer Signature

Tech Notes:

On arrival located and exposed riser lid in front yard, removed and cleaned filter and system was at proper working order. Pumped 1000 gallons from tank and put back filter. Customer was not home and could not have them flush. System is working as intended.



THIS IS NOT AN INVOICE.

Technician: Sean Splain







