



# Rosehill Reservoir Rehabilitation

Construction Progress: Photo Update #1

December 28, 2020

# South Stairs At Valve House

**Contract 1**





# Jackes Stairs

## Contract 1



# Lower Pathway - East Side

## Contract 1





## “S-Curve” Pathway located north-east side of Valve House



**Contract 1**



# Sod Installation - Top of the Reservoir

## Contract 1





# Sod Installation - West Slope

Contract 1





# Lower Perimeter Path - West Side (looking north)

Contract 1



12/21/2020 08:15



Upper Perimeter Pathway from Valve House looking north to Avoca Avenue

Contract 1





# New Washroom

## Contract 1





# New Public Washroom - looking South

Contract 1





New Public Washroom -  
Entrance to Family Washroom

Contract 1

12 / 11 / 2020 10 : 33



# Trellis Foundation on Upper Perimeter Pathway near Washroom      **Contract 1**





# Footings for Rosehill Garden

Contract 1





# Rosehill Garden - Completed Fence Footings

Contract 1



11/26/2020 11:47



# Foundation for the Water Feature

## Contract 1





# Water Feature - Foundation for the Stairs at Rosehill Avenue (leading up to Water Feature and Centennial Monument)

Contract 1





# Water Feature - Removing Forms

Contract 1



12/21/2020 14:11



Rosehill Node - Planter Box  
Contract 1



12/21/2020 08:11



Rosehill Node - Planter Box  
Contract 1



12/21/2020 08:11