

Rosehill Reservoir Rehabilitation and David A Balfour Park Installation

Community Update #35 – Photo Update
March 8, 2021

PUBLIC
AND PRIVATELY
NOT ALLOWED
ON THIS SLOPE

PLEASE
KEEP TO THE
WALKS

Sodding on plateau



Sodding (on the west slope, facing south)



Water Feature Foundation



Garden Fence Footings

Valve House Stairs



Jackes Stairs



Planting Bed at Rosehill Node



Washroom Windows



Washroom



Washroom Tiling



Washroom Ceiling Soffit

Trellis on the Upper
Pathway (East side)



Trellis Wood Slats



Garden Trellises



Upper Path (east side) looking north



Service Road looking south to Valve House



Little Park Driveway – Compacting



Lower Path installation