

# SUF

## SOUND URBAN FORESTRY, LLC

---

Appraisals ~ Site Planning ~ Urban Landscape Design and Management  
Environmental Education ~ Risk Assessments

9/11/19

**Mirasett HOA**  
C/o: Thomas Donlon

Cc: Suresh Bhagavan, City of Tumwater Community Development Department

RE: Mirasett Street Tree Year 2 Removals

Mr. Donlon:

Upon the request of the Mirasett HOA, I have assessed the street trees proposed for removal as part of the community's management plan developed in 2017. I met with you and inventoried the trees on March 26, 2019.

### **Identified Street Tree Removals**

The locations of the following trees are marked in red on the attached site map. Photos of the associated infrastructure damage are included as well.

<b>Associated Address</b>	<b>Species</b>	<b>Comments</b>
6939Southwick	White Ash	Roots are lifting and cracking the curb and lifting the sidewalk panels.
6941 Southwick	White Ash	Roots are lifting and cracking the curb and lifting the sidewalk panels.
7003 Southwick	White Ash	Roots are lifting and cracking the curb and lifting the sidewalk panels.
7017 Southwick	White Ash	Roots are lifting and cracking the curb and lifting the sidewalk panels.
7012 Southwick	White Ash	Roots are lifting and cracking the curb and lifting the sidewalk panels.
7022 Southwick	White Ash	Roots are lifting and cracking the curb and lifting the sidewalk panels.
7031 Southwick	White Ash	Roots are lifting and cracking the curb and lifting the sidewalk panels.
7136 Southwick	White Ash	Roots are lifting and cracking the curb and lifting the sidewalk panels.
7014 Mirasett	Red Maple	Roots are lifting and cracking the curb and lifting the sidewalk panels.
7018 Mirasett	Red Maple	Roots are lifting and cracking the curb and lifting the sidewalk panels.
7020 Mirasett	Red Maple	Roots are lifting and cracking the curb and lifting the sidewalk panels.
7036 Mirasett	Red Maple	Roots are lifting and cracking the curb and lifting the sidewalk panels.

Associated Address	Species	Comments
7043 Mirasett	Red Maple	Roots are lifting and cracking the curb and lifting the sidewalk panels.
7044 Mirasett	Red Maple	Roots are lifting and cracking the curb and lifting the sidewalk panels.

### **Comments**

It is my understanding that the HOA will be replanting with Rocky Mountain Glow maples and the removals and plantings will take place in October 2019. The trees shall meet the City's standards for deciduous trees in size and quality of stock.


Sincerely,



Kevin M. McFarland, Principal  
Consulting Forester  
ISA Certified Arborist PN-0373 & ISA Tree Risk Assessment Qualified

Sound Urban Forestry, LLC  
1910 E. 4<sup>th</sup> Ave., PMB 97  
Olympia, WA 98506  
360-870-2511

## Locations of Proposed Street Tree Removals



**Photo of Typical Damage with White Ash**



**Photo of Typical Damage with Red Maple**

