


-- Measurement Points --



KPF Home Inspections does not represent itself as a structural engineering firm. This report is provided ONLY for the benefit of the client in helping to decide if further evaluation by a structural engineer is warranted.

This diagram is NOT exactly to scale.


It was created from a snippet of the architectural plans found on the builder's website.

Front of Structure

Page A1


KPF Home Inspections does not represent itself as a structural engineering firm. This report is provided ONLY for the benefit of the client in helping to decide if further evaluation by a structural engineer is warranted.

-- Measurements Corrected for Floor Coverings --



This diagram is NOT exactly to scale.


It was created from a snippet of the architectural plans found on the builder's website.



This diagram is NOT exactly to scale.

It was created from a snippet of the architectural plans found on the builder's website.

-- Topographic Interpretation of Slab Surface Based on Measurements --



KPF Home Inspections does not represent itself as a structural engineering firm. This report is provided ONLY for the benefit of the client in helping to decide if further evaluation by a structural engineer is warranted.

This diagram is NOT exactly to scale.

It was created from a snippet of the architectural plans found on the builder's website.

Front of Structure

Page A4