



REIDY CONTRACTING GROUP

DOB TRACKING

Project: DEA - Tenant Improvements

Job # J16-015/016

Location: 99 10th Ave

Site Super: Conor O'Leary

Expeditor: Milrose Consultants

Expeditor Contact: Kevin Stiles

Special Inspector: Skyline Engineering

Special Inspector Contact: Ian Johnson

Application	Responsible Inspector	Rough In Inspection	Final Inspection	Notes
General Construction (5-8) - 12260447-01				
Flood Zone Compliance	Skyline	N/A	PENDING	
Fire-Resistant Penetrations and Joints	Skyline	PENDING	PENDING	
Energy Code Compliance Inspections	Skyline	N/A	PENDING	
Fire-Resistive Rated Construction	Skyline	PENDING	PENDING	
Structural (7, Roof) - 122604477-02				
Structural Steel - Welding	Skyline	PENDING	PENDING	
Structural Steel - High Strength Bolting	Skyline	PENDING	PENDING	
Structural Stability - Existing Buildings	Skyline	PENDING	PENDING	
Mechanical (7, 8, Roof) - 122604477-03				
Mechanical Systems	Skyline	PENDING	PENDING	
Energy Code Compliance Inspections	Skyline	N/A	PENDING	
Sprinkler (7, 8) - 122575034				
Hydrostatic test	Skyline	PENDING	PENDING	
Final inspection	Skyline	N/A	PENDING	
Electrical (7, 8, Roof) - M378429				
Final inspection	BEC	N/A	PENDING	
Plumbing (7, 8, Roof) - 122604477				
Plumbing roughing	DOB	PENDING	PENDING	
Fire Alarm (7, 8) - 122615697				
FDNY Inspection	FDNY	PENDING	PENDING	