



Shelbyville 7th Street Corridor Plan



Contents

Introduction	3
Existing Conditions	4
Process	6
Community Engagement and Participation	6
Community Meetings	6
Study Findings	9
Meeting #1 - Walkability and Land Use/Building Condition Survey Results	9
FIGURE 1: SUMMARY OF LAND USE AND BUILDING CONDITION SURVEY	9
FIGURE 2: WALKABILITY SURVEY HIGHLIGHTS	10
FIGURE 3: CURRENT LAND USE MAP	11
Meeting #2 - Visioning Workshop Responses and Maps	12
Meeting #3 - Draft Plan Feedback and Comments from Participants	14
Implementation	15
Recommendations	15
FIGURE 4: PRELIMINARY IMPROVEMENT RECOMMENDATIONS	15
FIGURE 5: EXISTING CONDITIONS	17
FIGURE 6: CONCEPTUAL STREET IMPROVEMENT DESIGN (NORTH OF CLEAR CREEK) BASED ON PUBLIC INPUT AND IDEAL CONDITIONS	18
FIGURE 7: CONCEPTUAL STREET IMPROVEMENT DESIGN (7th STREET AND BURKS BRANCH ROAD, WASHINGTON STREET TO CLEAR CREEK PARK)	19
FIGURE 8: CONCEPTUAL STREET NETWORK IMPROVEMENTS PLAN	21
FIGURE 9: CLEARVIEW PARK REDEVELOPMENT CONCEPT	23
FIGURE 10: RAILROAD SPUR ARTS DISTRICT CONCEPT	25
FIGURE 11: CONCEPTUAL TRAFFIC ROUNDABOUT	27
FIGURE 12: PROPOSED LAND USE	30
Project Phasing	31
Implementation Strategy	31
Appendix A: Group Photo Inventory Images	32
Appendix B: Group Mapping Exercises	34
Appendix C: Project Participants	36
About the Authors	37



Source: MapQuest

Aerial Image
7th Street Primary Study Area