

Dam Maintenance – Dec. 2021

On December 9th, 2021, Kirkpatrick Construction started work behind the spillway. Kirkpatrick construction removed the rocks behind the spillway. They laid a grade behind the spillway to make the creek smooth and remove the large piles of dirt that were blocking the water flow. After they finished grading the creek, they laid the rocks back to the creek behind the spillway flat. Now there is a smoother surface for the water to flow better. The project cost was \$5,800. There are pictures below of before and after the spillway work was completed. The before pictures are from December 2017 and the after pictures were taken on January 16th, 2022.



Figure 1: Before Picture from December 2017



Figure 2: After Picture from January 2022



Figure 3: Before Picture from December 2017



Figure 4: After Picture from January 2022



Figure 5: After Picture from January 2022



Figure 6: After Picture from January 2022