

**Product # 1-0801**  
**3/8" Boulder Canyon Granite**



- **1 Cubic Yard = 1.49 Tons**
- **Description**
  - **Crusher fines material**
- **Uses**
  - **Driveways**
  - **Parking lots**
  - **Trail paths and walkways**
  - **Structural fill**



# LABORATORY TEST REPORT

627 Sheridan Boulevard • Lakewood, CO 80214  
 303.975.9959 • office@westest.net

PROJECT: Valmont Pit  
 WesTest PROJECT NO.: 805522  
 CLIENT: Boulder Recycled Aggregate  
 Mr. Kent Hogan  
 6405 Valmont Rd.  
 Boulder, CO 80301

REPORT DATE: March 23, 2022  
 DATE SAMPLED: March 17, 2022  
 DATE RECEIVED: March 14, 2022  
 DATE TESTED: March 17 - 22, 2022  
 SAMPLED BY: Client  
 SOURCE: Stockpile  
 SAMPLE LOCATION: Valmont Pit- 4 Mile Canyon  
 SAMPLE DESCRIPTION: Crusher Fines 3/8" BCG  
 SAMPLE NO.: 1

### GRADATION ANALYSIS - AASHTO T 11 & T 27, ASTM C 117 & C 136

SIEVE SIZE	PERCENT PASSING	
	SAMPLE	CDOT CLASS 1 STRUCTURAL FILL SPECIFICATION
2"	100	100
1 - 1/2"	100	
1"	100	
3/4"	100	
1/2"	100	
3/8"	98	
#4	85	30 - 100
#8	70	
#16	53	
#30	40	
#50	30	10 - 60
#100	20	
#200	14.2	5 - 20

### PLASTICITY INDEX - AASHTO T 89 & T 90, ASTM D4318

		SPECIFICATION
LIQUID LIMIT (%)	No Value	35 Max.
PLASTIC LIMIT (%)	No Value	
PLASTICITY INDEX	Non-Plastic	6 Max.

\* Denotes deviation from specification

REVIEWED BY: \_\_\_\_\_