

DELHI JAL BOARD: GOVT. OF NCT OF DELHI
OFFICE OF THE EXECUTIVE ENGINEER (RWH/GWC)
ROOM NO. 209, VARUNALAYA PHASE-I
KAROL BAGH, NEW DELHI – 110005
23558264

No./DJB/EE(RWH/GWC)/2019/ 848

DATED: 8/3/19

To,

Principal,
Saraswati Bal Mandir Sr. Sec. School,
Ward No.-6, Mehrauli,
New Delhi-30


Subject:-Regarding adequacy of rain water harvesting system at Saraswati Bal Mandir Sr. Sec. School, Ward No.-6, Mehrauli, New Delhi-30.

Sir/Madam,

The above said unit has been inspected by Joint Inspection Team on 07.03.2019, constituted by Hon'ble NGT in O.A. No. 217/2016. It was found that two Nos. RWH pits are existing at site.

The existing RWH structures are adequate to harvest the roof top run-off for catchment area of above said unit. The RWH structure was found to be functional at the time of inspection.

You are advised to keep the existing RWH system neat & clean & maintain the same periodically. Rain Water conveyance system shall be duly kept connected to RWH pits and filter media shall be maintained and kept neat & clean, as per DJB norms and over flow shall always remain connected to municipal drain.


EE (RWH/GWC)
EE (G W CELL)
DELHI JAL BOARD
VARUNALAYA GHAWAN,
JHANDEWALLAN, N.D.-05