



Project/ Field Service Experience



AFTRAC

www.aftrac.com



AFTRAC WELL TESTING WORK EXPERIENCE

Client	Field / Location	Work / Job Scope Executed	Date Mobilised	Date Demobilised
ADDAX	KTM-18 HIGHISLAND VII	WELL INTERVENTION	01-01-2013	13-01-2013
	KTM-18 HIGHISLAND VII	WELL CLEAN UP OPERATIONS	22-12-2013	25-01-2014
	AD H-10/ HIGHISLAND -7	WELL INTERVENTION	03-09-2012	12-09-2012
	SCARABEO 3	WELL INTERVENTION	11-04-2012	21-04-2012
	KTM-15H ADRIATIC	WELL CLEAN-UP OPERATIONS	19-11-2012	27-11-2012
	SCARABEO 3	SURFACE WELLTEST	11-04-2012	30-06-2012
	ONOME ADNH-14H-OML-123	WELL CLEAN UP	27-06-2010	05-07-2010
AMNI INT.	IMA 13	WELL CLEAN UP	06-07-2010	21-07-2010
	IMA 14	SURFACE WELLTESTING & CLEAN UP	17-04-2012	24-10-2012
TOTAL E&P	IME 6 (OML102)	PRODUCTION OPTIMIZATION	27-02-2013	25-03-2013
	OLO, OML 58	TANK RIG-UP FOR CRUDE RECEIPT	24-01-2011	01-02-2011
	IBW - 19	SURFACE WELL TESTING	15-07-2010	17-07-2010
	OB 025, 111, 024	PRODUCTION OPTIMIZATION	30-04-2010	12-05-2010
	OB 25, 68, 111	PRODUCTION OPTIMIZATION	01-04-2010	12-04-2010
	OB 53, 113	PRODUCTION OPTIMIZATION	04-11-2010	09-11-2010
	OB 28/4, 28/5	PRODUCTION OPTIMIZATION	24-02-2014	04-03-2010
	OB 90 & 08	PRODUCTION OPTIMIZATION	08-10-2009	15-10-2009
	OB 80/4, 35/4, 28/4, 68/4	PRODUCTION OPTIMIZATION	23-12-2009	31-12-2009
	IBW 16	WELL CLEAN-UP OPERATIONS	17-02-2008	26-02-2008
OANDO	AKEPO 1ST	SURFACE WELL TEST	17-11-2009	17-12-2009
CENTURY ENERGY	ATALA	WELL COMPLETION	23-03-2012	26-04-2012
SEPLAT	OBEN	GAS WELL TEST CLEAN UP OPERATIONS	14-02-2013	02-03-2013
	AMUKPE 2T	WATER INJECTIVITY AND FALL-OFF TEST	04-11-2013	16-11-2013
MOVIDO	MOVIDO, EKEH-2H	SURFACE WELL TEST	27-01-2010	09-03-2010
HALLIBURTON	SEPLAT- OBEN-34	SURFACE WELL TEST AND SAND MONITORING	24-12-2014	01-10-2015
CETCO	ADDAX - AD-17H	WELL CLEAN UP	02-07-2014	02-08-2014
	ADDAX - AD - 10	WELL CLEAN UP	25-04-2014	07-05-2014
	ADDAX - AD - 11	RENTAL (4"x206 elbows, 24pcs)	11-04-2014	04-09-2014
	SPDC - ADANGA SOUTH	WELLTEST & CLEAN-UP	18-05-2014	12-06-2014
	ADDAX - SCARABEO OK - 33	WELLTEST & CLEAN-UP	26-05-2014	02-06-2014
	ADDAX - OK 34	WELL CLEAN UP	23-07-2014	19-07-2014
	ADDAX - AD-10	SURFACE WELL TESTING	24-05-2014	20-06-2013
	ADDAX - AD-7	WELL TEST SUPERVISION	01-06-2013	20-06-2013
	SPDC - AGBARAN 14	GAS WELL TEST	22-04-2013	07-05-2013
	SPDC - UGHELLI 18	WELL CLEAN UP	23-09-2012	10-10-2012
	SPDC - OB - 6, 8, 128/118	RENTAL (DATA HEADER 2X)	03-08-2012	09-10-2012
	SPDC - OYIGBO NORTH WELL	WELL TEST/ CLEAN UP	11-05-2012	14-05-2012
	SPDC - GBARAN 14	PRESSURE BLEED-OFF	31-07-2012	09-08-2012
	SPDC - UTOROGU 29	WELL CLEAN UP	21-08-2012	01-09-2012
	SPDC - UGHELLI 18	WELLTEST EQUIPMENT RENTAL	29-09-2012	09-10-2012
	SPDC - AGBARAN 14	GAS WELL TEST	22-04-2013	07-05-2013



AFTRAC WELL TESTING WORK EXPERIENCE

Client	Field / Location	Work / Job Scope Executed	Date Mobilised	Date Demobilised
BAKER HUGHES	SPDC - EA	COILED TUBING & FLOWBACK OPERATIONS	04-02-2017	19-04-2017
	SPDC - EPU/KUMA	COILED TUBING & FLOWBACK OPERATIONS	04-08-2017	30-04-2017
	NDPR - OGBELE 5	COILED TUBING & FLOWBACK OPERATIONS	05-03-2017	23-09-2017
	NDPR - OGBELE 7	COILED TUBING & FLOWBACK OPERATIONS	10-05-2017	11-12-2017
	SPDC - FYIP	COILED TUBING & FLOWBACK OPERATIONS	24-09-2017	26-10-2017
	SPDC - SOKU	COILED TUBING & FLOWBACK OPERATIONS	16-11-2017	01-09-2018
	EXXON - UNAM	COILED TUBING & FLOWBACK OPERATIONS	24-11-2017	27-07-2018
	EXXON - EDOP	COILED TUBING & FLOWBACK OPERATIONS	26-06-2018	25-03-2019
	DUBRI-GG8	COILED TUBING & FLOWBACK OPERATIONS	22-02-2019	07-03-2019
	EXON-WHISKY STAR	COILED TUBING & FLOWBACK OPERATIONS	01-03-2019	30-03-2019
	NAOC-IDU-8GP	GRAVEL PACK OPERATION	26-04-2019	12-05-2019
	BELEMAOIL-ROBERTKIRI	PRODUCTION OPTIMIZATION	21-10-2019	05-12-2019
EUNICEL	NPDC - Delta state	WELL TEST PERFORMANCE	12-11-2014	23-11-2014
	OFA 1	SURFACE WELL TEST	16-11-2012	07-12-2013
WELLFLUIDS SERVICES	NPDC - OBEN	OBEN GAS WELL TEST CLEAN UP	14-02-2013	02-03-2013
OILDATA/XENERGY	KWALE, ANEZIE 16	WELL CLEAN UP & WELL TEST	28-11-2015	05-12-2015
	EBENDO, OKW 17	EQUIPMENT HIRE (SSV)	16-09-2015	28-09-2015
	EBENDO 7	WELL CLEAN UP	04-03-2014	21-03-2014
	OFA 1	ACID SURFACE WELL TEST	24-01-2014	03-02-2014
	EBENDO 6, KWALE	WELL CLEAN UP & EXTENDED WELL TESTING	13-06-2013	11-07-2013
	OFA 1	WELLTEST CAMPAIGN	16-11-2013	07-12-2013
	EBENDO 5	WELL TEST & EQUIPMENT HIRE	20-12-2012	09-02-2013
	ATALA 1	PROVISION OF COMPLETION TUBING	18-06-2012	13-08-2012
	EBENDO 4	SURFACE WELLTEST	27-06-2012	17-08-2012
HERITAGE	DELTA OLE	PRODUCTION OPTIMIZATION	15-12-2017	18-04-2018
DUBRI	GILLIGILLI-8	EARLY PRODUCTON FACILITY	06-12-2017	02-03-2018
GEOPLEX/NAOC	OES INTEGRITY RIG	MER SURFACE WELL TESTING	05-06-2019	13-06-2019



AFTRAC FIELD WORK EXPERIENCE

CLIENT	Field / Location	Work / Job Scope Executed	Date Mobilised	Date Demobilised
ADDAX	KTM-18 HIGHLAND VII	SURFACE WELLTEST	01-01-2013	13-01-2013
	KTM-18 HIGHLAND VII	WELL CLEAN UP	22-12-2013	25-01-2014
	AD H-10/ HIGHLAND -7	SURFACE WELL TESTING	03-09-2012	12-09-2012
	SCARABEO 3	PROVISION OF SEPARATOR & 2 PERSONEL	11-04-2012	21-04-2012
	KTM-15H ADRIATIC	SURFACE WELLTEST & CLEAN UP	19-11-2012	27-11-2012
	SCARABEO 3	SURFACE WELLTEST	11-04-2012	30-06-2012
	ONOME ADN-14H-OML-123	WELL CLEAN UP	27-06-2010	05-07-2010
	OKWORI-SCARABEO 3-OK32	PROVISION OF CLAMPON PERSONNEL & EQUIPMENT	12-02-2014	18-02-2014
	OML 123, ANTAN FIELD	INSPECTION OF CLIENT EQUIPMENT	12-11-2013	23-11-2013
	SCARABEO 3-OK 30	SAND MONITORING ON WELL CLEAN-UP	02-11-2013	07-11-2013
	SCARABEO 3 - OK 29H	SAND MONITORING	16-09-2013	29-09-2013
	SCARABEO 3 - OK 28	SAND/SEDIMENT CHECK DURING WELL CLEAN-UP	21-07-2013	30-07-2013
	ONOME (SEAWOLF) ADN-14H	SAND MONITORING	27-06-2010	05-07-2010
	OKWORI-ND 6	SAND MANAGEMENT TRAINING	28-04-2008	03-05-2008
	AMNI INT.	IMA 13	WELL CLEAN UP	06-07-2010
IMA 14		SURFACE WELLTESTING & CLEAN UP	17-04-2012	24-10-2012
IMA 14		SAND MONITORING	31-05-2010	03-06-2010
IMA 13		SAND MONITORING DURING WELL TESTING	06-07-2010	18-08-2010
TOTAL E&P	IME 6 (OML102)	SAND CHECK CAMPAIGN	27-02-2013	25-03-2013
	OLO, OML 58	TANK RIG-UP FOR CRUDE RECEIPT	24-01-2011	01-02-2011
	IBW - 19	SURFACE WELL TESTING	15-07-2010	17-07-2010
	OB 025, 111, 024	TEMPORARY WELL HOOK UP	30-04-2010	12-05-2010
	OB 25, 68, 111	TEMPORARY WELL HOOK UP	01-04-2010	12-04-2010
	OB 53, 113	TEMPORARY WELL HOOK UP	04-11-2010	09-11-2010
	OB 28/4, 28/5	PIPING RIG-UP	24-02-2014	04-03-2010
	OB 90 & 08	TEMPORARY WELL HOOK UP	08-10-2009	15-10-2009
	OB 80/4, 35/4, 28/4, 68/4	TEMPORARY WELL HOOK UP	23-12-2009	31-12-2009
	IBW 16	WELL CLEAN-UP	17-02-2008	26-02-2008
	OFON 39, 42	SAND MONITORING SERVICE	14-11-2015	29-12-2015
	IBW 126, 128, 129, 15, 17	SAND MONITORING SERVICE	11-06-2015	17-11-2015
	OFON 41, 08, OML102	SAND MONITORING DURING WELL START UP/RAMP UP	25-09-2015	14-10-2015
	AMKP (AMD 1& 2) 2-12, 2-13, 2-15, 2-23, 2-41, 2-11, 207	SAND MONITORING SERVICE	29-06-2015	07-07-2015
	IME 7, 12	SAND MONITORING /PURCHASE OF ASD	05-07-2015	05-12-2015
	OBAGI OML 58 GAS WELLS	SAND MONITORING SERVICE	21-10-2014	10-11-2014
	SCAREBEO OK-33	SAND MONITORING SERVICE	25-05-2014	02-06-2014
	AMENAM KPONO 2-14	SENSOR RELOCATION/ TROUBLE SHOOTING	23-05-2014	26-05-2014
	OB 125, OML58	SAND MONITORING SERVICE	02-01-2014	12-03-2014
	AMKP, OML 99	SAND MONITORING/ANTIVIRUS ISSUES AND POOR CONNECTIONS	10-08-2014	12-08-2014
	OB 1-05, OML 58	SAND MONITORING CAMPAIGN	15-08-2013	28-08-2013
	OB 1-29, OML 58	SAND MONITORING CAMPAIGN	09-09-2013	24-09-2013
	AMKP (AMD 1& 2) 2-23,2-12, 2-03, 207	PERMANENT INSTALLATION AND SAND MONITORING	28-02-2013	01-03-2013
	OB 1-22, OML 58	SAND MONITORING CAMPAIGN	10-04-2013	10-10-2013
	IME 6	SAND MONITORING DURING WELL START UP	03-02-2013	03-08-2013

	IME 6 (OML102)	SAND CHECK CAMPAIGN	27-02-2013	25-03-2013
	OB 1-28	WELL CLEAN-UP & WELLTEST	12-08-2012	26-08-2012
	OFON 1&2	SAND MONITORING CAMPAIGN	27-01-2012	01-02-2012
	IBW 16	SAND MONITORING	06-04-2012	28-05-2012
	EBEN DST	SAND MONITORING	21-02-2012	04-04-2012
	AMENAM HP WELLS	INSTALLATION & COMMISSIONING OF Eexd's	25-07-2012	18-08-2012
	OB 1-28	WELL CLEAN-UP & WELLTEST	12-08-2012	26-08-2012
	OFON 1&2	SAND MONITORING CAMPAIGN	27-01-2012	01-02-2012
	IBW 16	SAND MONITORING	06-04-2012	28-05-2012
	EBEN DST	SAND MONITORING	21-03-2012	04-04-2012
	AMENAM HP WELLS	INSTALLATION & COMMISSIONING OF Eexd's	25-07-2012	18-08-2012
	AMKP 2-41	SAND MONITORING	15-10-2011	24-10-2011
	OB 126	SAND CHECK DURING WELL CLEAN UP	12-09-2011	28-09-2011
	AMKP 1-26, 1-37, 1-10, 1-27, 2-04, 2-08, 2-12	PERMANENT INSTALLATION AND SAND MONITORING	11-04-2011	22-04-2011
	ETINSONG 1 DST	SAND MONITORING ON DST	08-04-2011	25-04-2011
	IME 12	SAND CHECK DURING DST	21-09-2011	07-10-2011
	OML 100/102, IME-13	WELL CLEAN-UP	01-12-2011	29-12-2011
	AMKP 109, 119, 110 & 127	PRODUCTION & SAND MONITORING	16-02-2011	31-03-2011
	IBW 20	SAND MONITORING ON CLEAN UP	31-05-2011	01-07-2011
	AMKP 2-41	SAND MONITORING	15-10-2011	24-10-2011
	OB 126	SAND CHECK DURING WELL CLEAN UP	12-09-2011	28-09-2011
	AMKP 1-26, 1-37, 1-10, 1-27, 2-04, 2-08, 2-12	PERMANENT INSTALLATION AND SAND MONITORING	11-04-2011	22-04-2011
	ETINSONG 1 DST	SAND MONITORING ON DST	08-04-2011	25-04-2011
	IME 12	SAND CHECK DURING DST	21-09-2011	07-10-2011
	OML 100/102, IME-13	WELL CLEAN-UP	01-12-2011	29-12-2011
	AMKP 109, 119, 110 & 127	PRODUCTION & SAND MONITORING	16-02-2011	31-03-2011
	IBW 20	SAND MONITORING ON CLEAN UP	31-05-2011	01-07-2011
	IBW 19	SAND MONITORING ON WELLTESTING	15-07-2010	12-08-2010
	IBW 19	SAND MONITORING	10-12-2009	20-12-2009
	AKPO B-02	SAND MONITORING ON WELL CLEAN-UP	20-04-2009	08-05-2009
	AMENAM	PERMANENT INSTALLATION	17-03-2009	19-03-2009
	AKPO 114	SAND MONITORING / CONTROL SERVICES	06-04-2009	02-05-2009
	AKPO 1-09	SAND MONITORING /WELL CLEAN UP	15-03-2009	03-04-2009
	AMKP 2-18	INSTALLATION	27-10-2008	03-11-2008
	AMENAM 240	WATER INJECTION/ WELL CLEAN UP	26-09-2008	08-10-2008
	OML 130 AKPO 1-08	SAND MONITORING	19-11-2008	28-11-2008
	AMKP 1-37	SAND MONITORING	17-01-2008	26-01-2008
	IBW 16	SAND MONITORING FOR WELL CLEAN-UP/PRODUCTION T	15-03-2008	30-03-2008
	AMKP 1-25/ 1-38	SAND MONITORING ON WELL CLEAN-UP	16-04-2008	21-04-2008
	IBW 16	SAND MONITORING ON WELL CLEAN-UP	02-03-2008	08-08-2008
	EBOLIBO - USARI FC	USARI SAND CHECK CAMPAIGN	18-05-2008	27-05-2008
	IBW - 6/15	SAND MONITORING	21-12-2007	27-01-2008
	IBW 14	SAND MONITORING FOR PRODUCTION OPTIMIZATION	29-11-2007	02-12-2007
	OLO 1-5, IBW 14	SAND MONITORING FOR PRODUCTION OPTIMIZATION	06-07-2007	02-12-2007
OANDO	AKEPO 1ST	SURFACE WELL TEST	17-11-2009	17-12-2009
CENTURY ENERGY	ATALA	SUPPLY OF COMPLETION TUBING	23-03-2012	26-04-2012
SEPLAT	OBEN	GAS WELL TEST CLEAN UP	14-02-2013	02-03-2013

	AMUKPE 2T	WATER INJECTIVITY AND FALL-OFF TEST	04-11-2013	16-11-2013
MOVIDO	MOVIDO, EKEH-2H	SURFACE WELL TEST	27-01-2010	09-03-2010
HALLIBURTON	SEPLAT- OBEN-34	SURFACE WELL TEST AND SAND MONITORING	24-12-2014	01-10-2015
CETCO	ADDAX - AD-17H	WELL CLEAN UP	02-07-2014	02-08-2014
	ADDAX - AD - 10	WELL CLEAN UP	25-04-2014	07-05-2014
	ADDAX - AD - 11	RENTAL (4"x206 elbows, 24pcs)	11-04-2014	04-09-2014
	SPDC - ADANGA SOUTH	WELLTEST & CLEAN-UP	18-05-2014	12-06-2014
	ADDAX - SCARABEO OK - 33	WELLTEST & CLEAN-UP	26-05-2014	02-06-2014
	ADDAX - OK 34	WELL CLEAN UP	23-07-2014	19-07-2014
	ADDAX - AD-10	SURFACE WELL TESTING	24-05-2014	20-06-2013
	ADDAX - AD-7	WELL TEST SUPERVISION	01-06-2013	20-06-2013
	SPDC - AGBARAN 14	GAS WELL TEST	22-04-2013	07-05-2013
	SPDC - UGHELLI 18	WELL CLEAN UP	23-09-2012	10-10-2012
	SPDC - OB - 6, 8, 128/118	RENTAL (DATA HEADER 2X)	03-08-2012	09-10-2012
	SPDC - OYIGBO NORTH WELL	WELL TEST/ CLEAN UP	11-05-2012	14-05-2012
	SPDC - GBARAN 14	PRESSURE BLEED-OFF	31-07-2012	09-08-2012
	SPDC - UTOROGU 29	WELL CLEAN UP	21-08-2012	01-09-2012
	SPDC - UGHELLI 18	WELLTEST EQUIPMENT RENTAL	29-09-2012	09-10-2012
BAKER HUGHES	SPDC - EA	FLOW BACK OPERATIONS	04-02-2017	19-04-2017
	SPDC - EPU/KUMA	FLOW BACK OPERATIONS	04-08-2017	30-04-2017
	NDPR - OGBELE 5	FLOW BACK OPERATIONS	05-03-2017	23-09-2017
	NDPR - OGBELE 7	FLOW BACK OPERATIONS	10-05-2017	11-12-2017
	SPDC - FYIP	FLOW BACK OPERATIONS	24-09-2017	26-10-2017
	SPDC - SOKU	FLOW BACK OPERATIONS	16-11-2017	01-09-2018
	EXXON - UNAM	FLOW BACK OPERATIONS	24-11-2017	27-07-2018
	EXXON - EDOP	FLOW BACK OPERATIONS	26-06-2018	25-03-2019
	BELEMAOIL-ROBERTKIRI	SAND CLEAN-UP OPERATIONS	21-10-2019	05-12-2019
	NAOC-IDU-8GP	GRAVEL PACK OPERATION	26-04-2019	12-05-2019
	EXXON-WHISKY STAR	FLOW BACK DURING COIL TUBING OPERATIONS	01-03-2019	30-03-2019
	DUBRI-GG8	FLOW BACK DURING COIL TUBING OPERATIONS	22-02-2019	07-03-2019
EUNICEL	NPDC - Delta state	WELL TEST PERFORMANCE	12-11-2014	23-11-2014
	OFA 1	SURFACE WELL TEST	16-11-2012	07-12-2013
WELLFLUIDS SERVICES	NPDC - OBEN	OBEN GAS WELL TEST CLEAN UP	14-02-2013	02-03-2013
OILDATA/XENERGY	KWALE, ANEZIE 16	WELL CLEAN UP & WELL TEST	28-11-2015	05-12-2015
	EBENDO, OKW 17	EQUIPMENT HIRE (SSV)	16-09-2015	28-09-2015
	EBENDO 7	WELL CLEAN UP	04-03-2014	21-03-2014
	OFA 1	ACID SURFACE WELL TEST	24-01-2014	03-02-2014
	EBENDO 6, KWALE	WELL CLEAN UP & EXTENDED WELL TESTING	13-06-2013	11-07-2013
	OFA 1	WELLTEST CAMPAIGN	16-11-2013	07-12-2013
	EBENDO 5	WELL TEST & EQUIPMENT HIRE	20-12-2012	09-02-2013
	ATALA 1	PROVISION OF COMPLETION TUBING	18-06-2012	13-08-2012
	EBENDO 4	SURFACE WELLTEST	27-06-2012	17-08-2012
HERITAGE	DELTA OLE	MER WELL TEST	15-12-2017	18-04-2018
DUBRI	GILLIGILLI-8	EPF	06-12-2017	02-03-2018
SNEPCO	BONGA FPSO	PRE-COMMISSIONING AND SET-UP OF SAND MONITORS	09-04-2005	19-04-2005
	LAG/ ANTHONY	PROCUREMENT OF UIS	08-12-2011	09-12-2011
	LAG/ ANTHONY	INSTALLATION OF UIS	18-03-2012	19-03-2012
NAE	ABO 10/3	EQUIPMENT HEALTH CHECK/ SAND MONITORING	22-05-2014	24-05-2014
	ABO WELLS	INSTALLATION & COMMISSIONING OF EQUIPMENTS	13-07-2014	27-07-2014

	ABO WELLS	EQUIPMENT INSPECTION	17-10-2013	21-10-2013
	ABO 3ST	RISER INSPECTION	06-12-2013	18-12-2013
	ABO FPSO	TRAINING ON NORMS	07-12-2010	15-12-2010
	ABO FPSO	SAND MONITORING	14-01-2010	22-01-2010
	ABO FPSO	TRAINING ON NORMS	14-04-2010	19-04-2010
	OSHEI (OMOKU)	SAND MONITORING	19-08-2010	19-09-2010
	ONNE FOT	SAND MONITORING ACQUISITION	20-03-2014	21-03-2014
	FPSO ABO	SAND MONITORING ACQUISITION	30-05-2014	24-06-2014
	FPSO ABO	SAND MONITORING	07-09-2013	19-10-2013
	FPSO ABO	INSPECTION OF UIS	17-10-2011	21-10-2011
	FPSO ABO	PROVISION OF SAND DENSITY	28-02-2011	16-06-2011
	FPSO ABO	INSPECTION OF UIS	04-09-2011	06-10-2011
	FPSO ABO	HEALTH CHECK OPERATION ON CLAMPON DSP PARTICLE MONITORS	2019-01-28	02-05-2019
	FPSO ABO	HEALTH CHECK OPERATION ON CLAMPON DSP PARTICLE MONITORS	2019-04-15	2019-04-24
	FPSO ABO	PROCUREMENT/INSTALLATION OF SAND MONITORS & SAND MONITORING OPERATION	2019-08-24	05-09-2019
EXXON MOBIL	EKET	CLAMPON TRAINING	25-07-2013	29-07-2013
	UQUO 7 & 8	SAND MONITORING	18-12-2014	31-12-2014
	UQUO 4	SAND MONITORING ON WELLTEST CAMPAIGN	05-03-2013	06-06-2013
	EKET- UQUO 2 & 4	SAND MONITORING ON DST	16-04-2010	22-04-2010
	UQUO 3	PROVISION OF SAND MONITORING ON DST	27-12-2009	23-01-2010
	USARI B & C	SAND MONITORING	01-07-2008	07-09-2008
	USARI B & C	SAND MONITORING	08-04-2008	15-04-2008
	USARI B & C	SAND MONITORING	13-02-2008	06-04-2008
	USARI B & C	SAND MONITORING	26-06-2008	14-07-2008
	USARI B & C	SAND MONITORING	05-03-2008	31-03-2008
HALLIBURTON	SCARABEO 3	SAND MONITORING	13-05-2014	02-06-2014
NAOC	OSHEI (OMOKU)	SAND MONITORING	19-08-2008	19-08-2008
	OYO 4	ESTABLISH TREND OF PARTICLES	15-06-2007	29-06-2007
	UBIT GP G14	UBIT SAND ACOUSTIC MONITORING	01-09-2013	01-10-2013
	OGBAINBIRI	SAND MONITORING DURING WELL TEST OPERATIONS	18-12-2016	04-02-2017
NLNG	NLNG BONNY	SAND PARTICLE ANALYSIS	22-12-2010	05-01-2011
	NLNG BONNY	DEPOSIT DETERMINATION ON PIPELINES	20-02-2008	24-02-2008
SPDC	EA DRILL PLATFORM	SAND MONITORING	03-04-2012	04-04-2012
	EA DRILL PLATFORM	SAND MONITORING	11-02-2011	14-02-2011
	EA FIELD	SAND MONITORING	19-09-2011	07-10-2011
	EA FIELD	PROVISION OF SPECIALIST SUPPORT	17-02-2011	15-03-2011
	AGBADA 2	SAND MONITORING	05-03-2010	09-09-2010
	AGBADA	CILAMPON SENSOR HEALTH CHECK	09-10-2010	12-10-2010
	BONGA FPSO	CALIBRATION OF FPSO CLAMP-ON SENSORS	30-05-2009	05-07-2009
	UTOROGU	SAND MONITORING DURING WELL TESTING	24-12-2007	05-01-2008
	AGBADA	SAND MONITORING/WELL OPTIMISATION	24-05-2007	11-07-2007
	BONNY	SAND MONITORING	21-05-2007	25-05-2007
	AGBADA	PROVISION OF TECHNICAL SERVICES	07-01-2007	31-05-2007
	BONGA	SENSOR REPAIR	01-09-2006	04-09-2006
	BNAG	SENSOR REPAIR FOR OLOMA MANIFOLD	23-10-2006	12-11-2006
	BONGA	PROVISION OF TECHNICAL SERVICES	04-09-2003	21-10-2003
	BONGA WELL 7	PROVISION OF TECHNICAL SERVICES	11-03-2003	12-09-2003

	BONGA (SEDCO 709)	SANDMONITORING/ 2 SENSOR RENTAL	07-11-2003	11-11-2003
	WARRI	SAND MONITORING	31-07-2002	03-09-2002
SCHLUMBERGER	UBIT GP G14	SAND EROSION MONITORING	26-06-2013	10-07-2013
	ERHA FPSO	INTEGRITY CHECK ON ASD	23-07-2012	27-07-2012
	UBIT	SAND MONITORING SERVICES	28-08-2012	29-08-2012
	JACK RYAN (OML 130)-AKPO 114	SAND MONITORING & SAND CHECK CONTROL	15-09-2009	20-09-2009
	AKPO	SAND MONITORING SERVICES	08-04-2009	13-04-2009
	AKPO 1-14	SAND MONITORING SERVICES	01-03-2009	31-03-2009
	USARI	SAND CHECK CAMPAIGN	01-07-2008	09-07-2008
	JACK RYAN - AKPO 101	SAND MONITORING & SAND CHECK CONTROL	18-12-2007	24-12-2007
CHEVRON/IDMON	ABITEYE FLOW STATION	INSTALLATION & CALIBRATION OF CLAMPON DSP PARTICLE MONITOR	13-08-2019	22-08-2019
GEOPLEX/NAOC	OES INTEGRITY RIG	MER SURFACE WELL TESTING	05-06-2019	13-06-2019
FIRST E&P	ANYALA	PROCUREMENT & SUPPLY OF DSP PIG AND SAND MONITORS	31-07-2019	31-12-2020
	MADU	PROCUREMENT & SUPPLY OF DSP PIG AND SAND MONITORS	31-07-2020	31-12-2021
EQUITY	GBARAN 7	FLOW BACK OPERATIONS	07-03-2020	13-03-2020

List of Permanent Installed ClampOn Sensors in Nigeria by Year

Client	Field / Location	Work / Job Scope Executed	Type	Year
Shell	Utorogo	ClampOn DSP Particle Monitor	Topside	2001
Shell	Warri	ClampOn DSP Particle Monitor	Topside	2001
Shell	Bonga	ClampOn DSP Deepwater Particle Monitor	Subsea	2002
Shell	Bonny Island	ClampOn DSP Particle Monitor	Topside	2002
ExxonMobil	Erha	ClampOn DSP Particle Monitor	Topside	2003
ExxonMobil	Yoho	ClampOn DSP Particle Monitor	Topside	2003
ExxonMobil	Erha	ClampOn DSP Deepwater PIG Detector	Subsea	2004
Shell	Bonga	ClampOn DSP Particle Monitor	Topside	2004
Shell	Bonny Island	ClampOn DSP Particle Monitor	Topside	2004
Shell	Bonny Island Slug Catcher	ClampOn DSP Corrosion-Erosion Monitor	Topside	2004
Total	Amenaa Kpono	ClampOn DSP Particle Monitor	Topside	2004
Addax	Okwori Sandje Berge	ClampOn DSP Particle Monitor	Topside	2005
Addax	Okwori Sandje Berge	ClampOn DSP Particle Monitor	Topside	2005
ExxonMobil	Erha North	ClampOn DSP Deepwater PIG Detector	Subsea	2005
Shell	Forcados Yokri	ClampOn DSP Particle Monitor	Topside	2005
Total	Amenam	ClampOn DSP Particle Monitor	Topside	2005
Shell	Okoloma Gas Plant and Pipelines	ClampOn DSP Particle Monitor	Topside	2006
Shell	Alakiri	ClampOn DSP Particle Monitor	Topside	2006
Shell	Okoloma Gas Plant and Pipelines	ClampOn DSP Particle Monitor	Topside	2006
Shell	Okoloma Gas Plant and Pipelines	ClampOn DSP PIG Detector	Topside	2007
Shell	Okoloma Gas Plant and Pipelines	ClampOn DSP Particle Monitor	Topside	2007
Shell	Alakiri	ClampOn DSP Particle Monitor	Topside	2007
Shell	Bonga NW	ClampOn DSP Deepwater Particle Monitor	Subsea	2007
Shell	Bonga Phase 2	ClampOn DSP Deepwater Particle Monitor	Subsea	2007
Shell	Okaloma	ClampOn DSP PIG Detector	Topside	2007
Shell	TBA	ClampOn DSP Particle Monitor	Topside	2007
Shell	Bonga	ClampOn DSP Deepwater Particle Monitor	Subsea	2008
Nigerian Agip Energy	FPSO ABO	ClampOn DSP Particle Monitor	Topside	2010
Shell	EA	ClampOn DSP PIG Detector	Topside	2010
Shell	Bonga	ClampOn DSP Deepwater Particle Monitor	Subsea	2011
Shell	Afam F5	ClampOn SandQ Monitor	Topside	2012
Shell	BNAG	ClampOn DSP Particle Monitor	Topside	2012
Shell	Bonga	ClampOn DSP Deepwater Particle Monitor	Subsea	2012
Shell	Bonga	ClampOn DSP Deepwater Particle Monitor	Subsea	2012
Exxon	Ubit pilot project	ClampOn DSP Particle Monitor	Topside	2013
ExxonMobil	Erha North	ClampOn DSP Compact PIG Detector	Subsea	2013
Nigerian Agip Energy	Abo	ClampOn DSP Particle Monitor	Topside	2013
Shell	Bonga	ClampOn DSP Deepwater Particle Monitor	Subsea	2013
Shell	Forcados Terminal	ClampOn DSP Particle Monitor	Topside	2013
Total	Egina	ClampOn DSP Compact Particle Monitor	Subsea	2013
Total	Egina	ClampOn DSP Compact PIG Detector	Subsea	2013
ENI	Abo	ClampOn DSP Particle Monitor	Topside	2014
ExxonMobil	Erha	ClampOn DSP PIG Detector	Topside	2014
ExxonMobil	Erha North Phase II	ClampOn DSP Particle Monitor	Topside	2014
Shel	Bonga	ClampOn DSP Deepwater Particle Monitor	Subsea	2014
Shell	Bonga	ClampOn DSP Particle Monitor	Topside	2014

List of Permanent Installed ClampOn Sensors in Nigeria by Year

Client	Field / Location	Work / Job Scope Executed	Type	Year
Total	Bonga Phase III	ClampOn DSP Deepwater Particle Monitor	Subsea	2014
Chevron	Agbami	ClampOn DSP Deepwater Particle Monitor	Subsea	2014
Shell	Bonga	ClampOn DSP Deepwater Particle Monitor	Subsea	2015
Total	Amenam/Kpono	ClampOn DSP Particle Monitor	Topside	2015
Shell	Southern Swamp Associated Gas	ClampOn DSP Particle Monitor	Topside	2015
Shell	EA	ClampOn DSP Particle Monitor	Topside	2017
Chevron	Abite NAG	ClampOn DSP Particle Monitor	Topside	2017
Shell	EA	ClampOn DSP PIG Detector	Topside	2018
NAE	ABO	ClampOn DSP Particle Monitor	Topside	2019
First E&P	Madu	ClampOn DSP Particle Monitor	Topside	2020
First E&P	Madu	ClampOn DSP PIG Detector	Topside	2020
First E&P	Anyala	ClampOn DSP Particle Monitor	Topside	2020
First E&P	Anyala	ClampOn DSP PIG Detector	Topside	2020
NAE	ABO	ClampOn DSP Particle Monitor	Topside	2020
First E&P	Anyala	ClampOn DSP Particle Monitor	Topside	2021