



PRE MOBILISATION ROTARY DRILL RIG INSPECTION CERTIFICATION

GREEN TAG # 00154

DATE CHECKED: 9.12.2019	PLANT NUMBER: RT1.	PLANT TYPE: COMM 305.	DEPOT/SITE OF ORIGIN: CARCROFT	COMMENTS:	YES/NO	CLEANED READY FOR SITE	✓
DESTINATION / PROJECT:		PLANT TYPE:	DEPOT/SITE OF ORIGIN:	COMMENTS:	N/A		
✓	✓	✓	✓	✓	✓	ENGINE STARTS FIRST TIME	
✓	✓	✓	✓	✓	✓	PLANT TRACKS GREASED & WORKING	
✓	✓	✓	✓	✓	✓	HEAD ROTATION WORKING	
✓	✓	✓	✓	✓	✓	NO LEAKS ON WATER SWIVEL	
✓	✓	✓	✓	✓	✓	OIL LEVELS IN ENGINE, GEAR BOX AND PUMP	
✓	✓	✓	✓	✓	✓	PUMP FITTINGS AND GAUGE WORKING	
✓	✓	✓	✓	✓	✓	PRESSURES GAUGES WORKING	
✓	✓	✓	✓	✓	✓	HYDRAULIC HOSES NO LEAKS	
✓	✓	✓	✓	✓	✓	FEED CHAIN GREASED & WORKING	
✓	✓	✓	✓	✓	✓	SAFETY CAGE WORKING	
✓	✓	✓	✓	✓	✓	EMERGENCY BUTTONS WORKING	
✓	✓	✓	✓	✓	✓	WINCH ROPE GOOD CONDITION	
✓	✓	✓	✓	✓	✓	WIRELINE ROPE IN GOOD CONDITION	
✓	✓	✓	✓	✓	✓	ROTARY HEAD ROLLERS GREASED & WORKING	
✓	✓	✓	✓	✓	✓	DRILL PANEL LEVERS AND GAUGES ALL WORKING	
✓	✓	✓	✓	✓	✓	SIDE SENSORS AND REVERSING WARNING WORKING	
✓	✓	✓	✓	✓	✓	HAVS TAG PRESENT AND CORRECT	
✓	✓	✓	✓	✓	✓	FILLED WITH DIESEL	
✓	✓	✓	✓	✓	✓	OPERATOR'S MANUAL PRESENT	
✓	✓	✓	✓	✓	✓	FIRE EXTINGUISHER PRESENT	
✓	✓	✓	✓	✓	✓	PLANT NAPPY PRESENT	
✓	✓	✓	✓	✓	✓	VALID LOLER CERTIFICATION PRESENT	
✓	✓	✓	✓	✓	✓	LOAD TEST COMPLETED & DOCUMENT ATTACHED	
✓	✓	✓	✓	✓	✓	SAFE WORKING LOAD STICKERS DISPLAYED ON RIG	
✓	✓	✓	✓	✓	✓	IS PLANT REQUIRED TO BE DECONTAMINATED?	N/A
✓	✓	✓	✓	✓	✓	HAS PLANT BEEN DECONTAMINATED?	N/A
OTHER NOTES ABOUT THE PLANT:							
All OK. clw 2x suction hoses. 1 x spill kit (refreshed)							
SIGNED: <i>[Signature]</i>		NAME: PUEMETS.		DATE: 9/12/19			

Plant Service Request and Works Required

If any other issues with the item of plant in question are identified at any time during the above list of works being completed the workshop manager must be informed and all workshop documentation must be updated.

Date: 05/12/19		Date/Time required: 06/12/19	
Plant Item: GE0305		Plant no.: R71	
Hour reading: TBC		858.7	
Description of work required		Time required (hours)	
Steam clean		2	
Check over unit including rig pack and certs		1	
Grease the rig <i>cleansealants X2 fuel g.</i>		2+1	
Test pumps and inspect suction hoses		1	
Complete pre-mob check list and green tag.		1	
Fix engine cover catches		1	
Check wire ropes		1	
Measure the unit against the detc sheet. 5300 EXHA 1		1	
PRE MOB CHECK SHEET COMPLETED.			
WIRE LINE FURD - REMOVE & REWOUND		3	
REMOVE GEAR PATE & REPAIR.			
Parts/materials required		Quantity	
Tube of grease		2	
THROUGH JET WASH + BEHIND COVERS.			
Comments		REPAIRED WIRE LINE WITH GRAB * ISORIGHT U/S. FOR OF WMS. *	
Fitter assigned the works.		<i>Patience</i>	
Managers signature			



TC.