

Lifting Operations & Lifting Equipment Regulations 1998
 Provision & Use of Work Equipment Regulations 1998
 Regular Thorough Examination

Name of User SOCOTEC UK HOLDING LTD AND/OR SOCOTEC UK LIMITED AND/OR ANY
Location CARCROFT, ASKERN ROAD, CARCROFT, DONCASTER, SOUTH YORKSHIRE, DN6 8DG

Policy No. NV10405624 **Report No.** E60938040205 **Contract No.**

Item No. Examination Dates: Last Current Next	Description Serial No. Make/Model Year of Manufacture Location Examination Scheme Number	Safe Working Load(s)	A - Defects which could cause a danger to persons. Particulars of any repairs, renewals or alterations to rectify those defects and the time within which those defects shall be rectified. B - Identification of any other parts that require rectification C - Observations and Recommendations. (issues relating to health and safety. Any actions stipulated should be suitably and satisfactorily completed.)
YANMAR CPT 07-Feb-2020 04-Feb-2021 04-Feb-2022	Drilling Rig, Medium Duty Not marked YANMAR CPT Not marked Carcroft depot	Not marked	A None B Seat belt wiring not attached. Platform access steps distorted. Front nearside outer light, some bulbs not illuminating. C Observation- Item is a rubber tracked cone penetration test crawler. Recommendations- The configured capacity/operating limits should be ascertained and clearly marked. A test certificate or certificate of conformity should be held. A unique plant number or serial number should be clearly marked.

The above items were seen at:
 (If blank, refer to the location details)

Examination carried out on behalf of: SOCOTEC UK HOLDING LTD AND/OR SOCOTEC UK LIMITED AND/OR ANY
 P O BOX 100
 BURTON-ON-TRENT
 STAFFORDSHIRE
 DE15 0XD

First Thorough Examination

Subject to the satisfactory completion of any remedial action to defects noted on this report, which are or could become a danger to persons, the equipment is considered as having been installed correctly, and is safe to operate. (On the basis of a visual thorough examination of the equipment).

Regular Thorough Examination

Subject to the satisfactory completion of any remedial action to defects noted on this report, which are or could become a danger to persons, the equipment is considered as being safe to operate. (On the basis of a visual thorough examination of the equipment).

This report shall not be reproduced without the approval of Allianz Engineering and the Client for whom it was produced.

Side 1 of 2

Date of commencement of examination and tests

04-FEB-2021

Competent Person

Date of Report

04-FEB-2021

Allianz Engineering

Engineer Surveyor



UK Tel: +44(0) 1428 722407

ROI Tel: +00353(0) 1 613 4081



005

Andrew Robinson

