

Lifting Machines and Accessories Report



Lifting Operations & Lifting Equipment Regulations 1998
Provision & Use of Work Equipment Regulations 1998

Regular Thorough Examination

Name of User: **SOCOTEC UK HOLDING LTD AND/OR
SOCOTEC UK LIMITED AND/OR ANY**

Policy **NV10405624**
Number:

Contract
Number:

Report **E60938038833**
Number:

Location: **CARCROFT, ASKERN ROAD, CARCROFT,
DONCASTER, SOUTH YORKSHIRE, DN6
8DG**

Item No. Examination Dates: Last Current Next	Description Serial No. Make/Model Year of Manufacture Location Examination Scheme Number	Safe Working Load(s)	A. Defects which could cause a danger to persons. Particulars of any repairs, renewals or alterations to rectify those defects and the time within which those defects shall be rectified. B. Identification of any parts that require rectification C. Observations and recommendations (Issues relating to health and safety. Any actions stipulated should be suitably and satisfactorily completed.)
YANMAR CPT Unknown 07-Feb-2020 07-Feb-2021	Drilling Rig, Medium Duty YANMAR Carcroft depot	Not marked	A None B None C Observation- Item is a rubber tracked cone penetration test crawler. Recommendations- The configured capacity / operating limits should be ascertained and clearly marked. A test certificate or certificate of conformity should be held. A unique plant number or serial number should be clearly marked.

The above items were seen at: (If blank, refer to the Location details)

Visit made on behalf of:

Client Name

SOCOTEC UK HOLDING LTD AND/OR SOCOTEC UK LIMITED AND/OR ANY

Address

CARCROFT
ASKERN ROAD
CARCROFT
DONCASTER
SOUTH YORKSHIRE
DN6 8DG

This notification shall not be reproduced except in full without the approval of Allianz Engineering and the client for whom it was produced.

Client's Report Notes [These notes DO NOT form part of the Allianz Inspection Report]

Date of commencement of examination and tests 7-Feb-2020

Competent Person
Allianz Engineering

Date of Report 7-Feb-2020

UK Tel: +44 (0) 1428 722407
ROI Tel: +00353 (0) 1 613 4081

Engineer Surveyor

A. Robinson
A. Robinson

Allianz Engineering, Head Office, Haslemere Road, Liphook, Hampshire, GU30 7UN, United Kingdom.
Allianz Engineering Inspection Services Ltd. Registered in England Number: 5441840. Registered Office: 57 Ladymead, Guildford, Surrey, GU1 1DB, United Kingdom.
Allianz plc, Allianz House, Elmpark, Merrion Road, Dublin 4, Republic of Ireland. Allianz plc trading as Allianz is regulated by the Irish Financial Regulator. Registered in Ireland number 143108.
www.allianzengineering.co.uk



This is an electronically produced copy of an original report held on the Allianz Engineering computer database called FACE

Print

Close

[Print/email friendly page](#)

Attachments

Type

Comments

No Attachments