Plant Service Record

SOCOTEC

Date: 18 · X · 2022	Fitter's name: DSM
Plant Item: DANDO 3000	Plant no.: CT-08
Hour reading: 162.4	

Description of work carried out	Time taken (hours)	Initials
REPLACE HANDBRAWE LEVER		
SHOCK ABSORBER		DD
REMOVE AND RECTIFY REAR BRAWE		DD
CABLES		
INSTALL IT		DD

Parts/materials used	Quantity
WD - 40	0.5L

Fitter's comments:

REMOVE BRAWE CABLES AFTER I FOUND OUT WHEELS NOT SPINNIG AFTER APPLY AND REALASE HANDBRAWE

Fitter's Signature (work complete)	