

Plant Service Record

Date: 15 11 2023	Fitter's name: DOM		
Plant Item: DANOO 175 Plant no.: CT-08			
Hour reading: 228.8			
Description of work carried out	7	Γime taken (hours)	Initials
RECTIFY BRAVE CABLES			
RECTIFY BRAVE CABLES READJUST BRAVES			717
0			
Parts/materials used			Quantity
Fitter's comments:			
WHEELS TIGHTENED WITH TORQUE WRENCH 160Nm			
HAD TO WELD ON TOP BRAKE CABLE SHELL DUE TO WORN INSERT HOLE IN BACK PLATE (CHAIN WHEEL SIDE)			
INSERT HOLE IN BACY PLATE (CHAIN WHEEL SIDE)			
Fitter's Signature (work complete)			