

Plant Service Record

Date: 11-1V-2022	Fitter's name: DOM		
Plant Item: CT-03	Plant no.:	DANO 1	75
Hour reading:			
Description of work carried out		Time taken (hours)	Initials
INSTALL DRUM COVER			
- 11 - CLUTCH COVER AND SECURE WITH			
NEW NUTS			
PREPARE SPREAD LEGS PINS 2x			
The state of the s	faith couls	, ,	
INSTALL NEW ROPE WITH JOHN GOWAL			
Parts/materials used			Quantity
NEW RUPE W24278			1
W I SO I S			-L
Fitter's comments:			
Fitter's Signature (work complete)	Old		