



SOCOTEC

Plant Service Record

Date: 18-IV-2023		Fitter's name: DOM	
Plant Item: DANDO 3000		Plant no.: CT-09	
Hour reading:			
Description of work carried out		Time taken (hours)	Initials
ADJUST HANDBRAKE			DD
CHECK FOR FUEL LEAK			DD
REPLACE FUEL FILTER (REMOVE AND INSTALL SAME)			DD
RECTIFY OLIVE ON FUEL SUPPLY HOSE FROM FILTER HOUSING TO ENGINE			DD
Parts/materials used		Quantity	
Fitter's comments: RIG CAME BACK FROM SITE WITH LEAK FROM FILTER AREA AFTER INVESTIGATION I FOUND OLIVE ON DELIVERY HOSE HAD A ^{METAL} SHAVING ON ITS SEALING FACE. REMOVE SHAVING TIGHTEN FITTING. TEST IT OVER 3 days NO LEAKS FOUND			
Fitter's Signature (work complete)			