




SOCOTEC

Plant Service Record

| Date: 30-X-2023 | Fitter's name: DOM | |
|---|---|-----------|
| Plant Item: DANDO 175 | Plant no.: CT-34 | |
| Hour reading: | | |
| Description of work carried out | Time taken (hours) | Initials |
| REPLACE DESTROYED BEACON LIGHT | | DD |
| INSTALL PROPERLY CLUTCH COVER | | DD |
| ROPE RECTIFY | | |
| BRAVES | | |
| GREASE CHAIN + FABRICATE LITTLE WINDOW FOR GREASING | | DD |
| REPLACE SEIZED 2ND PART BRAVE CABLES LEFT + RIGHT | | DD |
| Parts/materials used | Quantity | |
| BRAVE CABLES 2nd PART | 2X | |
| Fitter's comments: SAFETY INSPECTION ON AERODROME SAFETY SHEET MTV 10072 HAVE BEEN DONE. | | |
| Fitter's Signature (work complete) |  | 30-X-2023 |