Plant Service Record

SOCOTEC

Date: 19-X-2021	**Fitter's name:** JDM
Plant Item: DANDO - 3000	**Plant no.:** CT-53
Hour reading: 41.1	

Description of work carried out	**Time taken (hours)**	**Initials**
REPLACE SNAPED FRONT BRAKE CABLE	7	[illegible]

Parts/materials used	**Quantity**
FRONT BRAKE CABLE	1

Fitter's comments:

~~BRAKE~~ BREAKDOWN IN OUR DEPOT IN UXBRIDGE

Fitter's Signature (work complete)	[signature]