



SOCOTEC

Plant Service Record

Date: 6-VI-2023		Fitter's name: DOM	
Plant Item: DANDO - 3000		Plant no.: CT-62	
Hour reading: 411.2			
Description of work carried out		Time taken (hours)	Initials
CHARGE BATTERY			
REPLACE WORN SET-UP ROPE			
INSPECT BRAVES			
CHECK IF ALTERNATOR CHARGING → OK			
OIL SERVICE - (OIL + FILTER CHANGE)			
GB OIL CHANGE + FLUSH			
FUEL FILTER CHANGE			
Parts/materials used		Quantity	
ENGINE OIL 15W-40		6.5L	
GB OIL 80W90		3L	
OIL FILTER; AIR FILTER, FUEL FILTER		1+1+1	
SET-UP ROPE W 24575		1	
Fitter's comments: INSPECT BRAVES → FOUND SOMETHING INSIDE DRUM → PROBABLY REASON WHY CHAIN WHEEL SIDE WHEEL STUCK (EXCESSIVELY WARM UP) WHEN RIG CAME BACK BATTERY WAS FLAT CHECK CHARGING → SPOT ON 14.2V			
Fitter's Signature (work complete)		9 VI 2023 	