

Plant Service Record

Date: 1 7-V-2024	Fitter's name: DoM		
Plant Item: DANDO - 100 Plant no.: CT-64			
Hour reading:			
Describuon of work carried out		Time taken (hours)	Initials
DRUM + CHAIN + ENGINE ALIGNMENT		ワク	
FABRICATE NEW K-WAYS FOR SLIDING MEMBER		179	
REPLACE FUEL HOSES		DO	
Oil SevVicE		79	
MODIFY CHAIN COVER WIDER + LUBE FLAP		77	
MODIFY MAST SHAFT TO FIT INTO MAST		DD	
PAINTED SIDE MAST STAYS (BLACK AND VELOW)		27	
INSTALL ROPE BACK ON A	RIG	,	717
Parts/materials used			Quantity
ENGILE OIL 15W-40		4	
OIL FILTER + FUEL FILTER		1+1	
OIL FICIENT FORE FILIENT		1 1 4	
Fitter's comments:			
RIG WAS IN NEED OF ALIGNMENT OF DRUM SPROCKET TO ENGINE. DOLE TO MISALIGNMENT CHAIN JUMPED OUT FROM AROW OF OFF BIG CHAIN WHEEL.			
Fitter's Signature (work complete)	22 - V -	2024	0