

Plant Service Record



Date: 23-V-2022		Fitter's name: DOM	
Plant Item: DANDO DUKE		Plant no.: CT- 111 72	
Hour reading: 139.4			
Description of work carried out		Time taken (hours)	Initials
FABRICATE NEW CLUTCH LEVER			DD
R & I CLUTCH LEVER			DD
Parts/materials used			Quantity
SOME ROUGH METAL BOLT + NUT			
Fitter's comments: JOHN GOWAN TESTED RIG AND FOUND CLUTCH LEVER CAME LOOSE. AFTER QUICK RESEARCH I DECIDED TO FABRICATE NEW LEVER BRACKET			
Fitter's Signature (work complete)			