



Full Member

REPORT OF THOROUGH  
EXAMINATION

Customer Order Number

T02372

Sales Job No

135398

Date of Examination

26/06/2024

Date of Report

27/06/2024

Report Number

147190

## Organisation for whom the thorough examination was made

Socotec UK Limited  
ESG House  
Bretby Business Park  
Ashby Road  
Burton on Trent  
DN15 0YZ

## Location at which the thorough examination was made

J.H. (Lifting Gear Hire) Ltd  
Unit Q  
London Road Trading Estate  
Sittingbourne  
Kent  
ME10 1NQ

Qty	Description & Identification of the Equipment	Safe Working Load / Standard	Date of Last Thorough Examination (If Known)
2	65 metre x 16mm diameter 6/36 IWRC galvanised RHOL wire rope, thimble eye one end talurit secured, fused and tapered other end MBL 18209 kg	3277 kg @ 5:1 F.o.S. 5462 kg @ 3:1 F.o.S	

ID Mark: W24714 to W24715

## Has this Equipment been...

Supplied New	Yes <input checked="" type="checkbox"/>	No
Supplied Reconditioned	Yes	No <input checked="" type="checkbox"/>
Examined Only	Yes	No <input checked="" type="checkbox"/>
Examined & Tested Only	Yes	No <input checked="" type="checkbox"/>
Examined, Repaired & Tested	Yes	No <input checked="" type="checkbox"/>

## Was the Examination carried out...

Before being issued for the first time	Yes <input checked="" type="checkbox"/>	No
Within an interval of 6 months	Yes	No <input checked="" type="checkbox"/>
Within an interval of 12 months	Yes	No <input checked="" type="checkbox"/>
As part of an Examination Scheme	Yes	No <input checked="" type="checkbox"/>
After Exceptional Circumstances	Yes	No <input checked="" type="checkbox"/>

Identification of any part found to have a defect that could become a danger to persons and a description of the defect. (If none, state NONE)  
NONE

Is the above a defect which is of immediate danger to persons?

Yes No ☒

If not an immediate danger, when might it become dangerous to persons without rectification?

Date:

Particulars of any repair, renewal or alteration required to remedy the defect identified above

Particulars of any tests carried out as part of the examination. (If none, state NONE)

NONE

## IS THIS EQUIPMENT SAFE TO USE / OPERATE?

Yes ☒ No

Person making this report

Jason Ashworth

Person authenticating this report

Roger Oliveira

Latest date by which next  
thorough examination must  
be carried out:

Qualifications: LEEA Foundation

Qualifications: LEEA TEAM Card Signature

25/12/2024

This equipment was manufactured in accordance with the Machinery Directive, Declaration of Conformity Issued and is available to view at our  
offices on request.

Rope ID W24714 fitted to CT8 on 01-08-24 by Dominik Orabich