
## J.H. (Lifting Gear Hire) LTD.

**UNIT Q, LONDON ROAD TRADING ESTATE** SITTINGBOURNE, KENT, ME10 1NQ

Tel: +44 (0)1795 425760 and 472168

Fax: +44 (0)1795 429476 Web: www.jhlifting.co.uk E-mail: info@jhlifting.co.uk





## REPORT OF THOROUGH **EXAMINATION OF LIFTING EQUIPMENT**

	1	OM
_	No.	C
		21
6474.65	***************************************	Committee City September .
	ISO 9	9001
	MOO.	TOOL

**Customer Order Number** Sales Job No T01840 129477 Date of Examination Date of Report **Report Number** 

This report complies with the requirements of the Lifting Operations and Lifting Equipment Regulations		ISO 9001 21/02 REGISTERED FIRM		21/02/2023	10/05/2023		137389		
					uhlah Aba Abassasa				
Socotec UK ESG House Bretby Busir Ashby Road Burton on Ti	ness Park	n examination was ma	ade	J.H. (Lifting G Unit Q	Trading Estate	n examinatior	1 was mad	le	
	Descripti	n O Identification of t	the Continues and		Cafa Miauliu a	. ( 1/-)	D.4		
Qty Description & Identification of the Equip			me Equipment	nt Safe Working Load			s) Date of Last Thorough Examination (If Known)		
1	65 metre x 16mm dia 6/ eye one end talurit secu MBL 18209 kg 5:1 for lifting (LOLER) - ID Mark: W24540	red, other end fused an	nd tapered		3277 kg @ 5: 5462 kg @ 3				
Has this Equipment been  Supplied New Yes X No X  Supplied Reconditioned Yes No X  Examined Only Yes No X  Examined & Tested Only Yes No X  Examined, Repaired & Tested Yes No X  Identification of any part found to have a defect that could become a could be could be come a could be could be come a could be could be come a			No X No X No X	Was the Examination carried out Before being issued for the first time Within an interval of 6 months Within an interval of 12 months As part of an Examination Scheme After Exceptional Circumstances			Yes Yes Yes Yes Yes Yes Yes	No X No X No X No X	
NONE	a defect which is of im	modiato dangor to nor	mone?						
io tilo above	a delect willer is of im	mediate danger to per	30113 :				Yes	No X	
	mediate danger, when m						Date:		
Particulars of	of any repair, renewal or	alteration required to	remedy the de	efect identified	d above				
Particulars NONE	of any tests carried out a	as part of the examina	tion. (If none, s	state NONE)					
		IS THIS E	QUIPMEN	T SAFE T	O USE / OPE	ERATE?	Yes )	( No	
Jason Ash						thoroug	atest date by which next norough examination must e carried out:		
Qualifications: LEEA Foundation Qualifications: LEEA TEAM Card Signature							20/08/2023		
This equip	ment was manufactured	in accordance with the	he Machinery D our offices o		aration of Conforn	nity issued an	nd is avail	able to view at	
TITED	04 56	eva~ or	_		ONTO	CT 08			

J.H. (Lifting Gear Hire) Ltd. Registered in England No: 1041586 VAT No: GB 203 2419 16