## TEBY LONGS RIG



## **Plant Service Record**

Date: 15 - 1 - 2019	Fitter's name	CDE	ANE
Plant Item: DANSO 2000	Plant no.:	OT SE	52
Hour reading:		34000	
Description of work carried out		Time taken (hours)	Initials
STRIP COUT CLUTCH			
		_	
NEW CLUTCH FIT			
NEW THRUST RIAM FITTED			
GREESE ALL POINTS	*		
Parts/materials used			Quantity
Fitter's comments:			
			1
			1
			4
Fitter's Signature (work complete)	CI		
	<u> </u>	ne	
Managers signature (uploaded)	THE	5	