



Plant Service Record

Date: 08 09 2021	Fitter's name: Dominic	
Plant Item: DANOO - 3000	Plant no.: CT-5-3	
Hour reading: 0		
Description of work carried out	Time taken (hours)	Initials
OIL SERVICE (Eng + G6) + AIR FILTER		DD
RE-TIGHTEN THE CHAIN		DD
RE-END ROPE (NEW IS 1.28m shorter)		DD
REPAIR AND MODIFIED CHAIN COVER		DD
FABRICATE TRAVEL PINS		DD
REPLACE REAR BRAKE CABLES		DD
MODIFIED CLUTCH COVER		DD
INSTALL HOUR COUNTER		DD
FLUSH FUEL TANK (R & I + clean)		DD
INSTALL EXTERNAL FUEL FILTER		DD
REPLACE PILLAR BEARING		DD
Parts/materials used	Quantity	
OIL FILTER	1	
AIR FILTER	1	
FUEL FILTER OEM	1	
EXTERNAL FUEL FILTER	1	
OIL	6.5	
GEARBOX OIL	1.5	
PILLAR BEARING	1	
Fitter's comments:		
<p>ROPE IS SHORTER 128cm = (1.28m) !</p> <p>HOUR COUNTER SET UP TO "0"</p> <p>RIG WAS TESTED ON BIO FUEL</p>		
Fitter's Signature (work complete)		