J.H. (Lifting Gear Hire) LTD.

UNIT Q, LONDON ROAD TRADING ESTATE SITTINGBOURNE, KENT, ME10 1NO

Tel: +44 (0)1795 425760 and 472168

Fax: +44 (0)1795 429476 Web: www.jhlifting.co.uk E-mail: info@jhlifting.co.uk

This report complies with the requirements of the Lifting Operations and Lifting Equipment Regulations



REPORT OF THOROUGH **EXAMINATION OF LIFTING EQUIPMENT**

27/05/2020



Date of Examination

27/05/2020

T00189

Sales Job No.

118165 **Date of Report**

Report Number 117840

DIM 51 ISO 9001 REGISTERED FIRM

Organisation for whom the thorough examination was made

Socotec UK Limited

ESG House

Bretby Business Park

Ashby Road

Burton on Trent

DN15 0YZ

Location at which the thorough examination was made

J.H. (Lifting Gear Hire) Ltd

Unit Q

London Road Trading Estate

Sittingbourne

Kent

ME10 1NQ

Qty Description & Identification of the Equipment Safe Working Load(s) **Date of Last Thorough** Examination (If Known) 2 20 metre x 8mm dia 7/19 IWRC 1960N/mm² galy wire rope with thimble 925 kg @ 5:1 F.o.S. 1157 eye one end talurit secured with captive eye latch hook, other end fused kg @ 3:1 F.o.S. and tapered MBL 4629 kg 5:1 for lifting (LOLER) - 3:1 for pulling/towing only (BS EN 16228) ID Mark: W24082 to W24083

Has this Equipment been					Was the Examination carried out				
Supplied New	Yes	X	No		Before being issued for the first time	Yes	X	No	
Supplied Reconditioned	Yes		No	X	Within an interval of 6 months	Yes	,,	No	X
Examined Only	Yes		No	Χ	Within an interval of 12 months	Yes		No	
Examined & Tested Only	Yes		No	Χ	As part of an Examination Scheme	Yes		No	
Examined, Repaired & Tested	Yes		No	X	After Exceptional Circumstances	Yes		No	

Identification of any part found to have a defect that could become a danger to persons and a description of the defect. (If none, state NONE) NONE

is the above a defect which is of immediate danger to persons?

Yes

No X

If not an immediate danger, when might it become dangerous to persons without rectification?

Date:

Particulars of any repair, renewal or alteration required to remedy the defect identified above

Particulars of any tests carried out as part of the examination. (If none, state NONE) NONE

IS THIS EQUIPMENT SAFE TO USE / OPERATE?

Person making this report

Qualifications: LEEA TEAM Card

Person authenticating this report

Shaun Broad

Latest date by which next

thorough examination must

Roger Oliveira

Qualifications: LEEA TEAM Card Signature

be carried out:

26/11/2020

This equipment was manufactured in accordance with the Machinery Directive, Declaration of Conformity issued and is available to view at our offices on request.

FITTED 17/6/2020