

J.H. (Lifting Gear Hire) LTD.

UNIT Q, LONDON ROAD TRADING ESTATE
SITTINGBOURNE, KENT, ME10 1NQ

Tel: +44 (0)1795 425760 and 472168

Fax: +44 (0)1795 429476

Web: www.jhlifting.co.uk

E-mail: info@jhlifting.co.uk



Lifting Equipment Engineers Association



REPORT OF THOROUGH EXAMINATION OF LIFTING EQUIPMENT

Customer Order Number D12499		Sales Job No 129354
Date of Examination 08/02/2023	Date of Report 13/02/2023	Report Number 137173

This report complies with the requirements of the Lifting Operations and Lifting Equipment Regulations

Organisation for whom the thorough examination was made Socotec UK Limited ESG House Bretby Business Park Ashby Road Burton on Trent DN15 0YZ	Location at which the thorough examination was made J.H. (Lifting Gear Hire) Ltd Unit Q London Road Trading Estate Sittingbourne Kent ME10 1NQ
--	---

Qty	Description & Identification of the Equipment	Safe Working Load(s)	Date of Last Thorough Examination (If Known)
1	90 metre x 16mm dia 6/36 IWRC 1960N/mm ² galv wire rope with thimble eye one end talurit secured, other end fused and tapered MBL 18209 kg 5:1 for lifting (LOLER) - 3:1 for pulling/towing only (BS EN 16228) ID Mark: W24538	3277 kg @ 5:1 F.o.S. 5462 kg @ 3:1 F.o.S	

Has this Equipment been...		Was the Examination carried out...	
Supplied New	Yes <input checked="" type="checkbox"/> No <input type="checkbox"/>	Before being issued for the first time	Yes <input checked="" type="checkbox"/> No <input type="checkbox"/>
Supplied Reconditioned	Yes <input type="checkbox"/> No <input checked="" type="checkbox"/>	Within an interval of 6 months	Yes <input type="checkbox"/> No <input checked="" type="checkbox"/>
Examined Only	Yes <input type="checkbox"/> No <input checked="" type="checkbox"/>	Within an interval of 12 months	Yes <input type="checkbox"/> No <input checked="" type="checkbox"/>
Examined & Tested Only	Yes <input type="checkbox"/> No <input checked="" type="checkbox"/>	As part of an Examination Scheme	Yes <input type="checkbox"/> No <input checked="" type="checkbox"/>
Examined, Repaired & Tested	Yes <input type="checkbox"/> No <input checked="" type="checkbox"/>	After Exceptional Circumstances	Yes <input type="checkbox"/> No <input checked="" type="checkbox"/>

Identification of any part found to have a defect that could become a danger to persons and a description of the defect. (If none, state NONE)

NONE

Is the above a defect which is of immediate danger to persons?

Yes No

If not an immediate danger, when might it become dangerous to persons without rectification?

Date:

Particulars of any repair, renewal or alteration required to remedy the defect identified above

Particulars of any tests carried out as part of the examination. (If none, state NONE)

NONE

IS THIS EQUIPMENT SAFE TO USE / OPERATE?

Yes No

Person making this report

Shaun Broad

Qualifications: LEEA TEAM Card

Person authenticating this report

Shaun Broad

Qualifications: LEEA TEAM Card Signature

Latest date by which next thorough examination must be carried out:

07/08/2023

This equipment was manufactured in accordance with the Machinery Directive, Declaration of Conformity issued and is available to view at our offices on request.