

# J.H. (Lifting Gear Hire) LTD.

UNIT Q, LONDON ROAD TRADING ESTATE  
SITTINGBOURNE, KENT, ME10 1NQ

Tel: +44 (0)1795 425760 and 472168

Fax: +44 (0)1795 429476

Web: www.jhlifting.co.uk

E-mail: info@jhlifting.co.uk



Lifting Equipment Engineers Association



# REPORT OF THOROUGH EXAMINATION OF LIFTING EQUIPMENT

Customer Order Number T01966		Sales Job No 130998
Date of Examination 27/06/2023	Date of Report 28/06/2023	Report Number 139881

This report complies with the requirements of the Lifting Operations and Lifting Equipment Regulations

<b>Organisation for whom the thorough examination was made</b> Socotec UK Limited ESG House Bretby Business Park Ashby Road Burton on Trent DN15 0YZ		<b>Location at which the thorough examination was made</b> J.H. (Lifting Gear Hire) Ltd Unit Q London Road Trading Estate Sittingbourne Kent ME10 1NQ	
Qty	Description & Identification of the Equipment	Safe Working Load(s)	Date of Last Thorough Examination (If Known)
2	65 metre x 16mm dia 6/36 IWRC galvanised RHOL wire rope, thimble eye one end talurit secured, fused and tapered other end  MBL 18209 kg  ID Mark: W24581 to W24582	3277 kg @ 5:1 F.o.S. 5462 kg @ 3:1 F.o.S	

<b>Has this Equipment been...</b> Supplied New Yes <input checked="" type="checkbox"/> No <input type="checkbox"/> Supplied Reconditioned Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> Examined Only Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> Examined & Tested Only Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> Examined, Repaired & Tested Yes <input type="checkbox"/> No <input checked="" type="checkbox"/>	<b>Was the Examination carried out...</b> Before being issued for the first time Yes <input checked="" type="checkbox"/> No <input type="checkbox"/> Within an interval of 6 months Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> Within an interval of 12 months Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> As part of an Examination Scheme Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> After Exceptional Circumstances Yes <input type="checkbox"/> No <input checked="" type="checkbox"/>
---	---

Identification of any part found to have a defect that could become a danger to persons and a description of the defect. (If none, state NONE)  
 NONE

Is the above a defect which is of immediate danger to persons? Yes  No

If not an immediate danger, when might it become dangerous to persons without rectification? Date:

Particulars of any repair, renewal or alteration required to remedy the defect identified above

Particulars of any tests carried out as part of the examination. (If none, state NONE)  
 NONE

**IS THIS EQUIPMENT SAFE TO USE / OPERATE?** Yes  No

Person making this report Shaun Broad Qualifications: LEEA TEAM Card	Person authenticating this report Shaun Broad Qualifications: LEEA TEAM Card Signature	Latest date by which next thorough examination must be carried out: 26/12/2023
--	---	---

This equipment was manufactured in accordance with the Machinery Directive, Declaration of Conformity issued and is available to view at our offices on request.

Rope fitted to CP62 - 16-04-2024 - Daniel Edwards  
 DE