

## Pre Site Check Sheet

## IN-PRE-002 (V1 August 2019)

## PRE MOBILISATION CABLE PERCUSSION DRILL RIG INSPECTION **CERTIFICATION**

DATE CHECKED: 20/8/21		PLANT NUMBER: CT65
DESTINATION / PROJECT: C-(OLLO		PLANT TYPE: CP Ris
		DEPOT/SITE OF ORIGIN:
	YES/NO	Central
	N/A	COMMENTS:
CLEANED READY FOR SITE		
ENGINE STARTS FIRST TIME		
OIL LEVELS IN ENGINE &GEAR BOX		
EMERGENCY BUTTONS WORKING		
WINCH ROPE GOOD CONDITION	1	
SET-UP ROPE IN GOOD CONDITION		
TRAVEL PINS IN PLACE	~	
ROAD BRAKES TESTED & WORKING		
BREAK-AWAY CABLE ATTACHED		
SPARE WHEEL ATTACHED		
TYRES CHECKED & LEGAL (INCLUDING SPARE)	~	
WHEEL CHOCKS PRESENT AND IN GOOD CONDITION		
WHEEL NUTS TIGHT & PRESENT		
LIGHTS & LIGHTING BOARD		
HAVS TAG PRESENT AND CORRECT		
FILLED WITH DIESEL		
OPERATOR'S MANUAL PRESENT		
FIRE EXTINGUSHER PRESENT		
PLANT NAPPY PRESENT		
VALID LOLER CERTIFICATION PRESENT	/	
LOAD TEST COMPLETED & DOCUMENT ATTACHED		
SAFE WORKING LOAD STICKERS DISPLAYED ON RIG	/	
IS PLANT REQUIRED TO BE DECONTAMINATED?	-	
HAS PLANT BEEN DECONTAMINATED?	_	
OTHER NOTES ABOUT THE PLANT:		
SIGNED: //	NAME: /	LUKTI I (EVAN DATE: 20/8/21