

J.H. (Lifting Gear Hire) LTD.

UNIT Q, LONDON ROAD TRADING ESTATE
SITTINGBOURNE, KENT, ME10 1NQ

Tel: +44 (0)1795 425760 and 472168

Fax: +44 (0)1795 429476

Web: www.jhlifting.co.uk

E-mail: info@jhlifting.co.uk



Lifting Equipment Engineers Association



REPORT OF THOROUGH EXAMINATION OF LIFTING EQUIPMENT

Customer Order Number POT00596		Sales Job No 120952
Date of Examination 22/01/2021	Date of Report 25/01/2021	Report Number 122929

This report complies with the requirements of the Lifting Operations and Lifting Equipment Regulations

Organisation for whom the thorough examination was made Socotec UK Limited ESG House Bretby Business Park Ashby Road Burton on Trent DN15 0YZ	Location at which the thorough examination was made J.H. (Lifting Gear Hire) Ltd Unit Q London Road Trading Estate Sittingbourne Kent ME10 1NQ
--	---

Qty	Description & Identification of the Equipment	Safe Working Load(s)	Date of Last Thorough Examination (If Known)
1	20 metre x 8mm dia 7/19 IWRC 1960N/mm ² galv wire rope with thimble eye one end talurit secured with captive eye latch hook, other end fused and tapered MBL 4629 kg 5:1 for lifting (LOLER) - 3:1 for pulling/towing only (BS EN 16228) ID Mark: W24169	925 kg @ 5:1 F.o.S. 1157 kg @ 3:1 F.o.S.	

Has this Equipment been... Supplied New Yes <input checked="" type="checkbox"/> No <input type="checkbox"/> Supplied Reconditioned Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> Examined Only Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> Examined & Tested Only Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> Examined, Repaired & Tested Yes <input type="checkbox"/> No <input checked="" type="checkbox"/>	Was the Examination carried out... Before being issued for the first time Yes <input checked="" type="checkbox"/> No <input type="checkbox"/> Within an interval of 6 months Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> Within an interval of 12 months Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> As part of an Examination Scheme Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> After Exceptional Circumstances Yes <input type="checkbox"/> No <input checked="" type="checkbox"/>
---	---

Identification of any part found to have a defect that could become a danger to persons and a description of the defect. (If none, state NONE)
NONE

Fitted to CT71 01/02/2020 @ James + Milton. (Set up Rope)

Is the above a defect which is of immediate danger to persons? Yes No

If not an immediate danger, when might it become dangerous to persons without rectification? Date:

Particulars of any repair, renewal or alteration required to remedy the defect identified above

Particulars of any tests carried out as part of the examination. (If none, state NONE)
NONE

IS THIS EQUIPMENT SAFE TO USE / OPERATE? Yes No

Person making this report Shaun Broad Qualifications: LEEA TEAM Card	Person authenticating this report Shaun Broad Qualifications: LEEA TEAM Card Signature	Latest date by which next thorough examination must be carried out: 21/07/2021
--	---	---

This equipment was manufactured in accordance with the Machinery Directive, Declaration of Conformity issued and is available to view at our offices on request.