

# J.H. (Lifting Gear Hire) LTD.

UNIT Q, LONDON ROAD TRADING ESTATE  
SITTINGBOURNE, KENT, ME10 1NQ

Tel: +44 (0)1795 425760 and 472168

Fax: +44 (0)1795 429476

Web: [www.jhlifting.co.uk](http://www.jhlifting.co.uk)

E-mail: [info@jhlifting.co.uk](mailto:info@jhlifting.co.uk)



Lifting Equipment Engineers Association



# REPORT OF THOROUGH EXAMINATION OF LIFTING EQUIPMENT

Customer Order Number T00269		Sales Job No 118496
Date of Examination 30/06/2020	Date of Report 30/06/2020	Report Number 118675

This report complies with the requirements of the Lifting Operations and Lifting Equipment Regulations

<b>Organisation for whom the thorough examination was made</b> Socotec UK Limited ESG House Bretby Business Park Ashby Road Burton on Trent DN15 0YZ		<b>Location at which the thorough examination was made</b> J.H. (Lifting Gear Hire) Ltd Unit Q London Road Trading Estate Sittingbourne Kent ME10 1NQ	
Qty	Description & Identification of the Equipment	Safe Working Load(s)	Date of Last Thorough Examination (If Known)
1	20 metre x 8mm dia 7/19 IWRC 1960N/mm <sup>2</sup> galv wire rope with thimble eye one end talurit secured with captive eye latch hook, other end fused and tapered  MBL 4629 kg  5:1 for lifting (LOLER) - 3:1 for pulling/towing only (BS EN 16228)  ID Mark: W24111	925 kg @ 5:1 F.o.S. 1157 kg @ 3:1 F.o.S.	

<b>Has this Equipment been...</b> Supplied New Yes <input checked="" type="checkbox"/> No <input type="checkbox"/> Supplied Reconditioned Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> Examined Only Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> Examined & Tested Only Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> Examined, Repaired & Tested Yes <input type="checkbox"/> No <input checked="" type="checkbox"/>		<b>Was the Examination carried out...</b> Before being issued for the first time Yes <input checked="" type="checkbox"/> No <input type="checkbox"/> Within an interval of 6 months Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> Within an interval of 12 months Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> As part of an Examination Scheme Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> After Exceptional Circumstances Yes <input type="checkbox"/> No <input checked="" type="checkbox"/>	
---	--	---	--

Identification of any part found to have a defect that could become a danger to persons and a description of the defect. (If none, state NONE)  
NONE

Is the above a defect which is of immediate danger to persons? Yes  No

If not an immediate danger, when might it become dangerous to persons without rectification? Date:

Particulars of any repair, renewal or alteration required to remedy the defect identified above

Particulars of any tests carried out as part of the examination. (If none, state NONE)  
NONE

**IS THIS EQUIPMENT SAFE TO USE / OPERATE?** Yes  No

Person making this report Roger Oliveira Qualifications: LEEA TEAM Card	Person authenticating this report Roger Oliveira Qualifications: LEEA TEAM Card Signature	Latest date by which next thorough examination must be carried out: 29/12/2020
---	---	---

This equipment was manufactured in accordance with the Machinery Directive, Declaration of Conformity issued and is available to view at our offices on request.

*Fitted @ Deeside Plant 24/08/2020*