



SOCOTEC

Plant Service Record

Date: 18-III-2024	Fitter's name: DM	
Plant Item: COMACCHIO-405	Plant no.: R-68	
Hour reading: 4278.9		
Description of work carried out	Time taken (hours)	Initials
REPAIR MAST WORK LIGHT PLUG		DD
FABRICATE BRACKET		
REMOVE + INSTALL MAIN WINCH ROPE		
STRIP OUT + CLEAN + REPLACE SEALS IN WINCH DRUM + BALL BEARING ON OTHER SIDE		
REPLACE SHELL OF R/C PLUG ON RIG		
REPLACE CABLE TO R/C		
REPLACE CHECK VALVE ON WINCH		
Parts/materials used	Quantity	
WINCH SEALS SET OD 180 ID 160 + GUIDE STRAP	1+1	
12 CORE CABLE	5.05m	
CHECK VALVE (FROM R-71)	1	
O-RING (VARIOUS SIZES)	5	
BALL BEARING	1	
Fitter's comments: Found FAULTY CHECK VALVE ON MAIN WINCH DRUM AFTER STRIPING OUT WINCH FOR ANOTHER "TIME FOUND LITTLE BALL BEARING / VALVE BALLS INSIDE HYD. MOTOR.		
Fitter's Signature (work complete)	16-IV-2024 <i>DM</i>	