

Plant Service Record



Date: 8-XI-2023		Fitter's name: DOM	
Plant Item:		Plant no.: R-67	
Hour reading: 3680			
Description of work carried out		Time taken (hours)	Initials
REPLACE WORKING LIGHT ON TOP OF MAST			DD
REPLACE FAULTY STEEL PIPE WITH HOSE			DD
TOP UP COOLANT (MSG ON DASHBOARD)			DD
Parts/materials used		Quantity	
45° L 10 fitting + straight L 10 fitting + FERRULES 1/4" HOSE		1+1+2 30 CM	
Fitter's comments:			
Fitter's Signature (work complete)		8-XI-2023	