Plant Service Record

SOCOTEC

Date: 15-V-2023	**Fitter's name:** DOM
Plant Item: COMACCHIO 405	**Plant no.:** R-68
Hour reading:	

Description of work carried out	Time taken (hours)	Initials
REPLACE 1/4" HOSE TO CONSOLE PANEL		DM

Parts/materials used	Quantity
10L FITTINGS	4
FERRULES	4
HOSE 1/4"	2m

Fitter's comments:

WHEN ITS BACK FROM SITE HOSE NEEDS TO BE INSPECTED AND PROBABLY REPLACED

12-13 of JUNE

Fitter's Signature (work complete)	15-V-2023