

Plant Service Record

Date: 15 VII \ 2024	Fitter's name: OOM, N.		
Plant Item: (OMACCHIO - 205	Plant no.:	R-70	
Hour reading: 2358.5 Description of work carried out		Time taken	Initials
BELLIN PUMP REBUILD		(hours)	
Parts/materials used			Quantity
CROSS CONVECTOR			2
CINCLIPS + LARGE RUBBER SLEEVE RING COVER GASHET			8+4 2 4
Fitter's comments: REBUILD BELLIN PUMP WITH NEW CONNECTING SHAFT SHAFT BUSHINGS PINS, FOR A CONNECTING SHAFT			
OF UCE POTON AND STATOR (USED CONDITION)			
The state of the s			
10 Bar WHILE LESTED WITH WHILK SWILL			
TESTER			
Fitter's Signature (work complete)	15 V	11 2024	Del