



SOCOTEC

Plant Service Record

Date: 27 VIII 2024		Fitter's name: DOM	
Plant Item: SOPACCHIO - 405		Plant no.: R-72	
Hour reading: 2928.7			
Description of work carried out		Time taken (hours)	Initials
REPLACE WINCH LEVER			DT
Parts/materials used		Quantity	
WINCH LEVER		1	
Fitter's comments: LEVER WAS HAD A LEAK FROM SHAFT SEAL AREA. THAT WAS A REASON FOR REPLACE			
Fitter's Signature (work complete)		28 VIII 2024	