

FIELD SERVICE REPORT



UK LIMITED

DATE-DAY <u>2</u>	MONTH <u>11</u>	YEAR <u>2022</u>	CUSTOMER: <u>Sora tec</u>			
SERIAL No. <u>3660</u>	PLANT No. <u>Boo 205</u>		SITE ADDRESS:			
HOURS ENGINE <u>960</u>			<u>Progress Ct Binley Coventry CV3 2TF</u>			
HOURS AIR <u>N/A</u>						
DRILL APPEARANCE <u>v. good</u>						
DID PROBLEM MAKE RIG INOPERABLE? YES <input type="checkbox"/> NO <input type="checkbox"/>						
SPARES USED ON MACHINE						
QTY:	PART No.	DESCRIPTION	TIME ARRIVED ON SITE: <u>9:00</u>			
			SERVICEMAN'S NAME(s)	HOURS WORKED		
					MILEAGE:	
					OUT	RETURN
			<u>J. BANNISTER</u>	<u>1.5</u>	<u>70</u>	<u>70</u>
			TOTAL			
			TOTAL MILEAGE			
			TRAVELLING TIME		<u>1.5</u> Hrs	<u>1.5</u> Hrs
			TIME LEFT SITE			
			SERVICEMAN'S HOME TELEPHONE No.	<u>07802766112</u>		
			CAR REG No.	<u>BN21 F6J</u>		

ACCOUNT OF THE TIME SPENT ON SITE AND DETAILS OF REPAIR CARRIED OUT

Test main hydraulic pump found no pressure
from main pump.

Now pump needed.

SERVICEMAN'S SIGNATURE

CUSTOMER'S SIGNATURE

[Signature]

[Signature]