



SOCOTEC

Plant Service Record

Date: 13.1X.2023		Fitter's name: DOM	
Plant Item: R-74 COMACCHIO 305		Plant no.: R-74	
Hour reading: 1354			
Description of work carried out		Time taken (hours)	Initials
REPLACE GATE LOCKER WITH DIFFERENT TYPE			DI7
INVESTIGATE OIL LEAK FROM TANK AREA			
R & I 2 SENSOR + RESEAL IT LEAK			DI7
Parts/materials used		Quantity	
ANTILUCE DROP CATCH		1	
Fitter's comments: FOUND LEAK FROM TANK (SENSOR AREA) LOOKS LIKE IT'S LEAKING ON WELDING RECTIFY it with special formula METAL GLUE LOOKS LIKE it's sealing properly			
Fitter's Signature (work complete)		13 IX 2023 ✓	