

# FIELD SERVICE REPORT



DATE-DAY <u>31</u> MONTH <u>1</u> YEAR <u>2022</u>	<b>CUSTOMER:</b> <u>SOC 0161</u>
SERIAL No. <u>3200</u> PLANT No. <u></u>	
HOURS ENGINE <u>3215/10495/305/993</u>	
HOURS AIR <u></u>	
DRILL APPEARANCE <u></u>	
<b>DID PROBLEM MAKE RIG INOPERABLE?</b> YES <input type="checkbox"/> NO <input type="checkbox"/>	<b>SITE ADDRESS:</b> <u>Pro-Quip - P.A. 113, 200000</u> <u>663 240</u>

**SPARES USED ON MACHINE**

QTY:	PART No.	DESCRIPTION	TIME ARRIVED ON SITE: <u>9:30</u>			
		<u>2 1000m rope</u>	SERVICEMAN'S NAME(s)	HOURS WORKED	MILEAGE:	
					OUT	RETURN
			TOTAL			
			TOTAL MILEAGE			
			TRAVELLING TIME		Hrs	Hrs
			TIME LEFT SITE			
			SERVICEMAN'S HOME TELEPHONE No.			
			CAR REG No.			

**ACCOUNT OF THE TIME SPENT ON SITE AND DETAILS OF REPAIR CARRIED OUT**

Carried out work on the 31st/10/22. The most of it was  
IN 18 15-3470  
was done for a period of 10  
hrs - 7.30 AM - 12.30 PM  
IN 12  
15-3470  
056 40310 5M Rope  
IN 18  
15-3470  
2 - 1000m 5m  
Carried out work on the 31st/10/22. The most of it was  
was done for a period of 9 hrs - 7.30 AM - 4.30 PM

SERVICEMAN'S SIGNATURE

CUSTOMER'S SIGNATURE

AA

[Signature]