



SOCOTEC

Plant Service Record

Date: 31 VIII 2023		Fitter's name: DOM	
Plant Item: COMACCHI 205		Plant no.: R-75	
Hour reading: 1583.8			
Description of work carried out		Time taken (hours)	Initials
R+I DPR MODULE + CHECK			
WORKED FINE WHILE TESTED			DD
RELOCATE GATE MAGNET TO "SAFE" POSITION			DD
REPLACE HOSE TO RAM ON MAST (SETUP RAM)			DD
Parts/materials used		Quantity	
HOSE 1/4 + 2 x 10L 90° fittings			
Fitter's comments: LOOKS LIKE water swivel leaking, FEW WASHERS UNDER TOP PLATE SO IT'S POSSIBLE TO RECTIFY ON SITE. NOTHING WAS REPORTED			
Fitter's Signature (work complete)		DD 6/07/2023	